

MISHAP REPORT

159th Aviation Bn.  
CH47B S/N67-18456  
3 May 1981 0930 hours  
Ft. Campbell, Ky.

Class B Aircraft Mishap

The aircraft was 4 wheel taxiing on the ramp area of the Hopkinsville Municipal Airport. There was a ground guide in front of the aircraft and another crewman standing on the ramp. The aircraft executed a turn and the (2) two aft rotor blades contacted a light standard.

The damage was restricted to (2) two aft rotor blades and (1) one light pole. There were no reported injuries to personnel.

*R.G. Orr*  
R.G. Orr ybn

RGO/ybn  
P31-62  
P7937