

MISHAP REPORT

Company D, 34th Support Battalion
CH47C BuNo 70-15031
22 Feb 1981, 1630 hours (local)
Ft. Hood, Texas

AIRCRAFT MISHAP - CLASS B OR C (undetermined)

Aircraft was one of a flight of two. Vibrations were reportedly experienced which resulted in a decision to execute a forced landing. There were reports of fire from the engine area (location unspecified) during the landing. The aircraft struck trees during the landing. There were no injuries.

The U.S. Army safety center has sent an accident investigation team to Ft. Hood.

A. Twilling
A. Twilling for
R.G. Orr

AT/ybn
P50-17
X2410