

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
TB55-1520-240-20-11 ONE TIME INSP OF LONGITUDINAL CYCLIC TRIM(LCT) ACTUATOR OPERATION CH-47D HELICOPTERS C/W. (EC7788)	THE BOEING CO., PHILA., PA.	12-Jan-1985	1	QC000000	
ACFT S/N:64-13125, CH-47A, INDUCTED AND CONVERTED TO CH-47D, S/N:84-24159 ON 85-02-14. TOTAL TIME AT MODIFICATION:3508.1 ACFT HRS. (EC7788)	THE BOEING CO., PHILA., PA.	28-Feb-1985	1	QC000000	
INSTAL AT BOEING FACILITY OF ENGINEERING CHANGE PROPOSAL(ECP) PHL-CH47D-035, INTERIM NIGHT VISION GOGGLE COMPATIBLE CK HAS BEEN C/W ON THIS ACFT. ECP KIT 145EK350. (EC7788)	THE BOEING CO., PHILA., PA.	28-Feb-1985	2	QC000000	
ACFT INSP CK LIST SYSTEM CONVERTED TO THE PROGRESSIVE PREVENTIVE MAINTENANCE(PPM) INSPECTION PROCEDURES IAW TM55-1520-240-PPM. THIS TM WILL BE APPLIED IN LIEU OF TM55-1520-240-PMS & TM55-1520-240-PM. TOTAL TIME ON ACFT:3508.1 HRS. (EC7788)	THE BOEING CO., PHILA., PA.	28-Feb-1985	3	QC000000	
TB55-1520-241-20-28, INSTAL OF CH-47D STAINLESS STEEL FLT CONTROL TUBES C/W. (EC7788)	THE BOEING CO., PHILA., PA.	28-Feb-1985	4	QC000000	
ACFT S/N:84-24159 TEST FLOWN AND ACCEPTED AT 3517.9 HRS. (EC7788)	THE BOEING CO., PHILA., PA.	22-Mar-1985	1	QC000000	
TB55-1520-240-20-6 ONE TIME INSP OF FWD AND AFT XMSN. GROUNDING RELEASE FOR CH-47D & YCH-47D HELICOPTERS C/W. (EC7788)	THE BOEING CO., PHILA., PA.	01-Jul-1985	1	QC000000	
TB55-1520-241-20-32 ONE TIME INSP OF PITCH LINK CONNECTING BOLTS PN:114R3650-13 ON CH-47B/C/D HELICOPTERS C/W. (EC7788)	THE BOEING CO., PHILA., PA.	18-Jul-1985	1	QC000000	
TB55-1520-240-20-8 COMPREHENSIVE SAFETY INSP OF CH-47D HELICOPTERS C/W. (EC7788)	THE BOEING CO., PHILA., PA.	11-Nov-1985	1	QC000000	
SOF MSG CH-47-85-19 ONE TIME & RECURRING INSP OF VERTICAL HINGE PINS IN CH-47B/C/D ROTARY HEAD C/W. (EC7788)	THE BOEING CO., PHILA., PA.	19-Nov-1985	1	QC000000	
SOF MSG CH-47-85-21 ONE TIME & RECURRING INSP OF CH-47D FLT CNTL MOUNTING PALLETS C/W(TB55-1520-240-20-10). (EC7788)	THE BOEING CO., PHILA., PA.	03-Jan-1986	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
SOF MSG CH-47-86-01 ONE TIME INSP OF PITCH LINK CONNECTING BOLTS, 114R3650-13, 13A C/W. (EC7788)	THE BOEING CO., PHILA., PA.	22-Apr-1986	1	QC000000	
SOF MSG CH-47-86-05 ONE TIME & RECURRING INSP AND CORRECTION OF CH-47 SERIES ACFT CORROSION PROBLEMS C/W(TB55-1520-241-20-38). (EC7788)	THE BOEING CO., PHILA., PA.	30-Jun-1986	1	QC000000	
SOF MSG CH-47-86-07 ONE TIME INSP OF MANUAL RELEASE CABLE TO FWD HOOK C/W (TB55-1520-241-20-39). (EC7788)	THE BOEING CO., PHILA., PA.	24-Sep-1986	1	QC000000	
SOF MSG CH-47-86-09 INSP OF XMSN PRESSURE SWITCHES C/W. (EC7788)	THE BOEING CO., PHILA., PA.	06-Nov-1986	1	QC000000	
SOF MSG CH-47-86-10 ONE TIME INSP OF CH-47A/B/C/D HELICOPTERS WITH ENGINE XMSN BREATHER LINES INSTALLED C/W(TB55-1520-241-20-40). (EC7788)	THE BOEING CO., PHILA., PA.	06-Nov-1986	2	QC000000	
SOF MSG CH-47-87-02 ENGINE CROSS SHAFT ONE TIME & RECURRING INSP C/W(TB55-1520-241-20-42). (EC7788)	THE BOEING CO., PHILA., PA.	15-Jan-1987	1	QC000000	
SOF MSG CH-47-87-01 ONE TIME AND RECURRING INSP OF CERTAIN CH-47D ACFT ROTOR HEADS C/W(TB55-1520-240-20-12). (EC7788)	THE BOEING CO., PHILA., PA.	10-Feb-1987	1	QC000000	
INSP OF PIVOTING & SWIVELING LOWER CONNECTION BOTH FWD & AFT TO ENSURE SLIP BUSHINGS ARE INSTALLED C/W(TB55-1520-240-20-13). (EC7788)	THE BOEING CO., PHILA., PA.	12-Feb-1987	1	QC000000	
THIS ACFT HAS SOME CONFIGURATION CHANGES WHICH REMAIN ON A/C AS A RESULT OF THE EAPS & IN-FLT REFUELING EVALUATIONS. ADDITIONALLY, THE D027R2 TRIAL INSTALLATION NVG COMPATIBLE KIT WAS INSTALLED ON THE ACFT. DURING THE PERIOD THE ACFT WAS AT BOEING VERTOL, THE TESTING CONDUCTED RESULTED IN NO EXTRAORDINARY FATIGUE LIFE. (EC7788)	THE BOEING CO., PHILA., PA.	14-Feb-1987	1	QC000000	
SOF MSG# 0051915Z(CH-47-87-04/TB55-1520-240-20-14) ONE TIME INSP AFT XMSN TO COOLER FAN QUILL SHAFT, C/W AT 3595.5 ACFT HRS. (EC7788)	USAAEFA, EDW AFB, CA.	19-May-1987	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
SOF MSG# 0291930Z JUN87 AFFECTING ALL U.S. ARMY OWNED AND OPERATED ACFT, LOCAL PURCHASE OF TIME CHANGE ACFT COMPONENTS/PARTS(GEN-87-02/TB55-1500 - 200-20-25). (EC7788)	AEFA, EDWARDS AFB, CA.	02-Jul-1987	1	QC000000	
SOF MSG# 0092200Z JUL87 TECHNICAL, CH-47D ACFT, REPLACEMENT OF ENGINE CROSS SHAFT BOLTS. (CH-47-87-06) (URGENT MWO55-1520-240-20-2) ENTERED AND COMPLETED. (EC7788)	AEFA, EDWARDS AFB, CA.	13-Jul-1987	1	QC000000	
SOF MSG# 016100Z JUL87 TECHNICAL, CH-47D SERIES HELICOPTERS, IMMEDIATE GROUNDING TO REPLACE THREE WAY HYDRAULIC VALVES. (CH-47-87-08/TB55-1520-240-20-15). N/A BY SERIAL NUMBER. (EC7788)	AEFA, EDWARDS AFB, CA.	16-Jul-1987	1	QC000000	
SOF MSG# 0142230Z SEP87 ONE TIME INSP OF SHAFT COUPLING WASHERS, CH-47B/C/D ACFT.(CH-47-87-10/TB 55-1520-241-20-45). (EC7788)	USAAEFA, EDWARDS AFB, CA.	16-Sep-1987	1	QC000000	
SOF MSG# 0241500Z SEP87 MAINT MANDATORY CH-47D HCPT, REDUCED INSP INTERVAL OF COMBINER XMSN FAN & DRIVESHAFT(CH-47-87-11/TB55-1520-240-20-16), COMPLETED @ 3620.8 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	29-Sep-1987	1	QC000000	
SOF MSG# 0022130Z NOV87 MAINT MANDATORY, CH-47D HELICOPTER, INSP OF AFT & COMBINING XMSN FAN BEARINGS(CH-47-87-12/TB55-1520-240-20-17) ENTERED AND COMPLETED AT 3620.8 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	04-Nov-1987	1	QC000000	
SOF MSG# 0052030Z NOV87 TECHNICAL, CH-47D HELICOPTER, ELECTRICAL GROUNDING OF FUEL FLOW XMITTER(CH-47-87-13/TB55-1520-240-20-18) ENTERED & COMPLETED AT 3620.8 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	06-Nov-1987	1	QC000000	
OCM/ACE PERFORMED AT 3643 ACFT HRS AT E-AFB-CA BY ACE TEAM MEMBER J AVSCOM OCM SEC ST. LOUIS, MO. (EC7788)	AEFA, EDWARDS AFB, CA.	21-Dec-1987	1	QC000000	
SOF MSG# 0031830Z DEC87, TECHNICAL CH-47D ACFT, ONE TIME RECURRING INSP OF FLT CNTL & UTILITY HYDRAULIC PUMP HOUSING RETAINING SCREWS(CH-47-87-14/TB55-1520-240-20-19) ENTERED & COMPLETED @ 3642.9 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	19-Feb-1988	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
SOF MSG# 0042300Z MAR88, TECHNICAL CH-47D ACFT, INSP OF HEATER FUEL LINES & ELECTRICAL COMPONENTS FOR CHAFFING(CH-47-88-03/TB55-1520-240-20-20) ENTERED AND COMPLETED AT 3642.9 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	16-Mar-1988	1	QC000000	
SOF MSG# 0222300Z MAR88, TECHNICAL CH-47D ACFT, ONE TIME INSP OF ENGINE CROSS SHAFT(CH-47-88-07/TB55-1520-240-20-21) ENTERED & COMPLETED @ 3647.5 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	25-Mar-1988	1	QC000000	
SOF MSG# 0082200Z APR88, ONE TIME INSP OF ENGINE CROSS SHAFT(CH-47-88-08/TB55-1520-240-20-22) COMPLETED AT 3650 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	21-Apr-1988	1	QC000000	
SOF MSG# 02611900Z MAY88 MAINT MANDATORY, CH-47D ACFT FLT CNTL & UTILITY HYD PUMP RETAINING SCREWS REPLACEMENT(CH-47-88-10/TB55-1520-240-20-23) ENTERED AND COMPLETED AT 3680.5 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	27-May-1988	1	QC000000	
SOF MSG# 0201830Z JUN88 ONE TIME INSP OF C-BOX XMSN FAN ASSY & RETQ OF AFT & COMBINING XMSN FAN ASSY(CH-47-88-12/TB55-1520-240-20-25) ENTERED & COMPLETED @ 3718.1 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	05-Jun-1988	1	QC000000	
SOF MSG# 0092200Z JUN88 TECHNICAL, CH-47D ACFT, ONE TIME INSP OF PIVOTING & SWIVELING SERVO CYLINDERS(CH-47-88-11/TB55-1520-240-50-01) ENTERED & COMPLETED @ 3718.1 ACFT HRS. (EC7788)	USAEFA, EDWARDS AFB, CA.	05-Jul-1988	1	QC000000	
SOF MSG# 0012307Z JUL88 CH-47 ACFT, COMB XMSN OIL COOLER FAN(CH-47-88-13/TB55-1520-240-50-01) ENTERED AND COMPLETED @ 3718.1 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	12-Jul-1988	1	QC000000	
SOF MSG# 0212200Z JUL88 TECHNICAL, CH-47D ACFT, ONE TIME INSP OF PIVOTING & SWIVELING SERVO CYLINDERS, EXPANDED COVERAGE(CH-47-88-14/TB55-1520-240--20-26) ENTERED AND COMPLETED @ 3720.5 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	22-Jul-1988	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF MSG# 02122000Z SEP88 PROCEDURE FOR FUEL SAMPLING WHEN USING THE EXTENDED RANGE FUEL SYSTEM (CH-47-88-15/TB55-1520-241-20-48) ENTERED & COMPLETED @ 3737.7 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	22-Sep-1988	1	QC000000
SOF MSG# 0211830Z SEP88 (GEN-88-02/TB1-500-200-20-26) ONE TIME INSP OF CORRECT INTERNAL PORTABLE FIRE EXTINGUISHER COMPLETED 22SEP88 @ 3740.6 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	23-Sep-1988	1	QC000000
SOF MSG# 0031800Z NOV88 CH-47C&D ACFT, IDENTIFICATION OF ADDITIONAL EMERGENCY DESCENT PROCEDURES(CH-47-88-16) COMPLETED @ 3748.2 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	10-Nov-1988	1	QC000000
SOF MSG# 0180022Z NOV88 ALL CH-47D ACFT, ENGINE CROSS SHAFT INSP(CH-47-88-18/TB55-1520-240-20-28) ENTERED & COMPLETED @ 3248.6 ACFT HRS. (EC7788)	AEFA, EDWARDS AFB, CA.	18-Nov-1988	1	QC000000
OCM/ACM PERFORMED AT 3752 ACFT HRS AT EDW AFB, CA. (EC7788)	AEFA, EDWARDS AFB, CA.	22-Dec-1988	1	QC000000
SOF MSG CH-47-88-21 ONE TIME INSP FOR CERTAIN S/N XMSNS(TB55-1520-240-20-29) COMPLETED. (EC7788)	USAAEFA, EDWARDS AFB, CA.	28-Dec-1988	1	QC000000
SOF MSG# 0122330Z DEC88 EMERGENCY, ALL SERIES CH-47 ACFT, IMMEDIATE SUSPENSION OF ALL CH-47 ACFT FLT OPERATION, COMPLETED 19DEC88 @ 3752.3 ACFT HRS (EC7788)	USAAEFA, EDWARDS AFB, CA.	09-Jan-1989	1	QC000000
SOF MSG# 013230Z DEC88 ALL CH-47 SERIES ACFT, INSTRUCTIONS FOR RETURNING ACFT TO FULL FLT STATUS (CH-47-88-21/TB55-1520-241-20-49)COMPLETED 19DEC89 AT 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	09-Jan-1989	2	QC000000
SOF MSG# 0272315Z JAN89 CH-47 ACFT ONLY, GROUNDING FOR APPLICATION OF MWO 55-1520-240-50-38(CH-47-89--03) COMPLETED 3852.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	03-Mar-1989	1	QC000000
SOF MSG# 0240055Z DEC88 CH-47 ACFT ONE TIME & RECURRING INSP OF FWD XMSN IMPELLER ASSY & ADDITIONAL INFO CONCERNING COMPLETION OF SOF CH-47-88-22 BOEING INSP. TB55-1520-240-20-30 COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAEFA, EDWARDS AFB, CA.	10-Mar-1989	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
SOF MSG#0 R 302300Z MAR89 CH-47D ACFT PREVENTIVE MAINTENANCE PROCEDURES FOR CONTROL COMPONENTS WITH ALBI PAINT & FIRE SLEEVES(CH-47-89-05/TB55-1520-240-20-35) COMPLETED AT 3752.3 ACFT HRS. (EC7788)	USAEFA, EDWARDS AFB, CA.	31-Mar-1989	1	QC000000	
MSG# PR 081900Z MAY89 NEW BASELINE ESTABLISHED FOR FUEL CELL INSP AT 3752.3 ACFT HRS. ACFT FLOWN 244.2 HRS SINCE CONVERTED TO A CH-47D. NEXT PHASE INSP WILL BE PHASE #3, CH-47-89-MIM-09 COMPLETED. (EC7788)	USAEFA, EDWARDS AFB, CA.	11-May-1989	1	QC000000	
MSG# 0082300Z FEB89 ALL CH-47D ACFT, ONE TIME INSP OF THE FWD & AFT ROTARY WING HEAD(CH-47-89-04/TB55-1520-240-20-34) COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAEFA, EDWARDS AFB, CA.	11-May-1989	2	QC000000	
MSG# 0042300Z JAN89 POLICY & PROCEDURES GUIDANCE FOR REVERTING FROM PROGRESSIVE PHASE MAINTENANCE TO PHASE MAINTENANCE. CH-47-89-01(TB55-1520-240-20-31) COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAEFA, EDWARDS AFB, CA.	30-May-1989	1	QC000000	
MSG# 0102230Z AUG89 EMERGENCY, IMMEDIATE GROUNDING OF CH-47D ACFT WITH COMBINING XMSN OIL COOLER FAN P/N 145DS518-4(CH-47-89-09) PREVIOUSLY GROUNDED BY SOF MSG CH-47-89-08. ENTERED AND COMPLETED. (EC7788)	USAAEFA, EDWARDS AFB, CA.	11-Aug-1989	1	QC000000	
MODIFICATION TO AVIONICS SHELF AND ANTENNA COVER PLATE FOR AN/ALQ-156 COMPLETED IAW MWO55-1520-240-50-25. (EC7788)	USAAEFA, EDWARDS AFB, CA.	07-Sep-1989	1	QC000000	
PROVISIONS FOR OMEGA/VLF NAVIGATION SYSTEM INSTALLED BY ISMSC IAW MWO55-1520-240-50-30. (EC7788)	USAAEFA, EDWARDS AFB, CA.	07-Sep-1989	2	QC000000	
MODIFICATION FOR INSTALL OF IMPROVED FUEL TANK VENTS AND GROUNDING RECEPTACLES INSTALL BY LSMSC IAW MWO55-1520-240-50-6 WITH THE EXCEPTION OF THE AFT FUEL VENT AT STATION(449.65)(LBL 34.20 CABIN CROWN). (EC7788)	USAAEFA, EDWARDS AFB, CA.	12-Sep-1989	1	QC000000	
SOF MSG 181600Z JUL89(CH-47-89-07/TB55-1520-240-20-37) LOOSE JAM NUTS ON LOWER INTEGRATED CONTROL ACTUATORS COMPLETED. (EC7788)	USAAEFA, EDWARDS AFB, CA.	24-Oct-1989	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
OCM/ACE PERFORMED AT 3752 ACFT HRS BY TEAM MEMBER J. AVSCOM OCM SEC, ST. LOUIS, MO. (EC7788)	USAAEFA, EDWARDS AFB, CA.	27-Oct-1989	1	QC000000	
SOF MSG 272215Z OCT89 CH-47-89-12 IMMEDIATE GROUNDING OF CH-47D ACFT COMPLETED 3752.2 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	02-Nov-1989	1	QC000000	
SOF MSG 071920Z SEP89 AMSAV XSOFC H-47-89-10 TB55-1520-240-20-39 INSP & DEGREASING COMB XMSN COOLING FAN DRIVESHAFT COMPLETED 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	01-Dec-1989	1	QC000000	
SOF MSG R191200Z OCT89 AMSAV-XSOFC H-47-89-11 TB55-1520-240-20-48 UNGROUNDING REQUIREMENTS COMPLETED(EXCEPT FOR VIB CK PARA 9G. ANNOTATED ON DA FORM 2408-13) 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	10-Dec-1989	1	QC000000	
SOF MSG 0171900Z NOV 89 CH-47D-89-13 TB55-1520-240-20-41 UNGROUNDING REQUIREMENTS COMPLETED 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	16-Dec-1989	1	QC000000	
SOF MSG R051900Z DEC89 AMSAV-X SOFC H-47D-89-14 TB55-1520-240-20-42 EXTENSION & CLARIFICATION OF COMBINER COOLING FAN DRIVESHAFT REGREASE COMPLETED 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	16-Dec-1989	2	QC000000	
SOF MSG 201700Z DEC89 AMSAV-X SOFC H-47-89-15, EXTENSION OF COMBINER COOLER FAN DRIVESHAFT INSP & FINITE INCREASE OF OIL COOLER FAN P/N145DS518-8 (SUNSTRAND) COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	21-Dec-1989	1	QC000000	
SOF MSG R291600Z JAN90 AMSAV-X SOFC H-47-90-03 TB 55-1520-240-20-42 EXTENSION OF COMBINER COOLING FAN DRIVESHAFT REGREASE TO 100 FLT HRS COMPLETED @ 3752 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	31-Jan-1990	1	QC000000	
SOF MSG 232130Z JAN90 AMSAV-AMSAV-XSOFC H-47-90-02TB55-1520-240-20-44 RECURRING EDDY CURRENT INSP OF ENGINE CROSS SHAFT COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	31-Jan-1990	2	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF MSG 291600Z JAN90 AMSAV-XSOF CH-47D-90-03 TB55-1520-240-20-42 EXTENSION OF COMBINER COOLING FAN DRIVESHAFT REGREASE COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	31-Jan-1990	3	QC000000
SOF MSG R0320000Z APR90 AMSAR-XSOF CH-47D-90-05 EXTENSION OF VIBRATION TEST ON COMBINING XMSN COOLING FANS & ADDITIONAL TROUBLESHOOTING PROCEDURES C/W AT 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	05-Apr-1990	1	QC000000
SOF MSG# P192100Z APR90 CH-47D ACFT, ONE TIME INSP OF(CH-47-90-07) FWD XMSN BARREL NUTS COMPLETED IAW TB55-1520-240-20-48 AT 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	25-Apr-1990	1	QC000000
SOF MSG R261900Z APR90 AMSAV-XSOF, CH-47-90-09/TB 55-1520-240-20-52, ONE TIME & RECURRING INSP OF PITCH LINK RETAINING HARDWARE COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	10-May-1990	1	QC000000
SOF MSG R211600Z MAY90 AMSAV-XSOF, CH-47-90-10/TB 55-1520-240-20-45, ONE TIME & RECURRING INSP OF R/H AFT BELLCRANK SUPPORT STRUCTURE COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	05-Jun-1990	1	QC000000
SOF MSG R172245Z APR90 AMSAV-XSOF, CH-47-90-06/TB 55-1520-240-20-46, ONE TIME & RECURRING INSP OF AFT XMSN COOLING FAN ASSY COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	15-Jun-1990	1	QC000000
SOF MSG 0121400Z JAN90 AMSAV-XSOF, CH-47-90-01/TB 55-1520-240-20-43, UNGROUNDING REQUIREMENTS OF FAN EATERS & CHANGES TO CH-47-90-11 COMPLETED @ 3752.3ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	06-Jul-1990	1	QC000000
SOF MSG P312030Z AUG90 AMSAV-XSOF, CH-47-90-11/TB 55-1520-241-20-53, ONE TIME INSP OF FUEL PUMP ELECTRIC GROUND, AND REVISION TO ELMER PROCEDURE COMPLETED AT 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	02-Aug-1990	1	QC000000
FECF-PHL-CH-47-D056R2 DROOP STOP SHROUD KIT INSTALLED. (EC7788)	THE BOEING CO., PHILA., PA.	14-Aug-1990	1	QC000000
FECF-PHL-CH-47-D056R2 INCORPORATED IAW CONTRACT # DAAK50- 80-C-0029, 83-C-0001, 83-0003, & 84-C-0004 (EC7788)	THE BOEING CO., PHILA., PA.	14-Aug-1990	2	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
'J' DESIGNATION ASSIGNED TO THIS ACFT IAW AR 705-24 & AMCR 95-6 BY MEMO AMCRE-AV DTD 21AUG90. THE 'J' DESIGNATION WILL REMAIN UNTIL THE ACFT IS NO LONGER REQUIRED TO SUPPORT ASSIGNED TEST PROGRAM. (EC7788)	USAAEFA, EDWARDS AFB, CA.	23-Aug-1990	1	QC000000	
ALL ITEMS OF PHASE #1 AND PHASE #2 COMPLETED @ 3752.3 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	23-Aug-1990	2	QC000000	
SOF MSG P112000Z SEP90 AMSAV-XSOF CH-47D-90-12/TB 55-1520-240-20-49 ONE TIME INSP & MOD TO HYD LINE CLAMPS C/W AT 3759.6 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	13-Sep-1990	1	QC000000	
SOF MSG P261900Z SEP90 AMSAV-XSOF CH-47D-90-13/TB 55-1520-240-20-50 ONE TIME INSP & REMOVAL OF FWD XMSN'S WITH SUSPECT SHAFT COMPLETED @ 3759.6 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA.	27-Sep-1990	1	QC000000	
OCM/ACE PERFORMED AT 3760 ACFT HRS AT EDWARDS AFB,CA. BY ACE TEAM MEMBER I. AVSCOM OCM SEC, ST. LOUIS, MO., EDWARDS AFB, CA. (EC7788)	USAAEFA, EDWARDS AFB, CA.	27-Dec-1990	1	QC000000	
MSG CH-47-91-ASAM-02 MWO CONVERSION TO ONE PIECE CROSS SHAFT, MSG P171830Z JAN91. (EC7788)	AQTD, EDWARDS AFB, CA.	18-Jan-1991	1	QC000000	
MSG CH-47-91-ASAM-03 REVISION TO CHECKLIST DURING OPERATION DESERT STORM MSG P312000Z JAN09. (EC7788)	USAAQTD, EDWARDS AFB, CA.	04-Feb-1991	1	QC000000	
ACFT MODIFIED TO HELICOPTER ICING SPRAY SYSTEM IAW USAAQTD TEST PROJECT 90-06, AVO#90-49 AWR DTD 13 DEC 90. (EC7788)	USAAQTD, EDWARDS AFB, CA.	04-Feb-1991	2	QC000000	
(GEN-91-ASAM-02) MSG# P012230Z FEB91 AUTHORIZATION FOR INSULATION AND USING CRYPTOGRAPHIC COMPUTER, CIT-IC. (EC7788)	USAAQTD, EDWARDS AFB, CA.	04-Feb-1991	3	QC000000	
MSG P 222100Z OCT90, CH-47-91-ASAM-01 COMPLETED AFT XMSN COOLING FAN VIB CHECK TB55-1520-240-20-51 (EC7788)	AQTD, EDWARDS AFB, CA.	13-Feb-1991	1	QC000000	
SOF MSG 0P022300Z APR91, CH-47-91-01/TB55-1520-240-20-55 ONE TIME INSP FOR SUSPECT INPUT PINION AND GEARS COMPLETED 3761 ACFT HRS. (EC7788)	AQTD, EDWARDS AFB, CA.	03-Apr-1991	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ASAM: P092200Z APR91, AMSAV-XSOF, CH-47-91-ASAM-05/TB55-1520-240-20-56 ACFT OPER AT GROSS WT ABOVE 50,000 LBS COMPLETED AT 3761.2 ACFT HRS. (EC7788)	USAAQTD, EDWARDS AFB, CA.	23-Apr-1991	1	QC000000
CH-47-91-ASAM-06 MSG# 251900Z/TB55-1520-240-20-57 ALL CH-47D & MH-47D ACFT OPERATING IN SOUTHWEST ASIA. INSTALL OF NEW FWD XMSN OIL COOLER AIR INLET DUCT P/N 14551981-2,-3,-4 C/W. (EC7788)	USAAQTD, EDWARDS AFB, CA.	29-Apr-1991	1	QC000000
MODIFICATION, REPLACING THE ENGINE CROSS SHAFT WITH A NEW ONE PIECE CROSS SHAFT FOR CH-47D IAW MWO 55-1520-240-50-43. (EC7788)	OLR LSMSC, EDWARDS AFB, CA.	26-Aug-1991	1	QC000000
MSG P281800Z(CH-47-91-ASAM-08) ONE TIME AND RECURRING INSP OF FWD AND AFT XMSN SUPPORT STRUCTURE COMPLETED. (EC7788)	USAAQTD, EDWARDS AFB, CA.	05-Sep-1991	1	QC000000
MSG P151900Z(CH-47-92-ASAM-01) TB1-5120-240-20-5 ONE TIME INSP OF INTERFERENCE BETWEEN THE ENGINE CROSS SHAFT & THE RIGHT HAND FAIRING ACCESS COVER COMPLETED. (EC7788)	USAAQTD, EDWARDS AFB, CA.	18-Oct-1991	1	QC000000
MSG P201500Z APR92(CH-47-92-ASAM-02) TB1-5120-240-20-60, ONE TIME INSP OF THE GENERATOR WIRE HARNESS AT THE FIRE EXTINGUISHER DISCHARGE TUBE C/W. (EC7788)	USAAQTD, EDWARDS AFB, CA.	26-Nov-1991	1	QC000000
MSG P222222Z APR92(CH-47-92-ASAM-04) TB1-5120-240-20-62, ONE TIME & RECURRING INSP OF CROSS SHAFT ADAPTERS C/W. (EC7788)	USAAQTD, EDWARDS AFB, CA.	24-Apr-1992	1	QC000000
SOF MSG CH-47-93-02, UNGROUNDING REQUIREMENTS FOR CH-47D ACFT, TB 1-1520-240-20-63 AND BOEING MSG 8-1420-3-4440 C/W. (EC7788)	AQTD, EDWARDS AFB, CA.	02-Nov-1992	1	QC000000
OCM/ACE PERFORMED AT 3834 ACFT HRS AT EDWARDS AFB,CA. BY ACE TEAM MEMBER X. AVSCOM OCM SEC, ST. LOUIS, MO., EDWARDS AFB, CA. (EC7788)	AQTD, EDWARDS AFB, CA.	01-Dec-1992	1	QC000000
ACFT REQUIRES SHIMS TO ALIGN ENGINE CROSS SHAFT. (.028 RH/.056 LH) (EC7788)	BOEING HELICOPTERS, EDWARDS AFB, CA.	25-Feb-1993	1	QC000000
MSG CH-47-92-ASAM-05 RESCINDED IAW CH-47-93-ASAM-02, TB1-1520-240-20-64. (EC7788)	AQTD, EDWARDS AFB, CA.	05-Mar-1993	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-93-ASAM-03 ONE TIME INSP OF PUMPING UNIT HYDRAULIC C/W. (EC7788)	AQTD, EDWARDS AFB, CA.	16-Mar-1993	1	QC000000	
CH-47-94-ASAM-01, TB1-1520-240-20-67, ONE TIME & RECURRING INSP OF ROTARY WING HEAD BUSHINGS N/A THESE ROTOR HEADS. (EC7788)	AQTD, EDWARDS AFB, CA.	20-Oct-1993	1	QC000000	
OCM/ACE PERFORMED AT 3921 ACFT HRS AT EDWARDS AFB,CA. BY ACE TEAM MEMBER, AVSCOM OCM SEC, ST. LOUIS,MO. (EC7788)	AQTD, EDWARDS AFB, CA.	05-Nov-1993	1	QC000000	
PHASE #3 COMPLETED @ 3923.9 ACFT HRS. NEXT PHASE #4 DUE AT 4123.9 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, CA. 93523	14-Jan-1994	1	QC000000	
CH-47-94-ASAM-03 ONE TIME & RECURRING INSP OF CERTAIN RIGID LINK PN: 1452240-10 TB1-1520-240-20-68 C/W. (EC7788)	AQTD, EDWARDS AFB, CA.	24-Jan-1994	1	QC000000	
CH-47-94-ASAM-04 ONE TIME INSP OF PILOT & COPILOTS SEAT BELT LATCH PINS TB1-1520-240-20-69 C/W. (EC7788)	AQTD, EDWARDS AFB, CA.	09-Feb-1994	1	QC000000	
MSG 251350Z APR94 (CH-47-94-ASAM-05/TB1-1520-240-20-71) ONE TIME INSP OF 5,000 LB TIE DOWN RECEPTACLE ASSY'S COMPLETED. (EC7788)	USAAQTD, EDWARDS AFB, CA.	10-May-1994	1	QC000000	
PERFORMED CONDUCTIVITY TEST ON CH-47A/C DRAGLINKS FOR TACOM. (EC7788)	CCAD, CORPUS CHRISTI, TX	07-Nov-1994	1	QC000000	
OCM/ACE PERFORMED AT 3999 ACFT HRS AT EDWARDS AFB,CA. (EC7788)	OCM SECTION, ST. LOUIS, MO.	02-Dec-1994	1	QC000000	
MSG 132230Z DEC94(CH-47-95-01/TB1-1520-243-20-02) ONE TIME INSP OF UPPER BOOST ACTS, COMPLETED. (EC7788)	USAAQTD ATTC, EDWARDS AFB, MO.	06-Dec-1994	1	QC000000	
MSG 1800ZZ JAN95(CH-47-95-ASAM-02/TB1-1520-243-20-4) ONE TIME TQ VERIFICATION OF #1 & #2 PTU MOUNT NUTS. (EC7788)	USAAQTD ATTC, EDWARDS AFB, MO.	19-Jan-1995	1	QC000000	
MSG 22239Z MAR95(CH-47-95-ASAM-03/TB1-1520-240-20-75) ONE TIME INSP FOR STRATO POWER PUMPS AND REPORTING FOR TURNAROUND PROGRAM. (EC7788)	USAAQTD ATTC, EDWARDS AFB, MO.	23-Mar-1995	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
600 HR FWD ENG MOUNT INSP COMPLETED ON #1 & #2 ENG MOUNTS AT 4030.5 ACFT HRS. (EC7788)	USAAEFA, EDWARDS AFB, MO. 93523	01-May-1995	1	QC000000
MSG 051912Z MAY95 SOF CH-47-95-02/TB1-1520-240-20-76 ONE TIME VISUAL INSP AND TQ CK OF LOWER DRIVE LINK TO SWASHPLATE RETAINING HARDWARE C/W. (EC7788)	USAAQDT ATTC, EDWARDS AFB, MO. 93524	17-May-1995	1	QC000000
MSG 251420Z MAY95 CH-47-95-ASAM-05/TB1-1520-240-20-77 SUPERSEDED AND REVISED BY CH-47-95-ASAM-06. (EC7788)	USAAQDT ATTC, EDWARDS AFB, MO. 93524	22-Aug-1995	1	QC000000
MSG 061805Z SEP95 CH-47-95-ASAM-07/TB1-1520-240-20-79 RECORDS CK AND RECURRING INSP ON ROTOR HEADS THAT HAVE MWO 1-1520-240-50-69. (EC7788)	USAAQDT ATTC, EDWARDS AFB, MO. 93524	07-Sep-1995	1	QC000000
MSG 061726Z NOV95 CH-47-96-ASAM-01/TB1-1520-240-20-80 REPLACEMENT OF AFT LANDING GEAR DRAG LINK ASSY THAT ARE SUSCEPTABLE TO STRESS CORROSION CRACKING DUE REPLACEMENT N/L/T 06NOV97. (EC7788)	USAAQDT ATTC, EDWARDS AFB, MO. 93524	07-Nov-1995	1	QC000000
MSG 252001Z JAN96 CH-47-96-ASAM-03/TB1-1520-240-20-82 ONE TIME VISUAL INSP OF PRESSURE GAGES FOR IDENTIFICATION TAPE LOCATION DUE N/L/T 04FEB96 C/W26JAN96 @ 4066.6 ACFT HRS. (EC7788)	USAAQDT ATTC, EDWARDS AFB, MO. 93524	26-Jan-1996	1	QC000000
MSG 121859Z SEP95 CH-47-95-ASAM-08/TB1-1520-240-20-78 INSP OF THE AFT VERTICAL SHAFT DUST SEAL FOR WEAR C/W. (EC7788)	USAAQDT ATTC, EDWARDS AFB, MO. 93524	11-Apr-1996	1	QC000000
REASSIGNED TO AVIATION TECHNICAL TEST CENTER(ATTTC)FT. RUCKER, ALA. AT 4098.8 ACFT HRS. (EC7788)	USAATTTC, FT.RUCKER, ALA.	21-May-1996	1	QC000000
TWX 241344Z JUN96(CH-47-96-ASAM-05/TB1-1520-240-20-84) ONE TIME INSP OF FWD CONTROL INSTALLATION FOR THE MANUFACTURER OF PIN P/N 114R3650-3 BOLT ASSYS C/W. (EC7788)	USAATTTC, FT.RUCKER, ALA.	25-Jun-1996	1	QC000000
TWX 061523Z JUN96(CH-47-96-ASAM-04/TB1-1520-240-20-83) ONE TIME INSP OF FWD AND AFT HEADS TO ENSURE LUBE OIL TO THE HORIZONTAL HINGE PIN BRGS C/W. (EC7788)	USAATTTC, FT.RUCKER, ALA.	27-Jun-1996	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
TWX 271541Z JUN96(CH-47-96-ASAM-06/TB1-1520-240-20-85) ONE TIME VIS INSP AND RECORDS CK OF THE UPPER BOOST ACTUATORS AND PULL TEST OF SWASHPLATES C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	09-Jul-1996	1	QC000000	
TWX 091405Z JUL96(CH-47-96-ASAM-07/TB1-1520-240-20-86) TO INSP THE BOND LINES ON THE 114P8079-2&3 STRAP ASSYS FOR LOOSENESS AROUND THE EDGES C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	11-Jul-1996	1	QC000000	
PHASE #4 COMPLETED AT 4105.9 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	31-Jul-1996	1	QC000000	
TWX 211509Z AUG96(CH-47-96-ASAM-08/TB1-1520-240-20-88) ONE TIME VIS INSP FOR AND REMOVAL OF CERTAIN S/N'ED 145D5102-3 FWD XMSN MAIN LUBRICATION PUMPS C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	21-Aug-1996	1	QC000000	
TWX 121316Z SEP96(CH-47-96-ASAM-09/TB1-1520-240-20-89) INSP AND REPAIR OF AFT PYLON CLAMSHELL DOOR LOWER LATCH TO PRECLUDE WEAR AND/OR IN FLT LOSS OF DOOR C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	16-Sep-1996	1	QC000000	
ACE/AACE PERFORMED AT 4109 A/C HRS AT BY DYNCORP FT. HOOK TX OLR PROFILER 'N'. (EC7788)	USAATTC, FT.RUCKER, ALA.	21-Oct-1996	1	QC000000	
TWX 141510Z NOV96(CH-47-97-01/TB1-1520-240-20-91) ONE TIME VIS INSP OF FWD XMSN MOUNTING(BARREL) NUTS P/N NAS 577B20A C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	14-Nov-1996	1	QC000000	
TWX 301923Z DEC96(CH-47-97-ASAM-02/TB1-1520-240-20-92) INSTALLATION OF GUARD AROUND CARGO HOOK RELEASE SWITCH ON WINCH/HOIST OPERATORS ASSY P/N 114E250-2 C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	06-Jan-1997	1	QC000000	
TWX 131514Z MAR97(CH-47-97-ASAM-04/TB1-1520-240-20-96)ONE TIME VIS INSP & REPL OF CERTAIN P/N 4C3074 CRISSAIR INC CK VALVE INSTALLED IN POWER CONTROL MODULE ASSYS WITH PORT MARKED FLT CONT PUMP ONLY C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	14-Mar-1997	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
TB1-1520-240-20-93 ALL CH-47D, MH-47D & MH-47E ONE TIME INSP FOR AND REPLACEMENT OF AN320-12 CASTELLATED NUTS MADE BY GREER NUT INC C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	26-Mar-1997	1	QC000000
TWX 021555Z APR97 INFORMATIONAL UPDATE & POSSIBLE SOLUTION FOR NAVSTAR AN/ASN-149(VI) GLOBAL POSITIONING SYSTEM DISPLAY UNIT LOCKUP WHENEVER THE RECEIVER IS TRACKING SATELLITE PRN 30 CH-47-97-ASAM-06 C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	03-Apr-1997	1	QC000000
TWX 141323Z APR97 ONE TIME RECURRING INSP OF POWER DISTRIBUTION FEEDER WIRING FOR FRAYING/CHAFFING & ARCHING/BURNING(CH-47-97-ASAM-07/TB1-1520-240-20-95) C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	15-Apr-1997	1	QC000000
TWX 291815Z MAY97 (CH-47-97-ASAM-09) OPERATION OF T-62T-28 AUXILLIARY POWER UNIT(APU) AND REPORT OF APU FLT HRS(CH-47-97-ASAM-09) C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	02-Jun-1997	1	QC000000
TWX 291548Z SEP97(CH-47-97-ASAM-10/TB1-1520-240-20-99) ONE TIME INSP OF ANVIS/HUD POWER SUPPLY C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	01-Oct-1997	1	QC000000
TWX 151327Z OCT97(CH-47-98-ASAM-01) UNCOMMANDED CONTROL UNPUTS C/W. (EC7788)	USAATTC, FT.RUCKER, ALA.	17-Oct-1997	1	QC000000
CH-47-98-ASAM-02/TB1-1520-240-20-100 EXTENSION FOR REPLACEMENT OF THE AFT LANDING GEAR DRAG LINK ASSY THAT ARE SUSCEPTIBLE TO STRESS CORROSION CRACKING,C/W AT 4144.0 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	17-Nov-1997	1	QC000000
CH-47-98-01/TB1-1520-240-20-103 ONE TIME INSP OF AFT UPPER BOOST ACTUATORS TO STATIONARY SWASHPLATE RETAINING HARDWARE, C/W AT 4155.1 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	18-Mar-1998	1	QC000000
HCPT ICING SPRAY SYSTEM(HISS) REMOVED EXCEPT FOR HARD POINTS AT 4168.2 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	16-Apr-1998	1	QC000000
TWX 282043Z APR98(CH-47-98-ASAM-03/TB1-2835-205-203) MANDATORY TQ CK & REPLACEMENT OF AUXILARY POWER UNIT BOLT C/W AT 4156.1 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	28-Apr-1998	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
OCM/ACE PERFORMED AT 4168 ACFT HRS BY TEAM MEMBER BB AMCOM PROJECT OLR FT.C.KY. (EC7788)	USAATTC, FT.RUCKER, ALA.	12-May-1998	1	QC000000	
TWX 141621Z MAY98 ONE TIME INSP FOR AFT XMSN WITH SUSPECTED IMPROPERLY SHIMMED IMPUT PINION GEAR ASSY(CH-47-98-ASAM-04/TB1-1520-240-20-102) C/W AT 4168.2 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	15-May-1998	1	QC000000	
TWX 161231Z JUL98 FLT RESTRICTIONS FOR ACFT WITH MWO 1-1520-240-50-67 NON-METALLIC SPLINE ADAPTER FOR COMBINING XMSN COOLING FAN DRIVE SHAFT APPLIED(CH-47-98-02/TB1-1520-240-20-105) AT 4168.2 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	17-Jul-1998	1	QC000000	
TB1-1520-240-20-101/CH-47-98-ASAM-05 REV TO CH-47-98-ASAM-02, AFT L/G DRAG LINK C/W AT 4169.7 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	18-Sep-1998	1	QC000000	
TWX 171543Z SEP98(CH-47-98-ASAM-05/TB1-1520-240-20-101) REV TO CH-47-98-ASAM-02 C/W @ 4169.7 ACFT HR (EC7788)	USAATTC, FT.RUCKER, ALA.	02-Oct-1998	1	QC000000	
OCM/JACE PERFORMED AT 4201 ACFT HRS BY TEAM MEMBER BB, AMCON PROJECT OLR, FT.C.KY. (EC7788)	USAATTC, FT.RUCKER, ALA.	08-Feb-1999	1	QC000000	
TB1-1520-240-20-106/CH-47-99-ASAM-01 ONE TIME INSP OF LAG DAMPERERS C/W AT 4201 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	10-Feb-1999	1	QC000000	
TB1-1520-240-20-107/CH-47-99-ASAM-02 ACTIONS TO REDUCE SUSCEPTIBILITY TO FLT CONTROL LOCK-UP AND/ OR UNCOMMANDED MANEUVERS, C/W AT 4201 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	17-Feb-1999	1	QC000000	
TB1-1520-240-20-108/CH-47-99-ASAM-03 ONE TIME AND RECURRING INSP OF HOIST/CARGO HOOK CONTROL PANEL & WATER INTRUSION IN THE COCKPIT C/W AT 4202.1 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	25-Feb-1999	1	QC000000	
TB1-1520-240-20-109/CH-47-99-ASAM-04 FWD AND AFT LONG CYCLIC TRIM YOKE BUSHINGS INSPECTIONS & ACFT MANUAL CHANGES C/W AT 4205.0 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	13-Mar-1999	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
TB1-1520-240-20-110/CH-47-99-ASAM-05 EXTENSION FOR REPLACE OF THE AFT LANDING GEAR DRAG LINK ASSYS THAT ARE SUSCEPTIBLE TO STRESS CORROSION CRACKING C/W, -5 LINKS INSTALLED, 4207.0 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	23-Apr-1999	1	QC000000	
TB1-1520-240-20-111/CH-47-99-01 ONE TIME INSP OF SYNC SHAFT MOUNTING BRACKETS FOR PROPER CLEARANCE TO SYNC SHAFT C/W AT 4220.5 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	08-Jul-1999	1	QC000000	
SOF CH-47-99-02 IMMEDIATE GROUNDING OF ALL H-47 ACFT C/W AT 4241.5 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	09-Aug-1999	1	QC000000	
TB1-1520-240-20-113/SOF CH-47-99-03 INSP OF FWD & AFT XMSNS GEAR/BRNG ASSY C/W RECORDS AT 4241.5 A/CHRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	27-Aug-1999	1	QC000000	
TB1-1520-240-20-114/SOF CH-47-99-04 INSP FOR FWD & AFT XMSN GEAR/BEARING ASSYS IDENTIFIED BY S/N PRE-FIX "VB" C/W AT 4241.5 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	27-Aug-1999	2	QC000000	
TB1-2835-205-20-4/CH-47-00-01 OPERATIONAL RESTRICTIONS AND REVISION TO HISTORICAL RECORDS FOR T-62T-2B AUX POWER UNIT(APU), C/W AT 4244.9 ACFT HRS. (EC7788)	USAATTC, FT.RUCKER, ALA.	12-Oct-1999	1	QC000000	
NOTE: THE LAST FLORESCENT PENTRANT INSP WAS PERFORMED ON #1 & #2 FWD AIRFRAME SUPPORT MOUNT LUGS AT 4030 ACFT HR. (EC7788)	USAATTC, FT.RUCKER, ALA.	29-Oct-1999	1	QC000000	
ACFT RECORDS TRANSCRIBED/CONVERTED FROM ELAS VERSION 3.3 TO ULLS-A AUTOMATED RECORDS VERSION L3P-02-02 CHG #44 ON THIS DATE 27DEC99 AT 4254.5 ACFT HRS. (EC7788)	LSI, CCAD, CORPUS CHRISTI, TX.	27-Dec-1999	1	QC000000	
CH-47-05-SOF-01 EDDY CURRENT OF FWD AND AFT SWASHPLATE INSPECTION COMPLETED 20050106 (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	26-Jan-2005	1	QC000000	
AIRCRAFT DELIVERED TO CORPUS CHRISTI ARMY DEPOT FOR RECAPITALIZATION/PHASE INSPECTION PROGRAM ON 27 AUGUST 2005 AND 4254.5 ACFT HRS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
AIRCRAFT COMPLETED RECAPITALIZATION AND 1-4 PHASE INSPECTION ON 8 JUNE 2005 BY CORPUS CHRISTI ARMY DEPOT. IAW ATCOM SOW WHICH INCLUDED ALL PHASE INSPECTIONS. NEXT PHASE INSPECTION IS #1 AT 4454.5ACFT HRS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	2	QC000000
ACFT. EXTERIOR PAINTED WITH ACFT GREEN MIL-C-46168 CREW COMPARTMENT WITH LUSTERLESS BLACK, MIL-C-46168 CABIN INTERIOR AND RAMP SURFACE WITH LUSTERLESS GREY MIL-C-46168, IAW 55-1500-345-23-2, PAGES-943. ACFT S/N:83-24105 AND SUBSEQUENT REQUIRE WHITE EXPOXY PAINT UN FLOOR BOARDS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	3	QC000000
ACE PERFORMED BY CORPUS CHRISTI ARMY DEPOT AT 4254.5 ACFT HRS. AND ON 8 JUNE 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	4	QC000000
FWD ENGINE MOUNT NDT WAS C/W @ 27 MAY 2004 AND ON 4254.5 ACFT HRS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	5	QC000000
MAINTENANCE ENGINEERING CALL(MEC)CH-47D, DRIVE SYS.MAINTENANCE NUMBER:(T33611) PROBLEM:ON AIRCRAFT CH-47D S/N:8424159 SEQ.3CQ04 THE C-BOX OUTPUT ADAPTER P/N:145D3407-8,S/N:A-583 WAS RECEIVED WITH 3 EA STEEL SPLIT LOCKING NUTS P/N:MS21045C9 INSTEAD OF 3 EA SELF-LOCKING HEX NUTS P/N:BACN10RJ9N. REQUEST AMCOM ENGINEERING APPROVAL TO USE THE ADAPTER WITH THE ABOVE NUTS AS IS. REFERENCE PREVIOUS MEC#T33380. ATTN: MR. GILBERTO LEOS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	6	QC000000
MAINTENANCE ENGINEERING CALL(MEC)CH-47D, DRIVE SYS.MAINTENANCE NUMBER:(T33611) MED DISPOSITION: THE NUT MS21045C9 IS AN ALL CORROSION RESISTING STEEL NUT THAT IS A GOOD SUBSTITUTE FOR THE BANCN10RJ9N. CCAD FAILED TO DOCUMENT THE SUBSTITUTION THROUGH AN MEC. THE ADAPTER S/N:A-583 HAS A UPGRADE NUT(MS21045C9) AND CAN BE USED AS IS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	7	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
BOEING SERVICE BULLETIN:CH-47-02-1009,01 JUL 1995 RECURRING INSPECTION OF PILOT AND COPILOT JETTISONABLE COCKPIT DOORS. (PCW)FACTORY INSTALLED-25 APRIL 2005 (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	8	QC000000	
BOEING SERVICE BULLETIN:CH-47-02-1011,01 JUL 1995 FUEL SYSTEM RELAY BOX AND LEVEL SENSING UNIT SUPPORT MOD. (PCW)FACTORY INSTALLED 25 APRIL 2005 (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	9	QC000000	
CH-47-98-ASAM-02,TB 1-1520-240-20-100,23 OCT 1997 EXTENSION FOR REPLACEMENT OF THE AFT LANDING GEAR DRAG LINK ASSEMBLIES THAT ARE SUSECETIBLE TO STRESS CORROSION CRACKING. C/W @ 4254.5 ACFT HRS.AND ON 3 FEB 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	10	QC000000	
CH-47-99-ASAM-01,TB 1-1520-240-20-106,08 FEB 1999 ONE TIME INSPECTION OF LAG DAMPENERS. C/W ON 26 MAY 2005 AND ON 4254.5 ACFT HRS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	11	QC000000	
CH-47-99-ASAM-03,TB 1-1520-240-20-108,24 FEB 1999 INSPECTION OF HOIST/CARGO CONTROL PANEL AND WATER INTRUSION IN THE COCKPIT. C/W @ 4254.5 ACFT HRS AND 12 DEC 2005 (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	12	QC000000	
CH-47-99-ASAM-04,TB 1-1520-240-20-109,15 MAR 1999 INSPECT. FWD AND AFT LONGITUDINAL CYCLIC TRIM YOKE BUSHING AND MAINT MANUAL CHANGE. C/W @ 4254.5 ACFT HRS.AND ON 14 JAN 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	13	QC000000	
CH-47-99-SOF-01,TB 1-1520-240-20-111,30 JUN 1999 ONE TIME INSPECTION OF SYNC SHAFT MOUNTING BRACKET FOR PROPER CLEARANCE TO SYNC SHAFTS. C/W @ 4254.5 ACFT HRS. AND ON 3 FEB 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	14	QC000000	
CH-47-99-SOF-02,06 AUG 1999,IMMEDIATE GROUNDING OF ALL H-47 SERIES AIRCRAFT. C/W @ 4254.5 ACFT HRS.AND ON 4 FEB 2005 (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	15	QC000000	
CH-47-00-ASAM-01/TB 1-1520-240-20-119,27 APR 2000 INITIAL AND RECURRING INSPECTION OF FUEL PODS FOR CORROSION AND ELECTRICAL BONDING. C/W @ 4254.5 ACFT HRS.AND ON 3 MARCH 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	16	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-00-ASAM-03/TB 1-1520-240-20-121,01 JUN 2000 HYDRAULIC FLUID SAMPLING FROM FLIGHT CONTROL AND UTILITY SYSTEM. C/W ON 25 MAY 2005 AND ON 4254.5 ACFT HRS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	17	QC000000	
CH-47-00-ASAM-05/TB 1-1520-240-20-123,28 JUL 2000 INSPECTION OF FORWARD AND SLIDER SHAFT SEALS. C/W @ 4254.5 ACFT HRS. AND ON 3 FEB 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	18	QC000000	
CH-47-00-ASAM-06/TB 1-1520-240-20-126,21 SEPT 2000 ONE TIME INSPECTION FOR DEFECTIVE FULL AUTHORITY DIGITAL ELECTRONIC CONTROL(FADEC)P3 DRAIN CARTIDGE C/W @ 4254.5 ACFT HRS. AND ON 12 FEB 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	19	QC000000	
CH-47-00-ASAM-07/TB 1-1520-240-20-125,26 SEPT 2000 INSPECTION OF UNTESTED FLIGHT SAFETY PART(FSP) BOLT P/N: 114R3650-7 C/W @ 4254.5 ACFT HRS. AND ON 21 MARCH 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	20	QC000000	
CH-47-00-ASAM-08/TB 1-1520-240-20-128,28 SEPT 2000 INSPECTION OF FORWARD YOKE SHAFT, P/N:145C3051-1 FOR CORROSION. C/W @ 4254.5 ACFT HRS. AND ON 12 JAN 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	21	QC000000	
CH-47-01-ASAM-01/TB 1-1520-240-20-127,11 OCT 2000 INSPECT. FOR INSTALLATION OF MA-16 INERTIA REELS P/N: 015-870145-3-10 C/W ON 20 MAY 2005 AND ON 4254.5 ACFT HRS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	22	QC000000	
CH-47-01-ASAM-02/TB 1-1520-240-20-130, 19 OCT 2000 INSPECT. FOR UNTESTED FLIGHT SAFETY PART BOLTS P/N: 114R3650-6 AND 114R3650-11. C/W @ 4254.5 ACFT HRS. AND ON 22 MARCH 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	23	QC000000	
CH-47-01-ASAM-07/TB 1-1520-240-20-135, 12 FEB 2001 INSPECTION FOR UNTESTED FLIGHT SAFETY PART BOLTS P/N: 114R3650-13 AND 114R3650-15 C/W @ 4254.5 ACFT HRS AND ON 06 FEB 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	24	QC000000	
CH-47-01-ASAM-08/TB 1-1520-240-20-138, 09 AUG 2001 INSPECTION OF FLIGHT AND UTILITY BOOST HYDRAULIC CONTROL MODULES. C/W @ 4254.5 ACFT HRS. AND ON 16 JAN 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	25	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-01-ASAM-09/TB 1-1520-240-20-139,06 SEPT 2001 MANDATORY INSPECTION FOR UNTESTED FLIGHT SAFETY PARTS(FSP)BOLTS,P/N:1143650-9 AND BACB30ST 10-40. C/W @ 4254.5 ACFT HRS. AND ON 22 MARCH 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	26	QC000000	
CH-47-02-ASAM-01/TB 1-1520-240-20-142,11 OCT 2001 ONE TIME INSPECTION OF THE TUNNEL COVER STRUT ASSEMBLIES. C/W @ 4254.5 ACFT HRS.AND ON 4 NOV 2004. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	27	QC000000	
CH-47-02-ASAM-02/TB 1-1520-240-20-143,26 DEC 2001 FORWARD YOKE SHAFT REPLACEMENT DATE EXTENSION C/W @ 4254.5 ACFT HRS.AND ON 12 JAN 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	28	QC000000	
CH-47-02-ASAM-03/TB 1-1520-240-20-147,12 JUN 2002 INSPECT. FOR IMPROPERLY MANUFACTURED/ASSEMBLED FUEL CONTROL RELAY BOXES. C/W @ 4254.5 ACFT HRS.AND ON 12 FEB 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	29	QC000000	
CH-47-02-ASAM-04/TB 1-1520-240-20-149,24 JUL 2002 INSPECTION FOR UNTESTED CRITICAL SAFETY ITEM(CSI) C/W @ 4254.5 ACFT HRS.AND ON 6 FEB 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	30	QC000000	
GEN-03-ASAM-04,16 DEC 2002,INSPECTION OF BATTERY BOX,CY8515 C/W @ 4254.5 ACFT HRS.AND ON 11 MAR 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	31	QC000000	
CH-47-03-ASAM-01,26 MAR 03,ENGINE DRIVE SHAFT LIFE EXTENSION. C/W @ 4254.5 ACFT HRS. AND ON 19 MARCH 2005. ENGINE S/N: A-921 ENGINE S/N: A-960 BOTH ENGINE DRIVE SHAFTS HAVE SERVICE LIFE OF 6000HRS. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	32	QC000000	
CH-47-04-ASAM-01,03 FEB 2004, AFT FUSELAGE BELLCRANK FASTNER C/W @ 4254.5 ACFT HRS. AND ON 15 MARCH 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	33	QC000000	
CH-47-04-ASAM-02,29 APR 2004,TRANSIENT AND AVOID BANDS ON THE CRUISE GUIDE INDICATOR C/W @ 4254.5 ACFT HRS. AND ON 8 FEB 2005. (RD7033)	CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI, TX 78419-5260	25-Apr-2005	34	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
<p>MAINTENANCE ENGINEERING CAL(MEC): MEC NUMBER: A36330 ENGINEERING DISPOSITION: THIS IS ONE-TIME APPROVAL. YOUR REQUEST TO LEAVE THE FOUR WASHER UNDER THE BRACKETS IS APPROVED AS WRITTEN. AUTHORIZED BY CHUK TRAN, AUTHORIZED ON: 30 MARCH 05 (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX 78419-5260</p>	<p>12-May-2005</p>	<p>1</p>	<p>QC000000</p>
<p>MAINTENANCE ENGINEERING CAL(MEC):MEC NUMBER: A33372 PROBLEM: ON AIRCRAFT CH-47D S/N 84-24159 SEQ 3CQ04,THE BELLCRANK SUPPORT ASSEMBLY P/N:145S1877-1 LOCATED IN THE FLIGHT CONTROL CLOSET HAS EXCESSIVE PLAY WHERE THE BELLCRANK P/N:145C1463-1 IS CONNECTED. THE BELLCRANK SUPPORT ASSEMBLY IS NOT AVAILABLE THROUGH SUPPLY CHANNELS UNTIL MID 2005. SUSPECT BUSHING AND/OR HOLE IN THE BELLCRANK SUPPORT IS ENLONGATED(0.3745" TO 0.3765"). REQUEST (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX 78419-5260</p>	<p>12-May-2005</p>	<p>2</p>	<p>QC000000</p>
<p>MAINTENANCE ENGINEERING CAL(MEC):MEC NUMBER: A33372 PROBLEM: AUTHORIZATION TO REPAIR THE BELLCRANK SUPPORT ASSEMBLY AS PER PREVIOUS MEC:#A25809 DATED 15 SEPT03. ATTN: CHUCK TRAN MED DISPOSITION: YOUR REQUEST TO REPAIR TO SUPPORTASSEMBLY IS APPROVED. USE REPAIR PROCEDURE OUTLINEPER MEC:A25809 MED AUTHORIZED BY: CHUCK TRAN MED AUTHORIZED ON 29 OCT 04 (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX 78419-5260</p>	<p>12-May-2005</p>	<p>3</p>	<p>QC000000</p>
<p>MAINTENANCE ENGINEERING CAL(MEC):MEC NUMBER: A25809 PROBLEM: SUPPORT ASSY P/N:145S1877-1 LOCATED IN THE FLIGHT CONTROL CLOSET HAS EXCESS PLAY WHERE BELLCRANK P/N:145C1463-1 IS CONNECTED. SUPPORT ASSY IS SECURED WITH HI-LOKS. NO ITEM ARE AVAILABLE THROUGH SUPPLY CHANNELS. SUSPECT BUSHING AND OR HOLE IS ENLONGATED. REQUEST"REPAIR PROCEDURES"AND ANY PERTINENT INFORMATION TO REPAIR/DOCUMENTION/ HISTORICAL RECORDS THAT MAY EFFECT FUTURE REPAIRS (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX 78419-5260</p>	<p>12-May-2005</p>	<p>4</p>	<p>QC000000</p>

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
<p>MAINTENANCE ENGINEERING CAL(MEC): MEC NUMBER: A25809 PROBLEM: IN THIS AREA. ATTN: CHUCK TRAN. MED DISPOSITION: YOU ARE AUTHORIZED TO REPAIR THE ENLONGATED HOLES THAT ATTACHES THE BELLCRANK AND THE BELLCRANK. PER DRAWING,THE READING FOR THESE HOLES ARE .3768-3763. THE ENLONGATED HOLES THAT YOU MEASURED ARE .385 INCHES. YOUR REQUEST TO USE STANDARD REAMER .391 IS AUTHORIZED. YOU NEED (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX 78419-5260</p>	<p>12-May-2005</p>	<p>5</p>	<p>QC000000</p>
<p>MAINTENANCE ENGINEERING CAL(MEC):MEC NUMBER: A25809MED DISPOSITION: TO USE LINE MACHINE FOR THESE HOLES. USE SAE 4130 MATERIALS FOR THE BUSHING, HEAT TREAT TO 125000 UTS USE TM 55-1520-240-23-9 SELECTING THE RIGHT BUSHING FOR .391 REAMER. MED AUTHORIZED BY CHUCK TRAN MED AUTHORIZED ON 15 SEPT 03 (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX 78419-5260</p>	<p>12-May-2005</p>	<p>6</p>	<p>QC000000</p>
<p>MAINTENANCE ENGINEERING CAL(MEC):MEC NUMBER: T33611 PROBLEM: ON AIRCRAFT CH-47D S/N 84-24159 SEQ 3CQ04, THE C-BOX OUTPUT ADAPTER P/N: 145D3407-8 S/N A-583 WAS RECEIVED WITH 3 EA STEEL SPLIT LOCKING NUTS P/N: MS21045C9 INSTEAD OF 3 EA SELF-LOCKING HEX NUTS P/N: BACN10RJ9N. REQUEST AMCOM ENGINEERING APPROVALTO USE THE ADAPTER WITH THE ABOVE NUTS AS IS. REFERENCE PREVIOUS MEC:#T33380. ATTN: MR. GILBERTO LEOS. (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX 78419-5260</p>	<p>12-May-2005</p>	<p>7</p>	<p>QC000000</p>
<p>MAINTENANCE ENGINEERING CAL(MEC): MEC NUMBER: T33611MED DISPOSITION: THE NUT MS21045C9 IS AN ALL CORROSION RESISTING STEEL NUT THAT IS A GOOD SUBSTITUTE FOR THE BACN10RJ9N. CCAD,FAILED TO DOCUMENT THE SUBSTITUTION THROUGH AN MEC. THE ADAPTER S/N A-583HAS A UPGRADED NUT(MS21045C9)AND CAN BE USED AS IS. MED AUTHORIZED BY: GILBERTO LEOS MED AUTHORIZED ON 15 NOV 04 (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX 78419-5260</p>	<p>12-May-2005</p>	<p>8</p>	<p>QC000000</p>
<p>CH-47-05-ASAM-01,CH-47 AIRCRAFT, AFT CRITICAL DYNAMIC COMPONENTS. C/W @ 4254.5 ACFT HRS. AND ON 26 JAN 2005. (RD7033)</p>	<p>CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI TX, 78419-5260</p>	<p>22-Jun-2005</p>	<p>1</p>	<p>QC000000</p>

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
AIRCRAFT PERMANENT CHANGE OF STATION, LOSING ACTIVITY: CORPUS CHRISTY ARMY DEPOT, UIC: W0H9AA, DODAAC: W58H0Z, GAINING ACTIVITY: 2-211 GSAB AT AASF MNARNG ST. PAUL MN, UIC: WYQLB1, DODAAC: W57LVB. (JL1033)	AASF MN ARNG, ST. PAUL MN	30-Jun-2005	1	QC000000	
AIRCRAFT ENTERED INTO MODULAR PMD AND 400 CSP IAW AIRWORTHINESS RELEASE FOR IMPLEMENTATION OF ALTERNATE MAINTENANCE CHECKLISTS FOR SELECTED CH-47D AIRCRAFT AWR: DATED 27 AUGUST 2004 ACFT HOURS:4292.9 (JL1033)	AASF MN ARNG, ST. PAUL MN	14-Jul-2005	1	QC000000	
CH-47-05-ASAM-02 ONE TIME INSP FOR S/N AND P/N OF AFT R/W HEAD ASSY COMPLIED WITH, N/A THIS ACFT 21 JUL 05 (JL1033)	AASF MN ARNG, ST. PAUL MN	21-Jul-2005	1	QC000000	
CH-47-05-ASAM-03 ONE TIME RECORDS INSP FOR FWD/AFTR/W HEAD DISCREPANT VERTICLE HINGE BEARINGS COMPLIED WITH 20050729 (JL1033)	AASF MN ARNG, ST. PAUL MN	22-Jul-2005	1	QC000000	
CH-47-05-SOF-02 ROTOR BLADE, ROOT END FIBER DISTORTION INTIAL AND AUGMENTATION OF PMD BLADE INSPECTIONS. COMPLIED WITH AT 4315.7 ACFT HRS 20050803 (JL1033)	AASF MN ARNG, ST. PAUL MN	22-Jul-2005	2	QC000000	
CH-47-05-ASAM-04 AFT TRANSMISSION SEAL RETAINER INSPECTION DUE AT NEXT PHASE BUT NLT 31 JUL 07 N/A THIS ACFT, ACFT RECAPPED AT CCAD AT 4254.5 HRS 20050630. AS PER PARA 5.3 OF ASAM MESSAGE, RD7033 CCAD C.C. TEXAS 78419-5260 (JL1033)	AASF MN ARNG, ST. PAUL MN	28-Jul-2005	1	QC000000	
CH-47-05-ASAM-06, HYDRAULIC SYSTEM MAINTENANCE COMPLIED WITH AT 4359.3 ACFT HOURS, 23 SEP 05 (JL1033)	AASF MNARNG, ST. PAUL MN	27-Sep-2005	1	QC000000	
CH-47-06-ASAM-01 ONE TIME INSPECTION OF UPPER BOOST ACTUATORS COMPLIED WITH 20060110. ACFT HRS 4454.7 (KK4090)	AASF MN-ARNG, ST PAUL, MN 55107	24-Jan-2006	1	QC000000	
CH-47-06-SOF-01 ONE TIME INSP OF M24 DOOR MOUNTED ARMAMENT SUBSYSTEM COMPLIED WITH 20060124 (KK4090)	AASF MN-ARNG, ST PAUL, MN	24-Jan-2006	2	QC000000	
CH-47-06-SOF-02, INSPECT FOR SUSPECT APU P/N INSTALLED. P/N 160150-10A INSTALLED (KK4090)	AASF, MN-ARNG, ST PAUL, MN	15-Feb-2006	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-06-ASAM-02 COMPLIED WITH. M240H GUN MOUNTS NOT INSTALLED (KK4090)	AASF MN-ARNG, ST PAUL, MN 55107	28-Feb-2006	1	QC000000	
COMPLIED WITH REQUIREMENTS OF CH-47-06-SOF-03 (FLIGHT RESTRICTIONS DUE TO AFT ROTOR BLADES) 20060310 (RW6066)	AASF MNARNG B CO 2/211, ST PAUL MN	10-Mar-2006	1	QC000000	
CSP 200 HOUR MAINTENANCE CHECKLIST INSPECTION/ SERVICE COMPLETED AT 4454.7 ACFT HRS. NEXT MAJOR INSPECTION (400 HOUR CSP) DUE AT 4654.5 ACFT HOURS (JL1033)	AASF MNARNG B CO 2/211, ST PAUL MN	22-Mar-2006	1	QC000000	
COMPLIED WITH REQUIREMENTS OF CH-47-06-ASAM-03 COMPONENT SERIALNUMBER: 108-706 AIRCRAFT HOURS: 4506.0	D CO., 2/135TH GSAB, 36 CAB, FORT SILL	15-May-2006	1	LR728742	
CH-47-06-SOF-04 SUSPECT AFT ROTOR BLADES C/W @ 4530.6 ACFT HRS.	D CO 2/135 AVN 36 CAB, FT SILL OK	26-May-2006	1	BM862318	
CH-47-06-SOF-05 COMPLIED WITH @ 4555.6 ACFT HRS	1109TH AVCRAD, GROTON CT	23-Aug-2006	1	JW546464	
CH-47-07-SOF-02 SUSPECT ROTOR BLADES COMPLIED WITH	MDARNG, APG-EA MD 21010	26-Jan-2007	1	DW156906	
AIRWORTHINESS RELEASE (AWR) FOR CH-47D HELICOPTERS WITH THE AN/AAR-57(V) 5 COMMON MISSILE WARNING SYSTEM /IMPROVED COUNTER MEASURES DISPENSER (CMWS/ICMD) INSTALLED(TT#30573) DATED 31 MAY 2006 R-3	DALLAS AASF, GRAND PRAIRIE, TX	20-Feb-2007	1	JM275429	
AIRWORTHINESS RELEASE FOR CH-47D HELICOPTERS WITH FLUX VALVE RELOCATED	DALLAS AASF, GRAND PRAIRIE, TX	20-Feb-2007	2	JM275429	
AIRWORTHINESS RELEASE (AWR) FOR OPERATION OF CH-47D HELICOPTERS WITH THE BLUE FORCE TRACKING (BFT) SYSTEM INSTALLED (TTS40209) DATED 7 FEB 07 R-7	DALLAS AASF, GRAND PRAIRIE, TX	20-Feb-2007	3	JM275429	
AIRWORTHINESS RELEASE (AWR) FOR CH-47D HELICOPTERS WITH THE ELECTRICALLY POWER HYDRAULIC ACCUMULATOR PUMP (TTS#39748) DATED 17 JAN 07	DALLAS AASF, GRAND PRAIRIE, TX	20-Feb-2007	4	JM275429	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
AIRWORTHINESS RELEASE(AWR) FOR CH-47D HELICOPTERS WITH THE ADVANCE HEADS UP DISPLAY(HUD) SYSTEM SIGNAL DATA CONVERTER(SDC) PART NUMBER 125110-007 INSTALLED(AWR32395)DATED 17 AUG 06	DALLAS AASF, GRAND PRAIRIE, TX	20-Feb-2007	5	JM275429
CH-47-07-ASAM-02 COMPLIED WITH @ 4572.3 ACFT HRS	DS2, AASF,MD.21010	07-Mar-2007	1	DM433444
ACE INSPECTION COMPLETED AT 4572 ACFT HRS BY TEAM MEMBER VV AMCOM/OLR MWO BRANCH	DS2, AASF,MD.21010	28-Mar-2007	1	DM433444
CH-47-06-SOF-06 COMPLIED WITH @ 4567.5 ACFT HRS ON 15 SEP 2006	1109TH AVCRAD, GROTON CT	24-Apr-2007	1	JW546464
CH-47-07-SOF-01 PREVIOUSLY COMPLIED WITH	1109TH AVCRAD, GROTON CT	24-Apr-2007	2	JW546464
CH-47-07-ASAM-01 COMPLIED WITH @ 4575.3 ACFT HRS ON 12 APRIL 2007	1109TH AVCRAD, GROTON CT	24-Apr-2007	3	JW546464
CRACK @ STA. 110 WL.52 IN FWD TRANSMISION TQ BOX REPAIRED BY CCAD TEAM @ 1109TH AVCRAD IAW MEC F60516	1109TH AVCRAD, GROTON CT	26-Apr-2007	1	JW546464
NEW 2408-17 INVENTORY INCORPERATED AS PER AMCOM CHANGE 57	1109TH AVCRAD, GROTON CT	15-May-2007	1	JW546464
CH-47-05-ASAM-05 COMPLIED WITH @ 4578.3 ACFT HRS.	1109TH AVCRAD, GROTON CT	01-Jun-2007	1	JW546464
400 HR CSM COMPLETED @ 4578.3 NEXT DUE 200 HR CSM @ 4778.3 ACFT HRS	1109TH AVCRAD, GROTON CT	12-Jun-2007	1	JW546464
CH47-07-SOF-03(SUSPECT ROTOR BLADE) COMPLIED WITH @ 4612.0 ACFT HRS.(JM275429)	CO B 2-149TH GSAB, GRAND PRAIRIE, TX	27-Sep-2007	1	JM275429
EMC TEST SUCCESFULLY COMPLETED FOR AWR(GARMIN GPS/MAP) DATED 05 OCT 07 @ ACFT HRS	DALLAS AASF, GRAND PRAIRIE, TX	19-Oct-2007	1	JM275429
EMC TEST SUCCESFULLY COMPLETED FOR AWR(GARMIN GPS/MAP) DATED 05 OCT 07 ON @ ACFT HRS	DALLAS AASF, GRAND PRAIRIE, TX	19-Oct-2007	2	JM275429
ERROR	DALLAS AASF, GRAND PRAIRIE, TX	19-Oct-2007	4	JM275429

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
AIRWORTHINESS RELEASE(AWR)FOR OPERATION OF US ARMY CH-47D CARGO HELICOPTERS WITH THE INFRARED SIGNATURE SUPPRESSOR(IRSS)SUPPORT STRAPS INSTALLED AT STATIONS 555,575,AND594(TASK NUMBER 48162)	DYNCORP FT.HOOD PROJECT OLR, GRAND PRAIRIE, TX	16-Jan-2008	1	AA821847	
SUBJECT:AIRWORTHINESS RELEASE(AWR) FOR CH-47D WITH INTERGRATED VEHICLE HEALTH MANAGEMENT SYSTEM(IVHMS)HEALTH AND USAGE MONITORING SYSTEM (HUMS) INSTALLED(TTS 52110)	FT HOOD PROJECT OLR, GRAND PRAIRIE, TX	27-Mar-2008	1	AA821847	
CH-47-08-AMAM-03 (AN/ASN-128B/D DOPPLER) COMPLIED WITH @ 4698.1 ACFT HRS	CO D 2/149TH GSAB, GRAND PRAIRIE, TX 75051	30-Mar-2008	1	JM275429	
SUBJECT:AIRWORTHINESS RELEASE(AWR)FOR OPERATION OF CH-47D HELICOPTERS WITH AN/AAR-57 COMMON MISSILE WARNING SYSTEM (CMWS)FIFTH ELECTRO-OPTICAL MISSILE SENSOR (EOMS)(TTS 55188)	PROJECT OLR FT.HOOD, GRAND PRAIRIE, TX	18-Apr-2008	1	AA821847	
ANNUAL ACE EVALUATION COMPLETED AT 4690 ACFT HRS AT GRAND PRAIRIE, TX BY TEAM MEMBERS RR & W	AMCOM PROJECT OLR, KILLEEN, TX	01-May-2008	1	AS425855	
SUBJECT:AIRWORTHINESS RELEASE(AWR)FOR INSTALLATION AND PREFORMANCE TESTING OF THE AN/ASN-128D DOPPLER GLOBAL POSITIONING SYSTEM NAVIGATION (DGNS)PREPLANNED PRODUCT IMPROVEMENT(DGNS-P31)INSTALLED ON CH-47D HELICOPTERS SERIAL NUMBER 90-00180 AND 81-23381	PROJECT OLR FT.HOOD, TX, GRAND PRAIRIE, TX	02-May-2008	1	AA821847	
CH-47-08-SOF-01(ENGINE TRANSMISSION PINION S/N CHECK) COMPLIED WITH @ 4696.1 ACFT HRS.(JM275429)	DALLAS AASF, GRAND PRAIRIE, TX 75051	28-May-2008	1	JM275429	
AIRCRAFT DEPLOYED BY SEA VESSEL TO ARIFJAN, KUWAIT FOR OPERATION IRAQI FREEDOM.JM275429	CO D 2-149TH GSAB, GRAND PRAIRIE, TX 75051	26-Aug-2008	1	JM275429	
CH-47-08-AMAM-05 (AFT P/V/H TIME CHANGE REQUIREMENT) COMPLIED WITH @ 4739.7 ACFT HRS. (JM275429)	CO D 2/149TH GSAB, BALAD, IRAQ 09391	26-Sep-2008	1	JM275429	
200 HR CYCLE INSPECTION COMPLETED AT 4752.0 ACFT HRS. 400 HR CYCLE INSPECTION DUE @ 4952.0 ACFT HRS (HV4034)	VERTEX/L-3, BALAD, IRAQ	30-Oct-2008	1	JM275429	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47 CORROSION ASSESSMENT CHECKLIST COMPLETED @4752.0 ACFT HRS. NEXT DUE @ 4952.0 ACFT HRS (HV4034)	VERTEX/ L-3, BALAD, IRAQ	30-Oct-2008	2	JM275429	
SWASHPLATE ROTATING RING NDI COMPLETED @ 4752.0 ACFT HRS IAW CH-47-05-01 (ADDENDUM 1). NEXT DUE @ 4952.0 ACFT HRS (HV4034)	VERTEX/ L-3, BALAD, IRAQ	30-Oct-2008	3	JM275429	
CH-47-08-AMAM-01 (AFT TRANSMISSION SEAL RETAINER) COMPLIED WITH @ 4752.0 ACFT HRS (HV4034)	VERTEX/ L-3, BALAD, IRAQ	30-Oct-2008	4	JM275429	
CH-47-09-SOF-02 (ENGINE D/S AND ADAPTERS) COMPLIED WITH @ 4827.6 ACFT HRS. (JM275429)	CO D 2/149TH GSAB, BALAD, IRAQ	17-Dec-2008	1	JM275429	
DATA LOSS OCCURED ON 19 NOV 08 AND DATA FROM 12-17 NOV WAS UNRECOVERABLE.	COD 2/149TH GSAB, JOINT BASE BALAD, IRAQ	20-Dec-2008	1	JM275429	
A3T COMPLETED @ 4950.5 ACFT HRS. DTD 2-MAR-09 BY MG9520 TAMP AVCRAD BALAD, IRAQ	TAMP AVCRAD BALAD, IRAQ, BALAD, IRAQ	02-Mar-2009	1	JM027933	
600 HR FWD ENG MOUNT INSP COMPLETED ON #1 FWD ENG MOUNT AT 4950.5 ACFT HRS. (JM027933)	B CO 834TH ASB, BALAD, IRAQ	09-Mar-2009	1	JM027933	
MEC F88801 A.27 FEB 09 PUB FIG127/45. FOR CRACK @ PYLON MOUNTING FORMER AROUND ONE BOLT HOLE STA 534,BL 0,WL 60(STA 534 FORMER CRACK) RMV UPPER PORTIONS OF TWO EA CAPS(INDEX NO. 23,PG 2-126 TM 1-1520-240-23-2) STOP DRILL CRACK. REPAIR CRACK IAW TM 1-1520-204-23-10 PG 8-26 REPAIR PROCEDUREFOR BULKHEAD FLANGE MEMBER USING 0.080 4130 AND USING REINFORCEMENT ON FWD SIDE OF SUPPORT FITTING.REPLACE CUT OUT PORTION OF CAP 2EA(IN. NO. 29 PG11600-16 OF DMWR 1-1520-240 &STIFFENER IN. NO. 30 PG 0116-00-16 OF DMWR 1-1520-240 USING 0.100 4130 FOR CAPS & 0.080 4230 FOR STIFFENER	BCO 834TH ASB, BALAD, IRAQ	18-Mar-2009	1	WO705244	
400 HR CYCLE INSPECTION COMPLETED AT 4950.5 ACFT HRS. 200 HR CYCLE INSPECTION DUE @ 5150.5 ACFT HRS (JM027933)	B CO 834TH ASB, BALAD, IRAQ	23-Mar-2009	1	JM027933	
AIRCRAFT RE-DEPLOYED BY SEA VESSEL TO CONUS. PORT OF ENTRY-BEAUMONT, TEXAS. JM275429	CO D 2-149TH GSAB, GRAND PRAIRIE, TX 75051	21-May-2009	1	JM275429	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
AMAM MSG H-47-09-AMAM-02, AFT SLIDER SHAFT ASSEMBLY RETIREMENT LIFE COMPLIED WITH AT 5019.0 ACFT HOURS.	D CO 2-149, GRAND PRAIRIE, TX	21-Jul-2009	1	WG833252	
CH-47-09-AMAM-03(HHFE) COMPLIED WITH ON 16 SEP 09 @ 5027 ACFT HRS. JM275429	DALLAS AASF, GRAND PRAIRIE, TX 75051	15-Sep-2009	1	JM275429	
NDI ON FWD ROTOR HUB SPLINECOMPLETED AT 5116.4 ACFT HRS	AFMA/URS, FT. LEWIS, WA. 98433	02-Feb-2010	1	SP905754	
NDI ON AFT ROTOR HUB SPLINECOMPLETED AT 5116.4 ACFT HRS	AFMA/URS, FT. LEWIS, WA. 98433	02-Feb-2010	2	SP905754	
MEC F103993 STA 594 STRAP REPAIR, COMPLETED AT 5116.4 ACFT HRS	AFMA/URS, FORT LEWIS, WA	19-Feb-2010	1	CC413290	
H-47-10-ASAM-02(STA 160 HYD CLAMPS) COMPLIED WITH AT 5116.4 ACFT HRS	AFMA/URS, FORT LEWIS, WA	26-Feb-2010	1	CC413290	
MEC F100452 BELLCRANK P/N 114C3319-20 SPACER SLEEVE, COMPLETED AT 5116.4 ACFT HRS	AFMA/URS, FORT LEWIS, WA	26-Feb-2010	3	CC413290	
ACE PERFORMED AT 5116 A/C HRS AT FT LEWIS, WA BY TEAM MEMBERS HH & X	AFMA, FT LEWIS, WA	04-Mar-2010	1	DM410620	
H-47-10-AMAM-03(FWD ROTOR HUB RETIREMENT LIFE REDCTION) COMPLIED WITH AT 5116.4 ACFT HRS	AFMA/URS, FORT LEWIS, WA	15-Mar-2010	1	CC413290	
600 HR NDI INSP OF #1 AND #2 FWD ENG MOUNTS AND ENGINE DRAG LINKS COMPLETED DURING RESET AT 5116.4 ACFT HRS	AFMA/URS, FT LEWIS, WA	26-Mar-2010	1	CC413290	
H-47-10-AMAM-04 (SLIDER SHAFT ASSY) COMPLIED WITH @ 5116.4 ACFT HRS	AFMA URS, FT LEWIS, WA 98433	07-Apr-2010	1	MC403028	
1200 HRS FUEL CELL INSPECTION COMPLETED AT 5116.4 ACFT HRS	AFMA/URS, FT. LEWIS, WA. 98433	07-Apr-2010	2	SP905754	
200/400 CSP COMPLETED AT 5116.4 ACFT HRS., NEXT INSP. 200 CSP DUE AT 5316.4 ACFT HRS.	AFMA/URS, FT. LEWIS, WA. 98433	07-Apr-2010	3	SP905754	
TB 1-2840-265-23 ON # 1 & # 2 ENG COMPLETED AT 5116.4 ACFT HRS.	AFMA/URS, GRAND PRAIRIE, TX 75051	13-Apr-2010	1	SP905754	
TB 1-1520-240-30-02 COMPLIED WITH AT 5124.1 ACFT HRS.	AFMA/URS, FT. LEWIS, WA. 98433	21-Apr-2010	1	SP905754	
COMPLETED EMC TEST PER AWR TTS 41283K FOR INSTALLATION OF MSPU MWO	URS/AFMA, FORT LEWIS WA	21-Apr-2010	2	CC413290	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
AIRWORTHINESS RELEASE(AWR) FOR CH-47D HELICOPTERS TO OPERATE MODERNIZED SIGNAL PROCESSING UNIT(MSPU)EQUIPMENT(TTS 412383)	URS/AFMA, FORT LEWIS WA	21-Apr-2010	3	CC413290
ACFT TRANSFERRED FROM TEXAS GUARD TO HIARNG B171 AT LSI FT LEWIS, WA @ 5126.9 ACFT HRS	AASF #1 HIARNG, FT LEWIS, WA	12-May-2010	1	JS795829
AIRWORTHINESS RELEASE (AWR TTS 63963), DATED 20 NOV 2008 R4 FOR INSTALLATION OF AN/PRC-117F SATCOM RADIO AT 5219.5 ACFT HOURS.	DOL ALMD FORT DRUM, NY 13602, SCHOFIELD BKS, HI 96857	24-Jun-2010	1	DB566403
ON THE MORNING OF SEPTEMBER 9, 2010 WHILE OPERATING OUT OF LONG HORN AIRFIELD, FT HOOD, TX ALMOST ALL HARD COPY HISTORICAL RECORDS WERE DAMAGED BY A FLOOD. DUE TO THE LOW POINT OF OPERATION AND POOR DRAINAGE, WATER LEVELS ELEVATED ABOVE OUR QC STAGING AREA. ONLY SOME HISTORICAL RECORDS COULD BE SALVAGED. ULLS-A SCP-6 DATA BASE WAS NOT DAMAGED. POC: QC DET. 1 D CO. 1-171 AVN	B CO 1-171 AVN, WP1BB0, FORT HOOD, TX	15-Sep-2010	1	DM378494
AIRCRAFT CONFIGURED FOR AIR DEPLOYMENT FROM FT HOOD, TX TO AFGHANISTAN AT 5280.6 ACFT HRS	D CO 1-171 AVN, WP1BD0, FORT HOOD, TX	24-Sep-2010	1	JS795829
AIRCRAFT ENTERED COMBAT OPERATIONS IN SOUTHWEST ASIA, AFGHANISTAN AT 5280.6 ACFT HRS	D CO 1-171 AVN, WP1BD0, BAGRAM, AFGHANISTAN	07-Oct-2010	1	JS795829
MEC [F116352] #1, #2 AND #9 SYNC SHAFT NUTS AUTHORIZATION FOR REUSE AFTER AIR DEPLOYMENT TO AFGHANISTAN AT 5280.6 ACFT HRS	D CO 1-171 AVN, WP1BD0, BAGRAM, AFGAHNISTAN	12-Oct-2010	1	JS795829
H-47-11-ASAM-01 AN960-1016 ALUMINUM WASHERS C/W @ 5280.6 ACFT HRS	D CO 1-171 AVN, WP1BD0, BAGRAM, AFGAHNISTAN	23-Oct-2010	1	JS795829
H-47-10-ASAM-07 5000 POUND TIE DOWN ADAPTOR RING INSPECTION C/W @ 5280.6 ACFT HRS	D CO 1-171 AVN, WP1BD0, BAGRAM, AFGAHNISTAN	23-Oct-2010	2	JS795829
EMC TEST COMPLETED ON ACFT 9300932 ON 05NOV2010 5578.8 ACFT HRS FOR ATIRCM INSTALLATION, AND WILL SATISFY REQUIREMENT FOR SAME CONFIGURATION OF FLEET	B CO 1-171 AVN, BAGRAM, AFGAHNISTAN	05-Nov-2010	1	RL270188

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
EMC TEST COMPLETED ON ACFT 9100255 FOR SATCOM INSTALLATION, AND WILL SATISFY REQUIREMENT FOR SAME CONFIGURATION ACFT	B CO 1-171 AVN, BAGRAM, AFGHANISTAN	05-Nov-2010	2	RL270188	
200 HR PMS2 COMPLETED AT 5307.3 ACFT HRS, NEXT INSP. 400 HR PMS3 DUE AT 5507.3 ACFT HRS	96TH ASB, KANDAHAR AFGHANISTAN 09355	13-Dec-2010	2	QC000000	
H-47-11-AMAM-01 AVIATION MAINTENANCE ACTION MESSAGE (AMAM), MAINTENANCE MANDATORY, UNIT LEVEL LOGISTICS SYSTEM-AVIATION (ENHANCED) INTEGRATED MATERIEL MANAGEMENT CENTER LEGITIMATE CODE FILE CHANGE 61 REQUIREMENTS, C/W @ 5307.3 ACFT HRS	D CO 6-101 GSAB, KANDAHAR AFGHANISTAN 09355	13-Dec-2010	3	RL270188	
PMS 3 COMPLETED @5501 ACFT HRS NEXT DUE PMS 2 @ 5701 ACFT HRS	L3 VERTEX, 96TH ASB, KANDAHAR, AFGHANISTAN 09355	22-Feb-2011	1	QC100000	
MEC [F121626] AUTHORIZATION TO INSTALL SLEEVE BUSHINGS PART NUMBER 145C2517-3, NSN 3120-01-117-7455 IN THE AFT PYLON WORK PLATFORM LATCH RECEPTACLES.	B CO 1-171, KANDAHAR, AFGHANISTAN 09355	22-Feb-2011	2	RL270188	
INITIAL COMPLIANCE COMPLETED IAW H-47-11-ASAM-03 PARAGRAPH #4 5636.5 ACFT HOURS	D CO 7-101, KANDAHAR, AFGHANISTAN 09355	05-Apr-2011	1	RL270188	
C/W REQUIREMENTS OF H-47-11-ASAM-04 (DAMPNER ROD END BEARINGS) AT 5692.5 ACFT HRS "PASS"	B CO 563D ASB, KANDAHAR, AFGHANISTAN 09355	19-Apr-2011	1	JB986281	
FINAL COMPLIANCE OF H-47-11-ASAM-03 COMPLETED. ALL CONTROL LINKS REPLACED	L3, 563RD ASB, KANDAHAR, AFGHANISTAN 09355	26-Apr-2011	1	KR521023	
MEC # F125717 SKIN BUCKLING BETWEEN STA 264-272 WL -30 BL 60R UNDER FLOOR BOARD BEHIND R/H MAIN FUEL POD. REPAIR DEFERED UNTILL RESET. ENSURE THE BUCKLED SKIN IS THOROUGHLY INSPECTED AT EACH SUBSEQUENT PMI TO ENSURE NO DEGRADATION IN CONDITION.	L-3 VERTEX, KANDAHAR, AFGHANISTAN 09355	28-Apr-2011	1	WD802287	
200 HR PMS2 COMPLETED AT 5692.5 ACFT HRS, NEXT INSP. 400 HR PMS3 DUE AT 5892.5 ACFT HRS	L3, 563RD ASB, KANDAHAR, AFGHANISTAN 09355	20-May-2011	1	KR521023	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
<p>MEC NUMBER: F128597 PROBLEM: THE FORWARD ROTARY WING HEAD, HORIZONTAL PIN BEARING (BEARING ROLLER. AIRFRAME) IS DUE TBO AT 5874.0 AIRCRAFT HOURS. THE FOUR HUNDRED (400) HOUR PHASE MAINTENANCE INSPECTION IS DUE AT 5892.5 AIRCRAFT HOURS. 18.5 HOURS PRIOR TO PHASE MAINTENANCE. THIS WOULD CREATE EXCESSIVE NON-MISSION CAPABLE MAINTENANCE (NMCM) AND INTERFERE WITH MISSION POSTURE. SOLUTION: IN ORDER TO MINIMIZE THE NMCM TIME, AUTHORIZATION IS REQUESTED TO EXTENT THE TBO TIME, 18.5 AIRCRAFT HOURS TO COINCIDE WITH PHASE MAINTENANCE AT 5892.5 AIRCRAFT HOURS. CURRENT AIRCRAFT HOURS: 5812.1 TBO DUE: 5874.0 ACFT HRS PHASE MAINTENANCE DUE: 5892.5 ACFT HRS</p>	<p>D CO 7-101 GSAB, KANDAHAR, AFGHANISTAN 09355</p>	<p>19-Jun-2011</p>	<p>1</p>	<p>DM378494</p>
<p>ACFT TRANSFERRED TO WVDB0 [CO B, 2-135 GSAB] AT 5894.8 A/C HRS</p>	<p>CO B, 2-135 GSAB (NE ARNG), KANDAHAR, AFGHANISTAN 09355</p>	<p>25-Jul-2011</p>	<p>1</p>	<p>GC861361</p>
<p>400 HR PMS3 COMPLETED AT 5894.8 ACFT HRS, NEXT INSP. 200 HR PMS2 DUE AT 6094.8 ACFT HRS</p>	<p>L3, 563RD ASB, KANDAHAR, AFGHANISTAN 09355</p>	<p>28-Aug-2011</p>	<p>1</p>	<p>JH930989</p>
<p>FINAL COMPLIANCE OF H-47-11-AMAM-03 (CHANGE 62) COMPLETED</p>	<p>D CO 7-101 GSAB, KANDAHAR, AFGHANISTAN 09355</p>	<p>24-Sep-2011</p>	<p>3</p>	<p>MA516322</p>
<p>FWD SWASHPLATE SN: A84973 MODIFIED IAW ARW DATED 30SEP2005 AT ACFT HRS 5993.0</p>	<p>DCO. 7-101 GSAB, KANDAHAR, AFGHANISTAN 09355</p>	<p>29-Sep-2011</p>	<p>1</p>	<p>JS042835</p>
<p>13OCT2011- MEC# F134687. AFT LEFT HAND LANDING GEAR TRUNNION CRACKED AT LOWER INBOARD CORNER. CRACK APPROX. 2 INCHES LONG. AUTHORIZED TO REPLACE THE LH AFT TRUNNION ASSY, P/N 114S3849-1. ACFT HRS: 6015</p>	<p>D CO, 7-101 GSAB, KANDAHAR, AFGHANISTAN 09355</p>	<p>13-Oct-2011</p>	<p>1</p>	<p>WJ173089</p>
<p>22OCT11- MEC# F135233. FITTING ATTACHMENT PN 114S4801-1 FOR AFT PYLON STA 482, BL 20L, WL 60, MOST FORWARD ON LEFT HAND SIDE DRILLED INTO SEVERAL TIMES ON FACE. 100H NDI REQUIRED UNTIL COMPONENT REPLACEMENT. FROM ACFT HOURS 6015.5</p>	<p>DCO 7-101 GSAB, KANDAHAR, AFGHANISTAN 09355</p>	<p>25-Oct-2011</p>	<p>3</p>	<p>JS042835</p>

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
FINAL COMPLIANCE WITH H-47-12-SOF-01 (DECU) COMPLETED PASS	B CO 563D ASB, KANDAHAR, AFGHANISTAN 09355	23-Nov-2011	1	TS333739
AIRCRAFT INSPECTED WITH AIRFRAME CONDITION EVALUATION CRITERIA BY AMCOM ACE TEAM	2-135TH GSAB, KANDAHAR, AFGHANISTAN 09355	04-Dec-2011	1	GC861361
#1 AFT ENG MOUNT OUTBOARD LUG HAS BEEN REEMED AND OVERSIZED BUSHING MANUFACTURED I/A/W MEC # F137363	B CO 563D ASB, KANDAHAR, AFGHANISTAN 09355	11-Dec-2011	1	TS333739
PMS2 COMPLETED @ 6096 ACFT HOURS NEXT DUE PMS3 @ 6294.8 ACFT HRS	B CO 563D ASB, KANDAHAR, AFGHANISTAN 09355	11-Dec-2011	2	TS333739
IN REFERENCE TO MEC# F135233. FITTING ATTACHMENT PN 114S4801-1 FOR AFT PYLON STA 482, BL 20L, WL 60, MOST FORWARD ON LEFT HAND SIDE, PART WAS REPLACED ON 3DEC11 AT 6095.5 ACFT HRS.	D CO 7-101, KANDAHAR, AFGHANISTAN 09355	12-Dec-2011	1	MP040369
A3T INSP. COMPLETED AT ACFT HRS. 6101.5 BY TEAM MEMBERS "S" AND "NN"	TASM-E/DYNCORP INTERNATIONAL, KANDAHAR, AFGHANISTAN 09355	13-Dec-2011	1	WC643445
H-47-11-AMAM-04 AN/ASN-128D DOPPLER AND AVIATION MISSION PLANNING SYSTEM (AMPS) SOFTWARE UPGRADE COMPLIED WITH 07MAR2012 ACFT HRS 6294.8	L3 VERTEX, KAF, AFGHAN. 09355	08-Mar-2012	1	JH930989
VISUAL AND NDI INSPECTION PERFORMED ON #1 AND #2 ENGINE FORWARD MOUNTS, AS WELL AS #1 AND #2 ENGINE DRAG LINKS. INSPECTION PERFORMED AT 6294.8 ACFT HRS.	L3 VERTEX, KAF, AFGHAN. 09355	10-Mar-2012	1	JH930989
PMS 3 COMPLETED AT 6294.8 AIRCRAFT HOURS. PMS 2 DUE AT 6494.8 AIRCRAFT HOURS.	L3 VERTEX, KAF, AFGHAN. 09355	20-Mar-2012	1	JH930989
ACFT TRANSFERRED TO WYQSB0 [CO B, 1-189 GSAB] AT 6393 ACFT HRS	B CO 1-189TH GSAB, KANDAHAR, AFGHANISTAN 09355	02-May-2012	1	RE195484
H-47-12-AMAM-02 COMPLIANCE (MAY 12,2012) FWD;AFT;C-BOX;1/2ENG XMSN OIL SAMPLE FREQUENCY CHANGED FROM 50HRS TO 400HRS	1/189TH AV BN, KANDAHAR, AFGHANISTAN 09355	30-May-2012	1	RK414064
PMS 2 COMPLETED AT 6494.8 ACFT HRS. NEXT PHASE PMS3 DUE AT 6694.8 ACFT HRS.	L-3 VERTEX, KANDAHAR, AFGHANISTAN 09355	23-Jun-2012	1	RG067435

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
H-47-12-ASAM-01 YAW INTEGRATED LOWER CONTROL ACTUATOR INPUT CONTROL HARDWARE/ HYD PRESSURE TUBE CLEARANCE, C/W @ 6594.8 ACFT HRS.	B 1/111TH GSAB, KANDAHAR, AFGHANISTAN 09355	15-Aug-2012	1	RW500223	
COMPLIED WITH H-47-12-AMAM-04 (FADEC EMERGENCY PROCEDURE CHANGE)	B CO 1-189TH AV, KANDAHAR, AFGHANISTAN 09355	19-Sep-2012	1	RE195484	
600 HR FWD ENG MOUNT INSP COMPLETED ON #2 FWD ENG MOUNT AT 6694.8 ACFT HRS.	L3 VERTEX CFT, KANDAHAR, AFGHANISTAN 09355	23-Sep-2012	1	DG769497	
PMS 3 400 HRS COMPLETED @ 6694.8 ACFT HRS. PMS2 DUE AT 6894.8 ACFT HRS.	L-3 VERTEX CFT, KANDAHAR, AFGHANISTAN 09355	03-Oct-2012	1	RL621128	
COMPLIED WITH H-47-13-ASAM-01	DCO 325 GSAB, KANDAHAR, AFGHANISTAN 09355	23-Oct-2012	1	DF431908	
COMPLIED WITH H-47-13-AMAM-02; ULLS-A(E) LCF CHANGE 63 REQUIREMENTS	D CO 3-25 AVN REGT, KANDAHAR, AFGHANISTAN 09355	02-Dec-2012	1	DF431908	
ASAM H-47-13-ASAM-02 " MID CABIN HATCH CARGO HOOK" COMPLIED WITH. 13-1 ENTRIES COMPLETED	D CO 2-3, KANDAHAR, AFGHANISTAN 09355	15-Dec-2012	1	BA896549	
MAINTANCE ENGINEERING ORDER NO # A6278 CH-47 WINDSHIELD/WINDSCREEN DAMAGE IN SOUTHWEST ASIA . INSPECT WINDSHIELD BEFORE AND AFTER AVERY FLIGHT. POC NICK HURTA, LE TEAM DSN # 861-2551	D CO 2-3, KAF	17-Dec-2012	1	BA896549	
COMPLY WITH ASAM H-47-13-ASAM-03 " INFRARED SUPPRESSOR SYSTEM" ACFT FINAL COMPLIANCE 16 JUN 13.	D CO 2-3, KAF	17-Dec-2012	2	BA896549	
AIRCRAFT RECEIVED CONUS FROM OEF, TRANSFERRED TO DET 1, CO. B, 1-189TH GSAB, MONTANA ARNG, WYQSB1 , HELENA, MT	AASF MTARNG, HELENA, MT 59602	31-Jan-2013	1	WI782929	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
<p>MEC NUMBER: F167609 PROBLEM: DURING INSPECTION THE MONTANA NATIONAL GUARD UNIT FOUND ON THE FWD YELLOW M/R BLADE WAS A CRACK APROX .5" ON THE EROSION STRIP LEADING EDGE AT THE END OF THE BLADE. AIRCRAFT IS PLANNED FOR RETIREMENT AND BEING FLOWN TO DELAWARE ONCE THE AIRCRAFT IS FMC.</p> <p>THE UNIT REQUESTS AUTHORIZATION TO REPAIR THE CRACK BY USING A STANDARD TM 1-1500-204 SHEET METAL REPAIR BY VACUUM SUCTION. THE CRACKED ARE WILL HAVE 9309.9 HYSOL APPLIED TO THE AREA AND THE EROSION STRIP WILL BE ADREDED USING THE VACUUM SUCTION REPAIR METHOD ALL PARTS AND MATERIALS ON HAND AND EXPERIENCE PERSONNEL WILL BE PERFORMING THIS REPAIR</p> <p>ENGINEERING DISPOSTION: MONTANA NG IS AUTHORIZED TO REPAIR THE MAIN ROTOR BLADE PN#114R1702-37 SN A1-1944 AS FOLLOWS: 1 REMOVE DAMGE 2 FILL AND FAIR THE VOIDED AREA USING 9309.3. 3 PRIOR TO EACH FLIGHT INSPECT FOR : A. DEBONDING USING A TAP TEST B. CRACKING USING A 10X MAGNIFYING GLASS 4 THIS REPAIR WILL BE FLOWN NO MORE THAN 40 AIRCRAFT HOURS. IF BLADE MUST BE USED LONGER, IT MUST HAVE ABRASION STRIP REPLACED AT AN APPROPRIATE FACILITY CURRENT AIRCRAFT HOURS 6836.0 MEC COVERS UNTIL 6876.0</p>	MT AASF, HELENA, MT 59602	11-Jun-2013	1	JN178524
H-47-13-SOF-02 SYNC SHAFT BOLTS COMPLIED WITH 14 JUNE 2013	MT AASF, HELENA, MT 59602	14-Jun-2013	1	JN178524
COMPLIED WITH GEN-13-AMAM-04 TRACKING OF AN/APN-209 COMPONENTS (RAD ALT)	MT AASF, HELENA, MT 59602	25-Jul-2013	1	DD199891
COMPLIED WITH H-47-13-AMAM-04 LCF CHANGE 64	MT AASF, HELENA, MT 59602	25-Jul-2013	2	JN178524
AIRCRAFT IS IN COMPLIANCE OF AWR TTS 835544A R1 DATED 16 MAY 2012 (LATE ENTRY)	MT AASF, HELENA, MT 59602	14-Aug-2013	1	JN178524
AIRCRAFT IS IN COMPLIANCE WITH TTS 69499E (R-9) DTD 16 MAR 12 (BFT/EDM)	MTAASF, HELENA, MT 59602	14-Aug-2013	2	JN178524

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8424159		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
AIRCRAFT IS IN COMPLIANCE WITH AWR TN 64589J R4 DATED 20 MAR 13 (ELECTRONIC CONTROL UNIT)	MT AASF, HELENA, MT 59602	15-Aug-2013	1	JN178524	
AIRCRAFT IS IN COMPLIANCE WITH AWR TTS 41283S DATED 24 JULY 12 R 15 (MSPU)	MT AASF, HELENA, MT 59602	15-Aug-2013	2	JN178524	
COMPLIED WITH H-47-13-ASAM-06 IMPROPERLY INSTALLED FASTENERS	B CO, 1-189TH GSAB, HELENA, MT 59602	22-Aug-2013	1	BS178633	