

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
AIRCRAFT S/N 66-19028, CH-47A, INDUCTED AND CONVERTED TO CH-47D, S/N 86-1654 ON 20 FEB 87. TOTAL TIME AT MODIFICATION;3375.5 HRS. (NO PID)	THE BOEING CO., PHILA., PA	03-Mar-1987	1	QC000000
PLASTIC MEDIA BLASTING (PMB) WILL BE ACCOMPLISHED IN THE STRIPPING OF THE AIRFRAME AS PART OF THE "D" MODIFICATION PROGRAM. TOTAL TIME AT MODIFICATION; 3375.5 HRS. (NO PID)	THE BOEING CO., PHILA., PA	03-Mar-1987	2	QC000000
TB 55-1520-241-20-40 ONE TIME INSPECTION OF CH47A,B, C, & D HELICOPTERS WITH ENGINE TRANSMISSION BREATHER LINES INSTALLED, COMPLIED WITH. (NO PID)	THE BOEING CO., PHILA., PA	26-Mar-1987	1	QC000000
AIRCRAFT S/N 86-1654 TEST FLOWN AND ACCEPTED AT 3382.5 ACFT HRS. (NO PID)	THE BOEING CO., PHILA., PA	31-Mar-1987	1	QC000000
SOF MESSAGE CH-47-87-06 REPLACEMENT OF ENG DRIVE SHAFT BOLTS COMPLIED WITH ON 21 JUL 87 AT 3434.8 ACFT HRS. (NO PID)	179TH AVN CO., FT. CARSON, CO 80913	21-Jul-1987	1	QC000000
SOF MESSAGE CH-47-87-08 IMMEDIATE GROUNDING FOR REPLACEMENT OF 3-WAY HYDRAULIC VALVES COMPLIED WITH ON 21 JUL 87 AT 3434.9 ACFT HRS. (NO PID)	179TH AVN CO., FT. CARSON, CO 80913	21-Jul-1987	2	QC000000
OCM/ACE PERFORMED AT 3433 ACFT HRS AT FT. CARSON. (NO PID)	AVSCOM OCM SECTION, ST. LOUIS, MO 80913	10-Aug-1987	1	QC000000
SOF MSG CH-47-87-10 ONE TIME INSPECTION OF BEVELED WASHERS ON ALL DRIVE SHAFTS FLEX PLATES COMPLIED WITH THIS STATION AT 3436.2 ACFT HRS. (NO PID)	A CO 2ND BN 158 AVN REGT, FT. CARSON, CO 80913	16-Sep-1987	1	QC000000
SOF MSG CH-47-87-12 INSO OF AFT & COMBINING XMSN FAN BEARING COMPLIED WITH THIS STATION AT 3459.2 ACFT HRS. (NO PID)	A CO 2ND BN 158 AVN REGT, FT. CARSON, CO 80913	03-Nov-1987	1	QC000000
SOF MSG CH-47-87-13 INSP OF FUEL FLOW TRANSMITTERSCOMPLIED WITH THIS STATION AT 3459.2 ACFT HRS. (NO PID)	A CO 2ND BN 158 AVN REGT, FT. CARSON, CO 80913	09-Nov-1987	1	QC000000
SOF MSG CH-47-87-14 INSP OF FLIGHT CONTROL & UTILITY HYD PUMP HOUSING RETAINING SCREW COMPLIED WITH ON 3473.7 ACFT HRS THIS STATION. (NO PID)	A CO 2ND BN 158 AVN REGT, FT. CARSON, CO 80913	09-Dec-1987	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
PERMANENT REPAIRS DONE TO #1 AND #2 FUEL FLOW TRANSMITTERS IAW SOF MSG. CH-47-87-13 AT THIS STATION BY CONTRACT TEAM. 3492.6 ACFT HRS. (NO PID)	A CO 2ND BN 158 AVN REGT, FT. CARSON, CO 80913	25-Jan-1988	1	QC000000	
SOF MSG CH-47-88-03 ONE TIME INSP OF HEATER FUEL LINE AND ELECTRICAL COMPONENTS FOR CHAFFING COMPLIED WITH AT 3507.0 ACFT HRS. (NO PID)	A CO 158 AVN REGT, FT. CARSON, CO 80913	07-Mar-1988	1	QC000000	
SOF MSG CH-47-88-07 INSPECTION OF #1 AND #2 ENG DRIVE SHAFT ASSY COMPLIED WITH AT 3509.7 ACFT HRS THIS STATION. (NO PID)	A CO 2 BN 158 AVN REGT, FT. CARSON, CO 80913	23-Mar-1988	1	QC000000	
SOF MSG CH-47-88-08 ONE TIME & RECURRING INSP OF #1 & #2 ENG D/S/ BOLTS, COMPLIED WITH THIS STATION AT 3471.0 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	05-May-1988	1	QC000000	
LATE ENTRY: OXYGEN SYSTEM INSTALLED 24MAY88 I/A/W AVSCOM LETTER DATED 4AUG87 BY IAMB DOL FT. CARSON.02 SYSTEM TO BE REMOVED FROM AIRCRAFT WHEN HIGH ALTITUDE MISSIONS ARE NO LONGER REQUIRED OR ACFT IS PERMANENTLY TRANSFERRED FROM FT. CARSON, CO. (NO PID)	IAMB, DOL, FT. CARSON, CO 80913	10-Jun-1988	1	QC000000	
SOF MSG CH-47-88-11 ONE TIME INSPECTION OF PIVOTING AND SWIVELING SERVO CYLINDER COMPLIED WITH THIS STATION AT 3513.0 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	10-Jun-1988	2	QC000000	
SOF MSG CH-47-88-10 CH-47D AIRCRAFT FLIGHT CONTROLAND UTILITY HYDRAULIC PUMP RETAINING SCREWS REPLACEMENT COMPLIED WITH THIS STATION AT 3513.0 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	13-Jun-1988	1	QC000000	
SOF MSG CH-47-88-12 MAINTENANCE AND ONE TIME INSPECTION OF C-BOX FAN ASSY AND RETORQUE OF AFT AND C-BOX FAN ASSY. C/W THIS STATION 28 JUN 88 AT 3513.0 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	28-Jun-1988	1	QC000000	
SOF MSG CH-47-88-13 DEPOT LEVEL INSPECTION OF C-BOX COOLER FAN ASSY. C/W THIS STATION AT 3515.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	11-Jul-1988	1	QC000000	
SOF MSG CH-47-88-14 ONE TIME INSPECTION OF PIVOTING AND SWIVELING SERVO CYLINDERS COMPLIED WIWITH THIS STATION AT 3517.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	22-Jul-1988	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
OCM/ACE PERFORMED AT 3517 ACFT HRS AT FT. CARSON CO BY ACE TEAM MEMBER I AVSCOM OCM SEC ST. LOUIS MO. (NO PID)	OCM/ACE TEAM, AVSCOM OCM SEC ST. LOUIS, MO	24-Aug-1988	1	QC000000
SOF MSG CH-47-88-15, PROCEDURE FOR FUEL SAMPLING WHEN USING THE EXTENDED RANGE FUEL SYSTEM (ERFS) C/W THIS STATION 26 SEP 88 AT 3517.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	26-Sep-1988	1	QC000000
SOF MSG GEN-88-02, ONE TIME INSPECTION OF INTERNALPORTABLE FIRE EXTINGUISHER C/W THIS STATION AT 3527.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	30-Sep-1988	1	QC000000
SOF MSG CH-47-88-18, CH-47D AIRCRAFT ENGINE CROSS SHAFTS INSPECTION C/W THIS STATION 18 NOV 88 AT 3519.7 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	18-Nov-1988	1	QC000000
SOF MSG CH-47-88-20, COMPLIED WITH THIS STAION 13 DEC 88 AT 3526.5 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	13-Dec-1988	1	QC000000
SOF MSG CH-47-88-21, ALL CH-47 SERIES A/C INSTR FOR RETURNING A/C TO FULL FLIGHT STATUS C/W THIS STATION 14 DEC 88. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	14-Dec-1988	1	QC000000
SOF MSG CH-47-88-22, C/W BY ADDING FWD AND AFT XMSN SERIAL NUMBER THIS STATION 28 DEC 88 AT 3526.5 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	28-Dec-1988	1	QC000000
SOF MSG CH-47-89-02, SUPERCEDE BY SOF MSG CH-47-89-03. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	09-Feb-1989	1	QC000000
SOF MSG CH-47-89-04, INSP OF FWD AND AFT HORIZONTAL BEARING (ROTARY WING HEAD) C/W THIS STATION 14 FEB 89 AT 3526.5 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	14-Feb-1989	1	QC000000
SOF MSG CH-47-89-03, GROUNDING FOR APPLICATION OF MWO 55-1520-240-50-38 COMPLIED WITH AT 3526.5 ACFTHRS. THIS STATION BY PROJECT OLR(LSSI) FT. CARSON,CO. 80913 (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	17-Feb-1989	1	QC000000
MWO 55-1520-240-50-38, COMPLIED WITH THIS STATION AT 3526.5 ACFT HRS BY OLR A CO 2/158 AVN REGT FT. CARSON, CO 80913. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	17-Feb-1989	2	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF MSG CH-47-88-23, ONE TIME INSP OF FWD XMSNS IMPELLER ASSY C/W THIS STATION 13 MAR 89 AT 3537.9ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	14-Mar-1989	1	QC000000
SOF MSG CH-47-89-05, INITIAL INSP OF CONTROL COMPONENTS WITH ALBI PAINT AND FIRE SLEEVES C/W THIS STATION 5 APR 89 AT 3564.0 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	05-Apr-1989	1	QC000000
SOF MSG CH-47-89-06, INSP ENGINE CROSS DRIVE SHAFT AND CHANGE INTERVAL C/W THIS STATION 26 JUN 89 AT 3578.8 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	26-Jun-1989	1	QC000000
MWO 55-1520-240-50-25, COMPLETED AT 3578.8 ACFT HRS THIS STATION FT. CARSON, CO 80913 BY PROJECT OLR. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	26-Jun-1989	2	QC000000
MWO 55-1520-240-50-30, COMPLETED AT 3578.8 ACFT HRS THIS STATION FT. CARSON, CO 80913 BY PROJECT OLR. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	26-Jun-1989	3	QC000000
SOF MSG CH-47-89-01, CONVERSION FROM PPM TO PHASE MAINTENANCE COMPLETED AT 3578.8 ACFT HRS THIS STATION BY PROJECT OLR FT. CARSON, CO 80913. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	10-Jul-1989	1	QC000000
PHASE #1-4 COMPLETED AT 3578.8 ACFT HRS THIS STATION FT. CARSON, CO 80913. PHASE #3 CYCLE #2 DUE AT 3778.8 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	10-Jul-1989	2	QC000000
SOF MSG CH-47-89-07, ONE TIME INSP OF ILCA JAM NUTS C/W THIS STATION AT 3589.4 ACFT HRS ON 4AUG89 (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	04-Aug-1989	1	QC000000
OCM/ACE PERFORMED AT FT. CARSON, CO BY ACE TEAM MEMBER W AVSCOM OCM SEC, ST. LOUIS, MO. (NO PID)	OCM/ACE TEAM W, AVSCOM OCM SEC, ST. LOUIS, MO	07-Aug-1989	1	QC000000
SOF MSG CH-47-89-09, IMMEDIATE GROUNDING OF CH-47DACFT WITH 145DS518-4 C-BOX COOLER FANS COMPLIED WITH 11 AUG 89 THIS STATION ON 3 OCT 89 AT 3589.4 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	11-Aug-1989	1	QC000000
SOF MSG CH-47-89-10, INSPECTION AND DEGREASING OF C-BOX COOLER FAN D/S, C/W THIS STATION ON 3 OCT 89AT 3589.4 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	03-Oct-1989	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF MSG CH-47-89-08, IMMEDIATE GROUNDING OF CH-47DACFT WHITH C-BOX COOLER FAN P/N 145DS518-3 COMPLIED WITH THIS STATION AT 3589.4 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	21-Oct-1989	1	QC000000
SOF MSG CH-47-89-11, UNGROUNDING REQUIREMENTS FOR CH-47D ACFT. C/W 21 OCT 89 THIS STATION AT 3589.4 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	21-Oct-1989	2	QC000000
SOF MSG CH-47-89-12, IMMEDIATE GROUNDING OF CH-47DACFT C/W THIS STATION 30 AUG89 AT 3595.8 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	30-Oct-1989	1	QC000000
SOF MSG CH-47-89-13, UNGROUNDING REQUIREMENT FOR CH-47D ACFT COMPLIED WITH 29 NOV 89 THIS STATION AT 3595.8 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	29-Nov-1989	1	QC000000
SOF MSG CH-47-89-15, EXTENSION OF C-BOX COOLER FAN D/S INSP AND FINITE LIFE INCREASE OF OIL COOLER FAN P/N 145DS5518-15 C/W THIS STATION 22 DEC 89 AT 3603.9 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	22-Dec-1989	1	QC000000
SOF MSG CH-47-90-01, UNGROUNDING REQUIREMENTS OF " FAN EATERS" AND CHANGES TO CH-47-89-11, FOR ALL CH-47D ACFT. C/W THIS STATION 16 JAN 90 AT 3605.6 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	16-Jan-1990	1	QC000000
LATE ENTRY: SOF MSG CH-47-87-11, REDUCED INSPECTION INTERVAL FOR C-BOX FAN AND D/S, C/W 2 OCT 87 THIS STATION AT 3450.0 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	1	QC000000
LATE ENTRY: REVISION TO REPLACEMENT OF ENGINE CROSS SHAFT BOLTS (CH-47-87-06) COMPLIED WITH 21 JUL 87 THIS STATION AT 3434.8 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	2	QC000000
LATE ENTRY: SOF MSG CH-47-88-04, CLEARING OF RED XPROCEDURES COMPLIED WITH 16 MAR 88 THIS STATION. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	3	QC000000
LATE ENTRY: SOF MSG CH-47-88-05, REVISION TO CH-47D ENGINE XMSN CLUTCH FAILURE TO ENGAGE PROCEDURES COMPLIED WITH 17 MAR 88. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	4	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
LATE ENTRY: SOF MSG CH-47-88-09, IDENTIFICATION OF ADDITIONAL EMERGENCY DESCENT PROCEDURES COMPLIED WITH 29 APR 88. THIS STATION FT. CARSON, CO 80913. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	5	QC000000
LATE ENTRY: SOF MSG CH-47-88-16, IDENTIFICATION OF ADDITIONAL EMERGENCY DESCENT PROCEDURES COMPLIED WITH 03 NOV 88. THIS STATION FT. CARSON, CO 80913. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	6	QC000000
LATE ENTRY: SOF MSG CH-47-88-17, CORRECTION TO IDENTIFICATION OF ADDITIONAL EMERGENCY DESCENT PROCEDURES COMPLIED WITH 9 NOV 88 THIS STATION FT. CARSON, CO. 80913. (NO PID)	P CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	7	QC000000
LATE ENTRY: SOF MSG CH-47-88-19, ONE TIME AND RECURRING INSPECTION OF FWD XMSN IMPELLER ASSY COMPLIED WITH THIS STATION AT 3536.0 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	8	QC000000
LATE ENTRY: SOF MSG CH-47. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	23-Jan-1990	9	QC000000
SOF MSG CH-47-90-03 EXTENSION OF COMBINING XMSN COOLER FAN D/S REGREASE TO 100 HRS. COMPLIED WITH 30 JAN 90 THIS STATION AT 3609.9 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	30-Jan-1990	1	QC000000
SOF MSG CH-47-90-02, RECURRING EDDY CURRENT INSP OF ENGINE CROSS SHAFTS COMPLIED WITH 2 FEB 90 THIS STATION AT 3612.9 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	02-Feb-1990	1	QC000000
SOF MSG CH-47-90-04, CH-47C ACFT, CARGO HOOK/WINCH CONTROL LOAD RELEASE BUTTON GUARD, COMPLIED WITH 19 MAR 90 THIS STATION AT 3638.6 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	19-Mar-1990	1	QC000000
SOF MSG CH-47-90-05, EXTENSION OF ACFT POWERTRAIN VIBRATION TEST FROM 25 HRS TO 50 HRS AND ADDITIONAL CORRECTION PROCEDURES TO SOF MSG CH-47-90-01, COMPLIED WITH 12 APR 90 THIS STATION AT 3649.9 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	12-Apr-1990	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF MSG CH-47-90-07, ACFT GROUNDED FOR ONE TIME INSP OF FWD XMSN MOUNT BARREL NUTS PRIOR TO NEXT FLIGHT, COMPLIED WITH 20 APR 90 THIS STATION AT 3656.6 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	20-Apr-1990	1	QC000000
SOF MSG CH-47-90-08, CLARIFICATION OF ONE TIME INSP OF CH-47D FWD XMSN MOUNT BARREL NUTS (CH-47-90-07) COMPLIED WITH 20 APR 90 THIS STATION AT 3656.6 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	20-Apr-1990	2	QC000000
SOF MSG CH-47-90-09, ONE TIME AND RECURRING INSP OF PITCH LINK RETAINING HARDWARE, COMPLIED WITH THIS STATION AT 3659.4 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	27-Apr-1990	1	QC000000
SOF MSG CH-47-90-06, ONE TIME RECURRING INSP OF AFT XMSN COOLER FAN, ACFT REST. FROM INTENTIONAL IMC FLIGHT, COMPLIED WITH 27 APR 90 THIS STATION AT 3659.4 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	27-Apr-1990	2	QC000000
SOF MSG CH-47-90-10, ONE TIME AND RECURRING INSP OF RIGHT HAND AFT BELLCRANK SUPPORT STRUCTURE, COMPLIANCE MESSAGE NOT APPLICABLE AT THIS STATION AND SERIES ACFT AT 3673.3 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	24-May-1990	1	QC000000
SOF MSG CH-47-90-11, ONE TIME INSP OF FUEL PUMP ELECTRICAL GROUND AND REVISION TO FUEL SYSTEM. COMPLIED WITH 2 AUG 90 THIS STATION AT 3715.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT CARSON, CO 80913	02-Aug-1990	1	QC000000
OCM/ACE PERFORMED AT 3715 ACFT HRS, FT CARSON CO BY ACE TEAM MEMBER X ANSCOM OCMSEC, ST. LOUIS, MO. (NO PID)	OCM/ACE TEAM X, AVSCOM OCMSEC ST. LOUIS, MO	31-Aug-1990	1	QC000000
SOF MSG CH-47-90-12 ONE TIME INSP & MODIFICATION OF HYDRAULIC LINE CLAMPS COMPLIED WITH 12 SEP 90 AT 3730.5 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO. 80913	12-Sep-1990	1	QC000000
SOF MSG CH-47-90-13 ONE TIME INSP & REMOVAL OF CH-47D FWD XMSN CONTAINING SUSPECT ROTOR SHAFTS, COMPLIED WITH THIS STATION 26 SEP 90 AT 3730.5 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO. 80913	26-Sep-1990	1	QC000000
LATE ENTRY: ACFT ARRIVED IN SWA. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO. 80913	04-Jan-1991	1	QC000000
PHASE #3 CYCLE 2 COMPLETED 19 JAN 91 AT 3766.9 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO. 80913	19-Jan-1991	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
LATE ENTRY: CH-47-91-ASAM-01, AFT XMSN FAN VIBRATION CHECK C/W 3769.9 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO. 80913	22-Jan-1991	1	QC000000
AVIATION SAFETY ACTION MESSAGE CH-47-91-ASAM-02, OPERATIONAL INSP OF ALL CH47D ACFT TO DETERMINE COMPLIANCE OF MWO 55-1520-240-50-43, COMPLETED 3821.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO. 80913	10-Mar-1991	1	QC000000
CH-47-ASAM-03, REVISION OF CHECK LIST FOR CH-47D ACFT INVOLVED IN OPERATION DESERT STORM C/W 3821.1ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO. 80913	10-Mar-1991	2	QC000000
MWO 55-1520-240-50-43, INSTALLATION OF ONE PIECE DRIVE SHAFT C/W BY DYNACORP OLR, KKMC, S. A. APO NY 09734. (NO PID)	DYNACORP OLR, KKMC, S. A. APO NY 09734	01-Apr-1991	1	QC000000
SOF MSG CH-47-97-01, EMERGENCY ONE TIME INSP AND REMOVAL OF COMB AND ENG XMSN CONTAINING SUSPECT INPUT PINIONS AND GEARS COMPLETED AT 3851.5 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, APO NY 09734	03-Apr-1991	1	QC000000
MWO 55-1520-240-50-54, INSTALLATION OF AN/APR-39 (V), INSTALLATION WITH DEPOT ASSISTANCE BY A CO 2/158 AVN REGT. (NO PID)	A CO 2/158 AVN REGT, APO NY 09734	03-Apr-1991	2	QC000000
CH-47-ASAM-05, READJUSTMENT OF TSN OF CERTAIN COMPONENTS ON ACFT THAT HAVE OPERATED ABOVE 50,000LBS.(OVER 50,000 LBS. LIMITATION NOT EXCEEDED). C/W 3869.2 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, APO NY 09734	01-May-1991	1	QC000000
SOF MSG CH-47-91-02, UPDATE TO CH-47-91-01 TO IDENTIFY SERVICEABLE COMBINER XMSN AND ENG XMSN, C/W AT 3877.7 ACFT HRS, 17 MAY 91. (NO PID)	A CO 2/158 AVN REGT, APO NY 09734	18-May-1991	1	QC000000
ACFT ARRIVED IN CORPUS CHRISTI, TX. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON CO 80913	27-Jul-1991	1	QC000000
ASAM(CH-47-91-ASAM-08) TB 55-1520-240-20-58 ALL CH-47D AND MH-47D SERIES ACFT, ONE TIME AND RECURRING INSP OF FWD AND AFT XMSN SUPPORT STRUCTURE, INITIAL REQUIREMENTS COMPLIED WITH AT 3885.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON CO 80913	04-Sep-1991	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-91-ASAM-04, LATE ENTRY, ALL CH-47C ONE TIME INSP AND REMOVAL OF CROSS SHAFT P/N 114D3247-1 CONTAINING XMSN SHAFT ADAPTER P/N 114D32444-1. NOTAPPLICABLE THIS ACFT. C/W AT 3885.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON CO 80913	17-Sep-1991	1	QC000000
LATE ENTRY, CH-47-91-ASAM-06, ALL CH-47D AND MH-47D OPERATING IN SWA, INSTALLATION OF NEW FWD XMSN AIR INLET DUCT. NOT APPLICABLE THIS ACFT. C/WAT 3885.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON CO 80913	17-Sep-1991	2	QC000000
LATE ENTRY, CH-47-91-ASAM-07, MAINTENANCE INFORMATION ON T55-L712 ENGINE C/W AT 3885.1 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON CO 80913	17-Sep-1991	3	QC000000
OCM/ACE PERFORMED AT 3899.0 ACFT HRS AT FT. CARSONCO BY ACE TEAM MEMBER I AVSCOM OCMSEC, ST. LOUIS, MO. (NO PID)	OCM/ACE TEAM I REGT, AVSCOM OCMSEC, ST. LOUIS, MO	01-Oct-1991	1	QC000000
ASAM CH-47-91-01, ONE TIME INSP FOR INTERFERENCE WITH ENGINE CROSS SHAFT AND RIGHT HAND COVER. COMPLIED WITH 22 OCT 91 BY IAMB, DOL, FT. CARSON, CO. 80913. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	22-Oct-1991	1	QC000000
CH-47-92-ASAM-02, ONE TIME INSP OF GENERATOR WIRE HARNESS AT THE FIRE EXTINGUISHER DISCHARGE TUBE. C/W 2 DEC 91 THIS STATION AT 3899.3 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	02-Dec-1991	1	QC000000
PHASE #4 CYCLE 2 COMPLETED 1 APR AT 3966.9 ACFT HRS, PHASE #1 CYCLE 3 DUE AT 4166.9 ACFT HRS. AVSCOM PROJECT OLR FT CARSON, CO 80913. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	01-Apr-1992	1	QC000000
CH-47-92-ASAM-04, MAINT MANDATORY, ALL CH-47D, ANDMH-47D, AND MH-47E ACFT, ONE TIME RECURRING INSP OF CROSS SHAFT ADAPTERS COMPLIED WITH 23 APR AT 4006.5 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	27-Apr-1992	1	QC000000
CH-47-92-ASAM-05, MAINT. MANDATORY, ALL CH-47D, MH-47D, AND MH-47E ACFT, REPLACEMENT OF HI-LOC FASTENER IN L/H, R/H BUTT LINE 18 BEAMS AT FUSELAGE STA. 83 TO 120 TO BE COMPLIED WITH N/L/T THE NEXT PHASE INSP OR WHEN ACFT IS INDUCTED INTO THE STIR PROGRAM, WHICHEVER OCCURS FIRST. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	29-Jun-1992	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
OCM/ACE PERFORMED AT 4129 ACFT HRS AT FT CARSON COBY ACE TEAM MEMBER R AVSCOM OCMSEC, ST. LOUIS,MO. (NO PID)	OCM/ACE TEAM R, AVSCOM OCMSEC, ST. LOUIS, MO	02-Sep-1992	1	QC000000
SOF MSG CH-47-93-01, IMMEDIATE GROUNDING OF ALL CH-47 AND MH-47 SERIES ACFT, COMPLIED WITH THIS STATION 6 NOV 92 AT 4134.7 ACFT HRS. AVSCOM PROJECT OLR. FT CARSON, CO. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	06-Nov-1992	1	QC000000
SOF MSG CH-47-93-02, (TB 1-1520-240-20-63) UNGROUNDING OF ALL CH-47 AND MH-47 SERIES ACFT. COMPLIED WITH THIS STATION 6 NOV 92 AT 4134.7 ACFTHRS. AVSCOM PROJECT OLR. FT CARSON, CO. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	06-Nov-1992	2	QC000000
CH-47-93-ASAM-03, MAINT. MANDATORY, ALL CH-47D, MH-47D,MH-47E ACFT, ONE TIME INSP OF PUMPING UNIT HYDRAULIC. COMPLIED WITH THIS STATION 16 MAR 93 AT 4157.8 ACFT HRS. AVSCOM PROJECT OLR, FT. CARSON, CO 80913. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	16-Mar-1993	1	QC000000
TB1-1520-240-30-01, DESERT STORM ACFT REDEPLOYMENTSPECIAL INSP AND REPAIR FOR CH-47D ACFT. C/W 22 MAR 93 THIS STATION AT 4161.0 ACFT HRS. ATCOM PROJECT OLR, FT CARSON CO. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	22-Mar-1993	1	QC000000
CYCLE 3 PHASE 1-4 STIR PROGRAM COMPLETED 22 MAR 93AT 4161.0 ACFT HRS. THIS STATION. NEXT PHASE DUE AT 4334.7 ACFT HRS CYCLE 4 PHASE #1 ATCOM PROJECT OLR, FT CARSON, CO. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	22-Mar-1993	2	QC000000
LATE ENTRY, CH-47-93-ASAM-02, MAINTENANCE MANDATORY ALL CH-47D, MH-47D, AND MH-47E ACFT, INSP OF HI-LOC FASTENER AT FUSELAGE STA. 83 TO 120DUE AT EVERY PHASER INSP, COMPLIED WITH AT 4149.7 ACFT HRS. (NO PID)	A CO 2/158 AVN REGT, FT. CARSON, CO 80913	05-Apr-1993	1	QC000000
SOF CH-47-93-03 ONE TIME RECORD CHECK OF ENGINE XMSN, P/N 145D6300 SERIES, TO IDENTIFY UNSERVICABLE XMSN, COMPLIED WITH 16JUL93 AT 4266.3ACFT HRS. (NO PID)	C CO. 4/228 AVN REGT, APO AA 34042	21-Jul-1993	1	QC000000
#1 ENGINE EMERGENCY POWER PANEL TRIPPED FOR 3 SECONDS AT 890 DEGREES PTIT. (NO PID)	A CO. 2/158 AVN REGT, FT. CARSON, CO. 80913	24-Jul-1993	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-94-ASAM-01, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, AND MH-47E ACFT. ONE TIME & RECURRING INSPECTIONS OF ROTARY WING HEAD BUSHINGS TO BE COMPLIED WITH WITHIN 20 HRS/ 20 DAYS OR PRIOR TO INSTALLATION OF ROTARY WING HEAD ASSY P/N 145R2003-9 & 145R2004-18, WAS COMPLIED WITH AT 4332.9 ACFT HRS. (NO PID)	A CO. 2/158 AVN REGT, FT. CARSON, CO. 80913	21-Oct-1993	1	QC000000
ASAM CH-47-94-ASAM-02, AVIATION SAFETY ACTION MESSAGE, CH-47D, MH-47D & MH-47E, AMENDMENT TO ONETIME & RECURRING INSP*S OF ROTARY WING HEAD BUSHINGS, (CH-47-94-ASAM-01). (NO PID)	A CO. 2/158 AVN REGT, FT. CARSON, CO. 80913	29-Oct-1993	1	QC000000
OCM/ACE PERFORMED AT 4333 ACFT HRS FT. CARSON, CO. BY ACE TEAM MEMBER C. (NO PID)	OCM/ACE TEAM #C, AVSCOM OCM SEC ST. LOUIS, MO	29-Oct-1993	2	QC000000
ASAM CH-47-94-ASAM-03, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, AND MH-47E ACFT, ONE TIME AND RECURRING INSP OF CERTAIN RIGID CONNECTING LINKS, P/N 145C3340-10 UNTIL REPLACEMENT TO BE COMPLIED WITH AS SOON AS PRACTICAL, BUT N/L/T 10 HRS 14 DAYS, WAS COMPLIED WITH 4 FEB 94 AT 4334.7 ACFTHRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	04-Feb-1994	1	QC000000
ASAM CH-47-94-ASAM-04, MAINTENANCE MANDATORY, ALL (OH-58), (AH-1), (UH-1), (CH-47), CREW SEAT BELTS, TO BE COMPLIED WITH PRIOR TO NEXT FLIGHT, WAS COMPLIED WITH 10 FEB 94 AT 4336.5 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	10-Feb-1994	1	QC000000
CYCLE 4, PHASE #1 WAS COMPLETED 17FEB94 AT 4332.9 ACFT HRS. THE NEXT PHASE, CYCLE 4, PHASE #2 IS DUE AT 4532.9 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	17-Feb-1994	1	QC000000
ASAM CH-47-94-ASAM-05, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, & MH-47E ACFT, ONE TIME INSP OF THE 5,000 LB. TIE DOWN RECEPTACLE ASSY*S P/N 114S2893, TO BE COMPLIED WITH WITHIN 10 ACFT HRS. 14 DAYS, COMPLIED WITH 4MAY94 AT 4379.7 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	06-Apr-1994	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ASAM CH-47-94-ASAM-06, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, &MH-47E ACFT, ONE TIME & RECURRING INSP OF PUMPING UNIT HYDRAULIC, TO BE COMPLIED WITH WITHIN 10 FLT HRS. OR 5 DAYS, C/W 4MAY94 AT 4379.7 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	06-Apr-1994	2	QC000000
OCM/ACE PERFORMED AT 4432 ACFT HRS FT. CARSON, CO. BY U. (NO PID)	OCM SECTION, ST. LOUIS, MO.	06-Aug-1994	1	QC000000
SOF MSG CH-47-95-01, ALL CH-47D, MH-47D, * MH-47E ACFT, ONE TIME VISUAL INSPECTION OF UPPER BOOST ACTUATOR SERIAL NUMBERS TO INSURE PROPER SCREWS ARE INSTALLED. COMPLIED WITH 94-12-06, ACFT HRS 4450.4. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	06-Dec-1994	1	QC000000
ASAM CH-47-95-ASAM-01, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, AND MH-47E ACFT, ONE TIME AND RECURRING INSP OF THRUST IDLER ASSY, WAS COMPLIED WITH 14DEC94 AT 4460.2 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	14-Dec-1994	1	QC000000
ASAM CH-47-95-ASAM-02, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, AND MH-47E ACFT, ONE TIME TORQUE VERIFICATION OF THE NUTS SECURING THE NO. 1 AND NO. 2 PTU MOTOR PUMP, P/N 145HS140-8, TO BE COMPLIED WITH WITHIN 10 HRS OR 14 DAYS, WAS COMPLIED WITH 23 JAN 95 AT 4468.7 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	23-Jan-1995	1	QC000000
ASAM CH-47-95-ASAM-04, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, AND MH-47E ACFT, ONE TIME INSP FOR STRATOPOWER PUMPS NSN 1650-01-249-4341 AND REPORTING FOR TURN AROUND PROGRAM, TO BE COMPLIED WITH WITHIN 10 HRS/14 DAYS, WHICHEVER OCCURS FIRST WAS COMPLIED WITH 29 MAR 95 AT 4531.0 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	28-Mar-1995	1	QC000000
SOF MSG CH-47-95-02, ALL CH-47D, MH-47D, MH-47E ACFT, ONE TIME VISUAL INSP & TORQUE CHECK OF LOWER DRIVE LINK TO SWASHPLATE RETAINING HARDWARE, TO BE COMPLIED WITH PRIOR TO NEXT ENGINE RUNUP/ FURTHER FLIGHT, WAS COMPLIED WITH 9MAY95 AT 4531.0 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	09-May-1995	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ASAM CH-47-95-ASAM-05, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, &MH-47E ACFT, INSP & LUBRICATION OF THE FLIGHT CONTROL ROD END BEARINGS (ROLLING ELEMENT), TO BE COMPLIED WITH AT THE NEXT PHASE INSP & EVERY 3RD PHASE INSP THEREAFTER, WAS COMPLIED WITH 31MAY95 AT 4531.0 ACFT HRS. NEXT INSP IS DUE AT CYCLE 5, PHASE #1 AT 5131.0 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	31-May-1995	1	QC000000
CYCLE 4, PHASE #2 WAS COMPLETEDD 7JUL95 AT 4531.0 ACFT HRS. THE NEXT PHASE, CYCLE 4, PHASE #3 DUE AT4731.0 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO. 80913	07-Jul-1995	1	QC000000
ACE PERFORMED AT 4598 ACFT HRS AT FT. CARSON, CO. BY THE ACE TEAM MEMBER N. (NO PID)	ATCOM SECTION, ST. LOUIS, MO.	10-Aug-1995	1	QC000000
ASAM CH-47-95-ASAM-06, REVISION OF CH-47-95-ASAM--05, ALL CH-47D, MH-47D, &MH-47E ACFT, INSP AND LUBRICATION OF THE FLT CONTROL ROD END BEARINGS (ROLLING ELEMENT), TO BE COMPLIED WITH AT THE NEXT PHASE INSP & AT 1ST & 3RD PHASE INSPECTION THEREAFTER, WAS PREVIOUSLY COMPLIED WITH 31MAY95 AT 4531.0 ACFT HRS. NEXT INSP IS DUE AT CYCLE 4, PHASE #3 AT 4731.0 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO.80913	23-Aug-1995	1	QC000000
ASAM CH-47-95-ASAM-07, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, &MH-47E ACFT, ONE TIME RECORDS CHECK FOR MWO-1-1520-240-50-69, REINSTALLATION OF MWO-1-1520-240-50-69 FOR ROTOR HEADS THAT WERE MODIFIED IN EUROPE, AND RECURRING VISUAL INSP FOR SLIPPED BUSHINGS AND/OR CRACKED PITCH HOUSING LUGSFOR ROTOR HEADS THAT HAVE MWO1-1520-240-50-69 APPLIED, TO BE COMPLIED WITH WITHIN 10HRS/14DAYS. COMPLETED 7 SEP 95 AT 4628.5 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO.80913	07-Sep-1995	1	QC000000
CH-47-96-ASAM-01, MAINTENANCE MANDATORY, ALL CH-47D, MH-47D, &MH-47E HELICOPTERS REPLACEMENT OFAFT LANDING GEAR DRAG LINK ASSEMBLIES THAT ARE SUSCEPTIBLE TO STRESS CORROSION CRACKS COMPLIED WITH AT 4658.1 ACFT HRS. (NO PID)	A CO 2/158TH AVN REGT, FT. CARSON, CO.80913	15-Nov-1995	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CYCLE 4,PHASE #3 WAS COMPLETED 18APR96 AT 4704.7 ACFT HRS. THE NEXT PHASE,CYCLE 4,PHASE #4 DUE AT 4904.7 ACFT HRS. (GM0000)	A CO 2/158 AVN REGT, FT CARSON CO. 80913	18-Apr-1996	1	QC000000	
OCM/ACE PERFORMED AT 4712 A/C HRS AT FT. CARSON,CO (NO PID)	PROJECT OLR, FT. HOOD,TX.	10-Jun-1996	1	QC000000	
CH-47-96-ASAM-03ONETIME VISUAL INSP OF ACCUMULATORPRESSURE GUAGES FOR TAPE COMPLETED AT 4704.7 ACFT HRS.6FEB96(LATE ENTRY) (NO PID)	A CO 2/158 AVN REGT, FT CARSON,CO. 80913	17-Jun-1996	1	QC000000	
CH-47-96-ASAM-04,ONETIME INSP OF FWD & AFT ROTOR HEADS TO ENSURE OIL FLOW TO HHP*S(TB1-1520-240-20-83)DATED 6JUN96 COMPLIED WITH 4714.5 ACFT HRS. (GH0000)	A CO 2/159 AVN, FT BRAGG N.C.28304	20-Jun-1996	1	QC000000	
#2 EMERGENCY PWR METER TRIPPED AT 4714.8 ACFT HRS.25JUN96 INDICATES 30 SECONDS. (GH0000)	A CO 2/159 AVN, FT BRAGG N.C.	25-Jun-1996	1	QC000000	
CH-47-96-ASAM-05 ONETIME INSP OF FWD CONTROL INSTALLATION FOR THE MANUFACTURE OF P/N 114R3650 BOLT ASSY COMPLIED WITH AT 4714.5 ACFT HRS (GH0000)	A CO 2/159 AVN, FT BRAGG N.C.28304	25-Jun-1996	2	QC000000	
CH-47-96-ASAM-07,TO INSPECT THE BOND LINES ON THE 11P8079-2AND-3 STRAP ASSY FOR LOOSENESS AROUND THEEDGES (TB1-1520-240-20-86) COMPLIED WITH 4727.3 ACFT HRS. (NO PID)	I CO 4/159 AVN, FT BRAGG N.C.	10-Jul-1996	1	QC000000	
CH-47-96-ASAM-06,ONETIME VISUAL INSP AND RECORDS CHECK OF UPPER BOOST ACTUATORS AND PULL TEST OF SWASHPLATES TO BE COMPLIED WITH N/L/T 12JUL96 OR 4737.3 ACFT HRS. COMPLIED WITH AT 4727.3 ACFT HRS. (NO PID)	I CO 159 AVN, FT BRAGG N.C.	22-Jul-1996	1	QC000000	
CH-47-96-ASAM-08,ONETIME INSP FOR AND REMOVAL OF CERTAIN S/N 145DS102-3 FWD XSMN MAIN LUBE PUMPS COMPLIED WITH 4727.3 ACFT HRS. (NO PID)	I CO 4/159 AVN, FT BRAGG N.C.	22-Aug-1996	1	QC000000	
CH-47-96-ASAM-09,INSP AND REPAIR OF AFT PYLON CLAMSHELL DOOR LOWER LATCH WITHIN 100 FLT HRS. COMPLIED WITH AT 4727.3 ACFT HRS. (NO PID)	I CO 4/159 AVN, FT BRAGG N.C.	17-Sep-1996	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-97-ASAM-01, ONE TIME RECORDS CHECK AND VISUAL INSP FOR SUSPECT S/N FWD SYNC SHAFT ASSY COMPLIED WITH AT 4727.3 ACFT HRS. (NO PID)	I CO 4/159 AVN, FT BRAGG N.C.	15-Oct-1996	1	QC000000	
SOF CH-47-97-01 ONE TIME VISUAL INSP OF FWD XSMN BARRREL NUTS C/W THIS STATION AT 4777 ACFT HRS. (NO PID)	A CO 159 AVN, FT BRAGG N.C.	15-Nov-1996	1	QC000000	
CH-47-97-ASAM-02, INSP OF CARGO GRIP HOOK RELEASE GUARD C/W THIS STATION AT 4805.8 ACFT HRS. (NO PID)	A CO 159 AVN, FT BRAGG N.C.	07-Jan-1997	1	QC000000	
GEN-97-ASAM-03, INSPECT ACFT FOR AN/ASN-149 GPS INSTALLATION C/W THIS STATION 5814.6 ACFT HRS. (NO PID)	A CO 159 AVN, FT BRAGG N.C.	29-Jan-1997	1	QC000000	
CH-47-97-ASAM-03, ONETIME/RECURRING INSP OF ALL RAMP/CABIN 5000 LB. TIEDOWN FITTINGS C/W AT 4823.9 ACFT HRS. (NO PID)	A CO 159 AVN, FT BRAGG N.C.	05-Feb-1997	1	QC000000	
CH-47-97-ASAM-05, (TB1-1520-240-20-93) ONE TIME INSP FOR AND REPLACEMENT OF AN320-12 CASTELLATED NUTS MADE BY GREER STOP NUT INC. COMPLIED WITH THIS STATION AT 4860.8 ACFT HRS. (NO PID)	A CO 159 AVN, FT BRAGG NC.	13-Mar-1997	1	QC000000	
CH-47-ASAM-04, ONETIME VISUAL INSP AND REPLACEMENT OF CERTAIN P/N463074 CRISSAIR INC. CHECKVALVES INSTALLED IN POWER CONTROL MODULES COMPLIED WITH AT 4868.9 ACFT HRS. (NO PID)	A CO 159 AVN, FT BRAGG N.C.	18-Mar-1997	1	QC000000	
CH-47-97-ASAM-06 INFORMATIONAL UPDATE AND POSSIBLE SOLUTION FOR NAVSTAR AN/ANS 149 (VI) GPS DISPLAY UNIT LOCKUP COMPLIED WITH 4873.0 ACFT HRS. (AM6772)	A CO 159TH AVN REGT, FT. BRAGG, NC	09-Apr-1997	1	QC000000	
CH-47-97-ASAM-08 INSP AND LUBE OF FLIGHT CONTROL CLOSET ROD ENDS COMPLIED WITH (EF0861)	C-159TH AVN REGT, FT BRAGG NC 28307	23-Apr-1997	1	QC000000	
CH-47-97-ASAM-07 ALL CH-47D, MH-47D&E ACFT ONE TIME AND RECURRING INSP OF PDP FEEDER WIRING FOR FRAYING/CHAFFING AND ARCING/BURNING CORRODED CIRCUIT BREAKERS FOR WATER INTRUSION/INSTALLATION OF CIRCUIT BREAKERS COVERS C/W 4879.4 ACFT HRS. (AM6772)	A CO 159TH AVN REGT, FT. BRAGG, NC	24-Apr-1997	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-97-ASAM-09 REVIEW ACFT DA FORM 2408-16*S TO IDENTIFY TSN AND TSO OF APU C/W 4903.7 ACFT HRS. (AM6772)	A CO 159TH AVN REGT, FT. BRAGG, NC	06-Jun-1997	1	QC000000	
PHASE 4 COMPLETED AT 4903.7 ACFT HRS, NEXT PHASE IS PHASE 1 DUE AT 5103.7 ACFT HRS (DR8176)	A 159TH AVN REGT (LM2), FT BRAGG, NC 28307	15-Aug-1997	1	QC000000	
CH-47-97-ASAM-10 ONE TIME INSPECTION OF ALL AN/AVS-7 SYSTEMS TO VERIFY INSTALLATION OF THE CORRECT POWER SUPPLY COMPONENT. TB 1-1520-240-20-99 (DK7781)	A CO.159TH AVN, FT. BRAGG, N.C 28307	30-Sep-1997	1	QC000000	
CH-47-98-ASAM-01 RECORDS REVIEW OF 6 MONTH AND CURRENT ACFT RECORDS FOR UNCOMMANDED CONTROL INPUTS. COMPLIED WITH AT 4973.2 ACFT HRS. (NO PID)	C CO. 159TH AVN, FT. BRAGG, NC. 38307-5000	05-Nov-1997	1	QC000000	
CH-47-98-ASAM-02 (TB 1-1520-240-20-100) EXTENSION FOR REPLACEMENT OF THE AFT LANDING GEAR DRAG LINK ASSEMBLIES THAT ARE SUSCEPTIBLE TO STRESS CORROSION CRACKING. COMPLIED WITH AT 4971.9 ACFT HOURS. (SJ5775)	C CO 159TH AVN, FT BRAGG, NC 28307-5000	17-Nov-1997	1	QC000000	
SOF CH-47-98-01 TB-1520-240-20-103, SOF ONE TIME INSP OF AFT UPPER BOOST ACTUATOR TO STATIONARY SWASHPLATE RET. HARDWARE COMPLIED WITH AT 5005.7 ACFT HRS (QC0014)	C-159TH AVN REGT, FT. BRAGG NC. 28307	19-Mar-1998	1	QC000000	
CH-47-98-ASAM-03 (TB 1-2835-205-20-03) ALL CH-47D MH-47D, MH-47E ACFT. MANDATORY TORQUE CK. AND REPLACEMENT OF AUX PWR UNIT BOLTS C/W AT 5024.3 A/C HRS. (EF0861)	C/159TH AVN REGT, FT. BRAGG NC. 28307-5000	29-Apr-1998	1	QC000000	
CH-47-ASAM-04(TB1-1520-240-20-120) ONE TIME INSP FOR AFT XMSN WITH SUSPECTED IMPROPERLY SHIMMED INPUT PINNION GEAR ASSY C/W AT 5032.1 A/C HOURS (EF0861)	C CO 159TH AVN REGT, FT BRAGG NC. 28307	14-May-1998	1	QC000000	
SOF MSG CH-47-98-02 (TB 1-1520-240-20-102) ALL H-47 SERIES ACFT, FLT RESTRICTIONS FOR ACFT WITH MWO 1-1520-240-50-67 NON METALLIC SPLINE ADAPTERS FOR COMBING XNSM COOLING FAN DRIVE SHAFT APPLIED C/W AT 5072.6 ACFT HRS (EF0861)	C COMPANY 159TH AVN REGT, FT BRAGG NORTH CAROLINA 28307	16-Jul-1998	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
PHASE #1 INSPECTION COMPLETED AND CORROSION X APPLIED TO UNDERFLOOR AREAS AT 5072.6 HRS NEXT PHASE INSPECTION DUE IS PHASE #2 DUE AT 5272.6 HRS (EF0861)	LMLM, FT BRAGG NORTH CAROLINA 28307	10-Sep-1998	1	QC000000
CH-47-98-ASAM-05(TB1-1520-240-20-101)AIR CRAFT RESTRICTED TO FLIGHT OPERATIONS AND INSPECTION PROCEDURES I/A/W ASAM C/W AT 5073.2 ACFT HRS. (ST8609)	C COMPANY 159TH AVN REGT, FT. BRAGG,NC 28307	17-Sep-1998	1	QC000000
CH-47-99-ASAM-01(TB1-1520-240-20-106) ONE TIME INSP OF LAG DAMPNERS C/W AT 5228.0 ACFT HRS. (QC0001)	C-159TH AVN REGT, FT BRAGG, NC	16-Feb-1999	1	QC000000
CH-47-99-ASAM-02(TB 1-1520-240-20-107) ALL H-47 HELICOPTERS, ACTIONS TO REDUCE SUSCEPTIBILITY TO FLIGHT CONTROL LOCK-UP AND/OR UNCOMMANDED MANEUVERS C/W AT 5228.0 ACFT HRS. S.TESSEIN SSG (ST8609)	C CO 159TH AVN REGT, FT. BRAGG, NC 28307	18-Feb-1999	1	QC000000
CH-47-99-ASAM-03 (TB 55-1520-240-20-108) ONETIME & RECURRING INSP OF HOIST/ CARGO HOOK CONTROL PANEL AND WATER INTRUSION IN THE COCKPIT. (IS4307)	C CO 159TH AVN, FT. BRAGG, NC	12-Mar-1999	1	QC000000
CH-47-99-ASAM-04 (TB 1-1520-240-20-109) MAINT MANDATORY INSP FWD & AFT YOKE BUSHINGS INSP & ACFTMAINT MANUAL CHANGES. (AM6772)	C CO 159TH AVN, FT. BRAGG, NC	17-Mar-1999	1	QC000000
CH-47-99-ASAM-05 TB1-1520-240-20-110 EXTENTION FORREPLACEMENT OF AFT LANDING GEAR DRAG LINK ASSY SUSCEPTIBLE TO STRESS CORROSION CRACKING (AM6772)	C CO 159TH AVN, FT BRAGG, NC	04-May-1999	1	QC000000
MEMO HQ FORSCOM DATED 7 APR 99 WAVIER OF ASAM CH-47-99-ASAM-02 (TB1-1520-240-20-107) HYD FILTER REPLACEMENT WAVIER EXPIRES 31 OCT 99 (EJ5910)	C 159TH AVN, FT BRAGG NC	25-Jun-1999	1	QC000000
SOF CH-47-99-01 (TB 1-1520-240-20-111)ONE TIME INSP OF SYNC SHAFT MOUNTING BRACKETS CLEARANCE C/W @ 5257.8 ACFT HRS. (BR9486)	C CO 159TH AVN REGT, FT BRAGG, NC 28307	08-Jul-1999	1	QC000000
SOF CH-47-99-02 IMMEDIATE GROUNDING OF ALL CH-47 ACFT CRACKED 1ST AND 2ND STAGE PLANETARY GEARS IN FWD & AFT XMSNS, C/W 5261.8 ACFT HRS.RS. (BR9486)	C CO 159TH AVN REGT, FT BRAGG, NC 28307-5000	10-Aug-1999	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
SOF CH-47-99-02 ACFT GROUNDED IMMEDIATELY PER SOFCH-47-99-02 SUSPECTED CRACK PLANETARY GEAR FWD AND AFT XMSN (SV0869)	C CO 159TH AVN, FT. BRAGG, NC	24-Aug-1999	1	QC000000	
SOF CH-47-99-03 (TB 55-1520-240-20-113) INSPECTION OF CH-47 ACFT FWD AND AFT XMSN GEAR/BEARING ASSY NOT COMPLIED WITH (SV0869)	C CO 159TH AVN, FT. BRAGG, NC	24-Aug-1999	2	QC000000	
SOF CH-47-99-04 (TB 1-1520-240-20-114) FOR FWD & AFT XMSN GEAR/BEARING ASSY IDENTIFIED BY S/N: PREFIX "VB" TO BE SERVICEABLE AT 5261.8 ACFT HRS. (BR9486)	C CO 159TH AVN REGT, FT BRAGG, NC 28307	26-Aug-1999	1	QC000000	
PHASE #2 INSP COMPLETED AT 5261.8 ACFT HRS PHASE #3 INSP DUE AT 5461.8 ACFT HRS CORROSION "X" APPLIED TO UNDER FLOOR BILGE AREA AT 5261.8 ACFT HRS. (BR9486)	LM2, FT BRAGG, NC 28307-5000	30-Aug-1999	1	QC000000	
SOF CH-47-99-05 (TB 1-1520-240-20-115) REPLACEMENT OF SUSPECT FWD & AFT XMSN ASSEMBLIES WITH ONES THAT HAVE BEEN INSP AND CLEARED FOR OPERATION. C/W AT 5268.5 ACFT HRS. (BR9486)	C CO 159TH AVN REGT, FT BRAGG, NC 28310	13-Sep-1999	1	QC000000	
SOF CH-47-00-01 (TB 1-2835-205-20-4) OPERATIONAL RESTRICTIONS AND REVISION TO HISTORICAL RECORDS FOR T-62T-2B APU C/W 5285.9 ACFT HRS FOR APU S/N: 877553. (BR9486)	C CO 159TH AVN REGT, FT BRAGG, NC 28310	12-Oct-1999	1	QC000000	
ACE PERFORMED BY TEAM MEMBER JJ AT 5295 ACFT HRS IN FT BRAGG, NC. AMCOM/OLR/MWO BRANCH, HUNTSVILLE, AL. (RK0881)	LMLM/OLR, HAAF SAV, GA	02-Nov-1999	1	QC000000	
SOF CH47-00-02 REVISION TO SOF CH47-00-01 OPERATIONAL RESTRICTIONS AND REVISION TO HISTORICAL RECORDS T-62T-2B APU C/W 5305.3 ACFT HRS (EJ5910)	C 159TH AVN, FT BRAGG NC 28310	15-Nov-1999	1	QC000000	
SOF CH-47-00-03 (TB 1-1520-240-20-116) INCREASE OF OPERATING LIMITATIONS FOR FWD AND AFT XMSN GEAR BEARING ASSY IDENTIFIED BY SN# PREFIX "VB" (BC3959)	CH-47-00-ASAM-01, FT BRAGG, NC	07-Dec-1999	1	QC000000	
CEP ISSUED AND OPERATED IAW AWR DTD 14 JUL 99 (AM6772)	C.CO. 159TH AVN, FT BRAGG, NC 28310	15-Jan-2000	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF CH-47-00-03 (TB1-1520-240-20-117) ONE TIME INSPECTION OF ENGINE XMSN RECORDS FOR SUSPECT GEARS AND REPLACEMENT OF SUSPECT XMSNS (BC3959)	CH-47-00-ASAM-01, FT BRAGG,NC	28-Jan-2000	1	QC000000
CH-47-00-ASAM-01 (TB1-1520-240-20-119) INITIAL ANDRECURRING INSPECTION OF FULE PODS FOR CORROSION AND ELECTRICAL BONDING (BC3959)	CH-47-00-ASAM-01, FT BRAGG,NC	28-Apr-2000	1	QC000000
SOF CH-47-00-05 (TB 1-1520-240-20-120) ONE TIME INSPECTION OF PITCH HOUSINGS (BR9486)	C CO 159TH AVN REGT, FT BRAGG, NC 28310	01-May-2000	1	QC000000
CH-47-00-ASAM-02 (TB1-1520-240-20-118) INITIAL ANDRECURRING INSPECTION AND REPLACEMENT OF HORIZONTALHINGE PIN SHOULDER BOLTS (BC3959)	CH-47-00-ASAM-01, FT BRAGG,NC	12-May-2000	1	QC000000
CH-47-00-ASAM-03 (TB 1-1520-240-20-121) HYDRAULIC FLUID SAMPLING FROM FLIGHT CONTROL AND UTILITY SYSTEMS (DG9497)	C CO. 159TH AVN REGT, FT. BRAGG, NC 28310	05-Jun-2000	1	QC000000
CH-47-00-ASAM-04(TB 1-1520-240-122) HORIZONTAL HINGE PIN INSPECTION (DG9497)	C CO. 159TH AVN, FT. BRAGG, NC 28310	28-Jul-2000	1	QC000000
CH-47-00-ASAM-05 (TB 1-1520-240-20-123) INSPECTIONOF FWD & AFT SLIDER SHAFT SEALS (DG9497)	C 159TH AVN, FT. BRAGG, NC	28-Jul-2000	2	QC000000
PHASE #3 COMPLETED AT 5457.0 ACFT HRS. PHASE #4 DUE AT 5657.0 ACFT HRS. CORROSION "X" APPLIED TO UNDER FLOOR BILGE AREA AT 5457.0 ACFT HRS. (TC9846)	LM2, FT. BRAGG, NC 28310	22-Aug-2000	1	QC000000
SOF CH-47-00-06 SPECIFIC APU P/N*S AND APU*S WITH ARMOR KITS ARE EXCLUDED FROM THE REQUIRED KIT INSTALLATION AND EXCLUDED FROM RESTRICTION IMPOSED BY SOF CH-47-00-01 (SV0869)	C-159TH AVN, FT. BRAGG, NC.	07-Sep-2000	1	QC000000
CH 47-00-ASAM-06 INSPECT FOR DEFECTIVE FADEC P3 DRAIN CARTRIDGE PRIOR TO NEXT FLT BUT NLT 05 OCT 2000 (BC3959)	C/159TH AVN, FT BRAGG, NC	21-Sep-2000	1	QC000000
CH-47-00-ASAM-07(TB1-1520-240-20-125)INS PECT FOR UNTESTED P/N 114R3650-7 BOLTS ON H-47 AIRCRAFT C/W27SEP00 JC6066 TI (JC6066)	C CO 159TH AVN, FT BRAGG NC	26-Sep-2000	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF CH-47-00-07(TB1-1520-240-20-129)INSPECT COMBINING TRANSMISSION COOLING FAN DRIVE SHAFT C/W 27SEP00 JC6066 TI (JC6066)	C CO 159TH AVN, FT BRAGG NC	27-Sep-2000	1	QC000000
CH-47-00-ASAM-08 (TB 1-1520-240-128) INSPECT FORWARD YOKE SHAFT FOR CORROSION AND CHIPPED PAINT (SV0869)	C CO 159TH AVN, FT. BRAGG, NC.	28-Sep-2000	1	QC000000
CH-47-01-ASAM-01(TB 1-1520-240-20-127) INSPECT FORINSTALLATION OF MA-16 INERTIA REELS, P/N 015-870145-3-16. C/W (DG9497)	C/159TH AVN, FT. BRAGG, NC	12-Oct-2000	1	QC000000
CH-47-01-ASAM-02 (TB 1-1520-240-20-130) INSPECT FOR UNTEST FSP BOLTS P/N 114R3650-11 AND 114R3650-6 (SV0869)	C CO 159TH AVN, FT. BRAGG, NC.	24-Oct-2000	1	QC000000
ACE COMPLETED AT 5533 ACFT HRS. BY ACE MEMBER L AMCOM OLR/MWO BRANCH (EH9090)	LM2, FT. BRAGG, NC. 28310	30-Oct-2000	1	QC000000
CH-47-01-ASAM-03(TB1-1520-240-131)INSPE CT FWD AND AFT ROTOR HUB LIGHTENING HOLES (JC6066)	C CO 159TH AVN, FT BRAGG NC	09-Nov-2000	1	QC000000
CH-47-01-ASAM-04 (TB 1-1520-240-20-133) INSPECT FOR UNTESTED FSP P/N114R2168-3 AND 114R2168-4 TIE BAR PIN ASSY. (SV0869)	C CO 159TH AVN, FT. BRAGG, NC. 28310	14-Dec-2000	1	QC000000
CH-47-01-ASAM-05 (TB 1-1520-240-20-132) INSPECT DROOP STOP BOLTS. (SV0869)	C CO 159TH AVN, FT. BRAGG, NC. 28310	14-Dec-2000	2	QC000000
SOF CH-47-01-01 (TB 1-1520-240-20-134) INSPECT AFT ROTOR HEAD ASSY AND ENGINE CROSS SHAFT ADAPTER ASSY FOR MH-47E CLOSED LOOP ESCAPEMENTS (SV0869)	C CO 159TH AVN, FT. BRAGG, NC. 28310	27-Dec-2000	1	QC000000
CH-47-01-ASAM-06 (TB 1-1520-240-20-132) ADDITIONALINFORMATION FOR CH-47-01-ASAM-04 (SV0869)	C CO 159TH AVN, FT. BRAGG, NC. 28310	27-Dec-2000	2	QC000000
SOF CH-47-01-02 INSPECTION OF DROOP STOPS (SV0869)	C CO 159TH AVN, FT. BRAGG, NC. 28310	05-Feb-2001	1	QC000000
CH-47-01-ASAM-07 INSPECTION FOR UNTEST PN 114R3650-13 AND 114R3650-15 BOLTS (BC3959)	C CO 159TH AVN, FT. BRAGG, NC. 28310	13-Feb-2001	1	QC000000
SOF CH-47-01-03 (TB1-1520-240-20-137) INSPECT DROOP STOPS (BC3959)	C CO 159TH AVN, FT. BRAGG, NC. 28310	20-Feb-2001	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-01-ASAM-08 (TB1-1520-240-20-138) INSP POWER,PRESSURE AND RETURN CONTROL MODULE ASSEMBLIES TO ENSURE SHUT-OFF DIAPHRAM HARDWARE IS INSTALLED (TC9846)	LM2, FT. BRAGG, NC. 28310	10-Aug-2001	1	QC000000	
CH-47-01-ASAM-09 (TB 1-1520-240-20-139) INSP FOR UNTESTED FSP 114R3650-9 (DRIVE ARM UPPER ATTACH BOLT) AND BACB30ST10-40 (AFT FIXED LINK LOWER ATTACH BOLTS) C/W AT 5653.0 ACFT HRS BY T CHERRY, LM2 TI (TC9846)	LM2, C CO. 159TH AVN, FT BRAGG, NC 28310	06-Sep-2001	1	QC000000	
CH-47-02-ASAM-01(TB 1-1520-240-20-142) INSPECT STRUT ASSEMBLIES WITHIN THE NEXT 10 FLIGHT HOURS BUT NLT 18 OCTOBER 2001 C/W AT 5653 ACFT HRS (JC6066)	C CO 159TH, FT BRAGG NC	11-Oct-2001	1	QC000000	
ACFT DISASSEMBLED FOR AIR TRANSPORT TRAINING (C5 TEARDOWN) AT 5653.0 ACFT HRS. (TC9846)	LM2 C/159 AVN, FT BRAGG, NC 28310	17-Nov-2001	1	QC000000	
CORROSION "X" CPC COMPOUND APPLIED TO UNDERFLOOR AREAS DURING PHASE INSPECTION AT 5653.0 ACFT HRS. (TC9846)	LM2 C/159 AVN, FT BRAGG, NC 28310	17-Nov-2001	2	QC000000	
PHASE #4 COMPLETED AT 5653.0 ACFT HRS. PHASE #1 DUE AT 5853.0 ACFT HRS. (TC9846)	LM2 C/159 AVN, FT BRAGG, NC 28310	17-Nov-2001	3	QC000000	
CH-47-02-ASAM-02 (TB 1-1520-240-143) INSPECT THE FWD YOKE SHAFT WITHIN THE NEXT 10 FLT HRS BUT NLT 31 DEC 2001 C/W @ 5661.7 ACFT HRS. (JI0357)	C CO, 159 AVN REGT, FT. BRAGG, NC 28310-5000	02-Jan-2002	1	QC000000	
SOF CH-47-02-01 (TB 1-1520-240-20-144) INSPECT SWASHPLATE LOWER SEAL RETAINER SELF LOCKING NUTS C/W @ 5677.6 ACFT HRS. (JC6066)	C CO 159TH AVN REGT, FT BRAGG, NC 28310	25-Jan-2002	1	QC000000	
CH-47-02-02 (TB 1-1520-240-20-141) ALL H-47 SERIESAIRCRAFT INSPECTION OF THE ROTARY WING HEAD TIE BAR ASSEMBLY AND ROTOR TACHOMETER. C/W @ 5677.6 ACFTHRS. (JC6066)	C CO 159TH AVN REGT, FT BRAGG, NC 28310	25-Jan-2002	2	QC000000	
CH-47-02-03 (TB 1-1520-240-20-141) ALL H-47 SERIESAIRCRAFT, REVISION TO CH-47-02-02 INSPECTION OF THE ROTARY WING HEAD TIE BAR ASSY AND ROTOR TACHOMETER. C/W @ 5677.6 ACFT HRS. (JI0357)	C CO 159TH AVN REGT, FT BRAGG, NC 28310	30-Jan-2002	1	QC000000	
ACE COMPLETED @ 5695.5 ACFT HRS BY ACE MEMBER "L" AMCOM OLR/MWO BRANCH. (EH9090)	LMLM, FT BRAGG, NC 28310	07-Feb-2002	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF CH-47-02-04 (TB 1-1520-240-20-145) INSPECTION OF THE FWD PIVOTING ACTUATOR UPPER ATTACHMENT BEARING. C/W @ 5699.2 ACFT HRS (BR9486)	C CO 159TH AVN REGT, FT BRAGG, NC 28310	08-Feb-2002	1	QC000000
CH-47-02-ASAM-03(TB1-1520-240-20-147) INSPECTION OF FUEL CONTROL RELAY BOX WITHIN THE NEXT 10 FLT HRS BUT NLT 26 JUNE 02 C/W @5791.4 ACFT HRS. (JC6066)	C CO 159TH AVN REGT, FT BRAGG NC 28310	13-Jun-2002	1	QC000000
SOF CH-47-02-06 (TB 1-1520-240-20-148) INSPECTION OF THE COMBINING TRANSMISSION PRIOR TO THE NEXT ENGINE START BUT NLT 25 JUN 02 C/W @ 5792.8 ACFT HRS. (JI0357)	C CO, 159TH AVN REGT, FT. BRAGG, NC 28310	19-Jun-2002	1	QC000000
CH-47-02-ASAM-04 (TB 1-1520-240-20-149) INSPECTIONFOR UNTESTED CSI P/N 114C3044-2 AFT YOKE SUPPORT SHAFT C/W @ 5816.4 ACFT HRS. (JI0357)	C CO, 159TH AVN REGT, FORT BRAGG, NC 28310-5000	29-Jul-2002	1	QC000000
SOF CH-47-03-01, INSP FWD AND AFT SWASHPLATE BEARING AND SEAL FOR CONDITION C/W @ 5850.7 A/CHRS (KM1702)	C CO 159TH AVN, FORT BRAGG, NC	07-Oct-2002	1	QC000000
CORROSION "X" CPC COMPOUND APPLIED TO UNDERFLOOR AREAS DURING PHASE INSPECTION AT 5850.7 ACFT HRS. (TC9846)	LM2 C/159 AVN, FT BRAGG, NC 28310	04-Nov-2002	1	QC000000
PHASE #1 COMPLETED AT 5850.7. PHASE #2 DUE AT 6050.7 ACFT HRS. (TC9846)	LM2 C/159 AVN, FT BRAGG, NC 28310	04-Nov-2002	2	QC000000
COMPLY WITH REQUIREMENTS OF GEN-03-ASAM-01 BEFORE 5911.2 ACFT HRS BUT NLT 31 DEC 2002 C/W @ 5901.2 ACFT HRS (JC6066)	C CO 159TH AVN, FT BRAGG NC 28310	17-Dec-2002	1	QC000000
ACE COMPLETED AT 5984 ACFT HRS BY ACE MEMBER G AMCOM OLR/MWO BRANCH (JK5734)	C. CO. 159TH AVN REGT, FT. BRAGG, NC. 28310	09-Feb-2003	1	QC000000
CH-47-04-ASAM-01 AFT FUSELAGE BELLCRANK FASTENER FOR CORRECT INSTALLATION WITHIN 10 FLT HRS. NLT 17 FEB 04 C/W @ 6050.1 ACFT HRS. (JK5734)	C. CO. 159TH AVN REGT, FT. BRAGG, NC. 28310	09-Feb-2003	2	QC000000
CH-47-03-ASAM-01 ENGINE DRIVE SHAFT RETIREMENT LIFE INCREASED TO 6000 HRS. COMPLY NO LATER THAN 25 APR 03. C/W @ 5934.5 ACFT HRS. (WT3879)	C. CO 159TH AVN, FT. BRAGG, NC. 28310	27-Mar-2003	1	QC000000
ECL CRL QDNT PN:MCH15-6, SN:218F FOUND ACCEPTABLE PER ASAM Z PRELIM CHK. CTL QDNT WAS MARKED IAW ASAM (SA9972)	OLR/LMLM, FT. BRAGG, NC. 28310	22-Apr-2003	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
ACE COMPLETED AT 5984 ACFT HRS BY ACE MEMBER G AMCOM OLR/MWO BRANCH (EH9090)	LMLM, FT. BRAGG, NC. 28310	07-Aug-2003	1	QC000000	
ENGINE MOUNT NDI (EDDY CURRENT) INSPECTION COMPLETED AT 6050.0 ACFT HRS. BY T CHERRY, LM2 TI,FBG NC, 28310 (TC9846)	LM2, C/159 AVN, FT BRAGG, NC 28310	09-Feb-2004	1	QC000000	
CH-47-04-ASAM-01 AFT FUSELAGE BELLCRANK FASTNER FOR CORRECT INSTALLATION WITHING 10 FLT HRS NLT 17 FEB 04 C/W @ 6050.1 ACFT HRS (JK5734)	C. CO. 159TH AVN REGT, FT BRAGG, NC 28310	09-Feb-2004	2	QC000000	
CH-47-04-ASAM-02 TRANSIENT AND AVOID BANDS ON THE CGI COMPLIED WITH 6052.5 ACFT HRS. (AM6772)	C. CO. 159TH AVN REGT, FT BRAGG, NC 28310	07-May-2004	1	QC000000	
PHASE 1-4 COMPLETED IAW AWR DTD 28 AUG 03 AT 6050.0 ACFT HRS. 200 HR CSM DUE AT 6250.0 ACFT HRS 400 HR CSM DUE AT 6450.0 HRS. (AM6772)	C. CO. 159TH AVN REGT, FT BRAGG, NC 28310	24-May-2004	1	QC000000	
ACFT ENTERED INTO ALT MAINTENANCE CHECKLIST AWR DATED 27 AUG 04 (AM6772)	C.CO. 159TH AVN, FT BRAGG, NC 28310	27-Aug-2004	1	QC000000	
CH-47-05-ASAM-01 MANDATORY PARTS REPLACEMENT OF AFT CRITICAL DYNAMIC COMPONENTS, COMPLIED WITH AT 6190.7 AIRCRAFT HOURS 18 OCT 04. (JH7517)	C CO 159TH AVN, FT. BRAGG, NC 28310	18-Oct-2004	1	QC000000	
ACE COMPLETED AT 6191 ACFT HRS BY ACE TEAM MEMBER "L" AMCOM OLR/MWO BRANCH (EH9090)	DS2, FT BRAGG, NC 28310	03-Nov-2004	1	QC000000	
BLUE FORCE TRACKER ENHANCED INSTALLED AND OPERATED IAW AWR DATED 24 JUL 04. (AM6772)	C.CO. 159TH AVN, FT BRAGG, NC 28310	20-Nov-2004	1	QC000000	
EXTENDED LENGTH FLARE DISPENCER CABLE INSTALLED & OPERATED IAW AWR DATED 26 NOV 04. (AM6772)	C.CO. 159TH AVN, FT BRAGG, NC 28310	20-Nov-2004	2	QC000000	
CH-47-05-SOF-01 SWASHPLATE ROTATING RING COMPLIED WITH 6202.0 ACFT HRS (AM6772)	C CO 159TH AVN REGT, BALAD, IRAQ	25-Jan-2005	1	QC000000	
ACFT ENTERD INTO OPERATION IRAQI FREEDOM 6206.3 ACFT HRS. (AM6772)	C CO 159TH AVN REGT, BALAD AIRFIELD IRAQ	15-Feb-2005	1	QC000000	
200HR CYCLE SERVICE MAINTENANCE COMPLETED AT 6246 ACFT HRS NEXT 400HR CSM DUE AT 6646 ACFT HRS. (DH0154)	I CO 4-159TH AVN REGT, BALAD AIRFIELD IRAQ	26-Mar-2005	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ACFT CONFIGURED AND OPERATED IAW AWR DTD 01NOV04 IR ANTI-COLLISION STROBE LIGHT (AM6772)	C CO 159TH AVN REGT, BALAD AIRFIELD IRAQ	28-Mar-2005	1	QC000000
CRACK @ STATION 482 UNDER TRANSFER BELL CRANK. REPAIRED AS PER AMCOM LETTER MEC NO: LE-BA008-1040POC: MARTIN ROSE (DH0154)	ICO 4-149TH AVN REGT, BALAD AIRFIELD IRAQ	15-May-2005	1	QC000000
CH-47-05-ASAM-03 INSP FOR SUSPECTED VHP BEARINGS C/W AT 6400.5 A/C HOURS (AF7216)	C CO 159TH AVN REGT, BALAD AIRFIELD IRAQ	23-Jul-2005	1	QC000000
CH-47-05-ASAM-02 ALL CH-47 SERIES AIRCRAFT AFT HEAD SERIAL NUMBER CHECK C/W AT 6400.5 A/C HRS (AF7216)	C CO 159TH AVN REGT, BALAD AIRFIELD IRAQ	23-Jul-2005	2	QC000000
CH-47-05-SOF-02 ONE TIME INSP OF ROTOR BLADE ROOT END FIBER DISTORTION COMPLIED WITH @ 6400.5 ACFT HRS (DS3992)	C CO 159TH AVN REGT, BALAD AIRFIELD IRAQ	25-Jul-2005	1	QC000000
400 HR CYCLE SERVICE MAINTENANCE COMPLETED @ 6400 ACFT HRS. NEXT PHASE DUE @ 6600 ACFT HRS. (DH0154)	I CO. 4/159TH AVIM, BALAD AAF 09391	13-Aug-2005	1	QC000000
CH-47-05-ASAM-06 HYD FLUID SYS MAINT PROCEDURE CHANGES COMPLIED WITH @ 6487.2 ACFT HRS 400.5 ACFT HRS (DS3992)	C CO 159TH AVN REGT, BALAD AIRFIELD IRAQ	17-Sep-2005	1	QC000000
MWO-1-1520-240-50-BFT 47-002 (DEC 06) AWR BFT GENERATION 3 SYSTEM. 7 FEB 06 (TTS26600) R D (ER6229)	DCO 3/82 GSAB, FT BRAGG NC 28311	10-Jan-2006	1	QC000000
ASAM CH-47-06-01 INSPECTION OF UPPER BOOST ACTTUATORS END CAPS COMPLIED WITH AT 6527.0 ACFT HRS M (ER6229)	DCO 3/82 GSAB, FT BRAGG GSAB	10-Jan-2006	2	QC000000
STA 482 L/S BULK HEAD SKIN AND CAP CRACKED AUTH REPLACEMENT I/A/W MEC# DTA 15 FEB 06 F46336 (ER6229)	DCO 3/82 GSAB, FT BRAGG GSAB	14-Jan-2006	1	QC000000
SOF CH-47-06-01 COMPLIED AS PER PARA 7.1.2 OF SOF @ 6527 HRS MICHAEL MOORE (GUN NOT INSTALLED) (ER6229)	DCO 3/82 GSAB, FT BRAGG NC 28311	19-Jan-2006	1	QC000000
OCM/ACE PERFORMED AT 6527.0 ACFT HRS. BY TEAM MEMBERS UU+J (ER6229)	DCO 3/82 GSAB, FT BRAGG NC 28311	23-Jan-2006	1	QC000000
CO-PILOTS PEDAL BOX PITCH SUPPORT BELLCRANK PITTEDREPLACED I/A/W MEC# DTA 15 FEB 06 F466337 (NA7064)	DYCORP, FTCKY	23-Jan-2006	2	QC000000
NDI OF #1 ENG FWD AND AFT ENG MOUNTS COMPLETED AT 6527.0 ACFT HRS, NEXT DUE AT 7127.0 ACFT HRS. (NA7064)	DYCORP, FTCKY	25-Jan-2006	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
NDI OF #2 ENG FWD AND AFT ENG MOUNTS COMPLETED AT 6527.0 ACFT HRS, NEXT DUE AT 7127.0 ACFT HRS. (NA7064)	DYCORP, FTCKY	25-Jan-2006	2	QC000000	
ASAM CH-47-05-05 REPLACEMENT OF ALL MODULES CHECK VALVES TO P/N 4C5202 AT ACFT HRS 6527.0 (NA7064)	DYCORP, FTCKY	03-Mar-2006	1	QC000000	
ASAM CH-47-06-02 INSP OF M240H MACHINE GUN MNT CAMFOLLWER C/W AT 6527.0 ACFT HRS (NOT INST) (NA7064)	DYCORP, FTCKY	03-Mar-2006	2	QC000000	
ASAM CH-47-06-03 COMPLIED AS PER PARA 4.1 OF SOF @ 6527 ACFT HRS (AFT BLADE DISTORTION) (NA7064)	DYCORP, FTCKY	08-Mar-2006	1	QC000000	
AFT SWIVELING ACT. SUPPORT MOUNT OUTB LUG REAM TO .628 AUTH REPAIRED I/A/W MEC# F47609 (NA7064)	DYCORP, FTCKY	14-Mar-2006	1	QC000000	
FWD XMSN TORQUE BOX AIRFRAME CRACKED ON L/H SIDE UNDER XMSN MNT AUTH REPAIRED I/A/W MECH# F47609 (NA7064)	DYNCORP, FTCKY	22-Mar-2006	1	QC000000	
AWR (TTS# 22052) FOR CH-47D MODIFICATION OF C-BOX UPPER CLAMSHELL C/W AT 6527 ACFT. (NA7064)	DYNCORP, FTCKY	26-Mar-2006	1	QC000000	
ASAM CH-47-06-03 INSP OF AFT LCT ACTIATOR S/N 118-824 AND YOKE C/W AT ACFT HRS 6527. (NA7064)	DYNCORP, FTCKY	11-May-2006	1	QC000000	
CRACK AT STATION 594 WL+10 BL 50 L AUTH REPAIR I/A/W MECH# F49726 (NA7064)	DYNCORP, FTCKY	22-May-2006	1	QC000000	
FWD RAMP BEAM AT STATION 10.777 AUTH REPAIRED I/A/W MEC# F49725 (NA7064)	DYNCORP, FTCKY	22-May-2006	2	QC000000	
FLUX VALVE RELOCATION C/W I/A/W AWR DATED 6 SEP 05.	D CO 3-10 GSAB, FT DRUM, NY 13602	24-May-2006	1	KC981398	
SOF CH-47-06-04 (SUSPECT AFT BLADES) COMPLIED AS PER PARA 7.1.2 OF SOF @ 6527 ACFT. (NA7064)	DYNCORP, FTCKY	26-May-2006	1	QC000000	
#1 ENG INBOARD MOUNT LUG BUSHIG OVERSIZED I/A/W TM 1-1520-240-23-3 TASK 4-33 (NA7064)	DYNCORP, FTCKY	30-May-2006	1	QC000000	
#2 ENG INBOARD MOUNT LUG BUSHIG OVERSIZED I/A/W TM 1-1520-240-23-3 TASK 4-33 (NA7064)	DYNCORP, FTCKY	30-May-2006	2	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
TB 1-1520-240-30-02-CH47D AIRCRAFT DESERT OPERATIIONS SPECIAL INSP. AND CLEANING COMPLETED AT 6527.0 ACFT HRS. (NA7064)	DYNCORP, FTCKY	12-Jun-2006	1	QC000000	
PHASE RESET 1-4 COMPLETED AT ACFT HRS 6527.0 NEXT PHASE #1 DUE AT 6927.0 ACFT HRS. (NA7064)	DYNCORP, FTCKY	12-Jun-2006	2	QC000000	
AWR DATED 17AUG06 (ADV HUD) SUPERSED AWR DATED 20MAY04	D CO 3-10 GSAB, FT DRUM NY	17-Aug-2006	1	QC111111	
CH-47-06-SOF-05 SERIES AIRCRAFT, SUSPECT FWD ROTORBLADES COMPLIED WITH AT 6595.5 ACFT. HRS. (ER6229)	DCO 3/82 GSAB, FT BRAGG NC 28311	23-Aug-2006	1	QC000000	
CH-47-06-SOF-06 RECORDS CHECK FOR CERTAIN PITCH HOUSING AND VERTICAL SHAFTS C/W AT 6624 ACFT HOURS (BC6643)	DCO 3/82 GSAB, FT BRAGG NC 28310	19-Sep-2006	1	QC000000	
CH-47-07-SOF-01 COMPLIED WITH AT 6661.3 ACFT HRS (ER6229)	DCO 3/82 GSAB, FT. BRAGG NC	24-Oct-2006	1	QC000000	
CH-47-07-01 COMPLIAD WITH @ 6661.3 ACFT HRS (EXTENDING NDI REQ ON SWASHPLATE ROTATING RING TO 200 HRS) (ER6229)	DCO 3/82 GSAB, FT. BRAGG NC 28310	26-Oct-2006	1	QC000000	
SATCOM INSTALLATION C/W I/A/W AWR DATED 8 SEP 06.	D CO 3-10 GSAB, FT DRUM, NY 13602	01-Nov-2006	1	KC981398	
AVIATION SAFETY ACTION MESSAGE (ASAM), MAINTENANCEMANDATORY, H-47 SERIES AIRCRAFT, ARC-220/KY-100 START-UP PROCEDURES, CH-47-07-ASAM-01 COMPLIED WITH AT: 6674.3 ACFT HRS (TC9846)	DS2 ALMB/DOL, FT BRAGG, NC 28310	17-Jan-2007	1	QC000000	
SAFETY OF FLIGHT, TECHNICAL ALL H-47 SERIES AIRCRAFT, SUSPECT ROTOR BLADES, CH-47-07-SOF-02 COMPLIED WITH AT 6674.3 ACFT HRS (TC9846)	DS2 ALMB/DOL, FT BRAGG, NC 28310	23-Jan-2007	1	QC000000	
AVIATION SAFETY ACTION MESSAGE (ASAM), MAINTENANCEMANDATORY, H-47 ACFT, INSP OF 145C3340-2 RIGID CONNECTING LINKS, CH-47-07-ASAM-02 COMPLIED WITH AT: 6675.3 ACFT HRS (TC9846)	DS2 ALMB/DOL, FT BRAGG, NC 28310	05-Mar-2007	1	QC000000	
ACE INSPECTION COMPLETED BY TEAM MEMBER "VV" AMCOM/OLR ACFT HRS:6709	DS-2, FT DRUM NY	08-Jun-2007	1	ED687157	
PMS2 COMPLETED @ 6716.7 A/C HRS	D CO 3/10 GSAB, FT DRUM, NY 13602	11-Jun-2007	1	JB178832	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
MCP INSTALLATION C/W I/A/W AWR DATED 12 DEC 02.	D CO 3-10 GSAB, FT DRUM, NY 13602	18-Jun-2007	1	KC981398	
BASIC A/C, WEIGHED AT: FT DRUM, NY 13602	B CO 277TH ASB, FT DRUM, NY 13602	12-Jul-2007	1	CC025738	
EMC TEST COMPLETED AFTER SUCESFULL INTALLATION OF MILES GEAR. COMPLETED AT 6035.3 ACFT HRS	D CO 3-10 GSAB, FT POLK, LA	08-Aug-2007	1	AC312272	
AWR DATED 15MAR05 (M240H MACHINE GUN AND TARGET POINTER ILLUMINATOR.	D CO 3-10 GSAB, FT DRUM NY 13602	19-Sep-2007	1	CH477819	
AWR 07FEB07 R-7 (BFT) SUPERSEDS BFT AWR DATED 28DEC06	D CO 3-10 GSAB, FT DRUM NY	19-Sep-2007	2	CH477819	
CMWS INSTALLATION C/W I/A/W AWR DATED 10 JUL 07.	D CO 3-10 GSAB, FT DRUM, NY 13602	22-Sep-2007	1	KC981398	
EDM INSTALLATION C/W I/A/W AWR DATED 17 JUN 05.	D CO 3-10 GSAB, FT DRUM, NY 13602	22-Sep-2007	2	KC981398	
CH-47-07-SOF-03 S/N CHECK FOR SUSPECT ROTOR BLADES C/W @6777.2 A/C HRS.	D CO 3-10 GSAB, FT DRUM, NY	01-Oct-2007	1	KC981398	
HUMS INSTALLATION C/W I/A/W AWR DATED 7 SEP 07.	D CO 3-10 GSAB, FT DRUM, NY 13602	02-Oct-2007	1	KC981398	
EPUSHA INSTALLATION C/W I/A/W AWR DATED 11 DEC 06.	D CO 3-10 GSAB, FT DRUM, NY 13602	02-Nov-2007	1	KC981398	
C/W SERVICE BULLETIN 145-53-1046 INSTALLATION OF IR SUPPRESSOR SUPPORT STRAPS AT STATIONS 555,575, AND 594	OLR/DS-2, HAAF / 912-315-7963	14-Nov-2007	1	RD459339	
C/W SERVICE BULLETIN 145-53-1046 INSTALLATION OF IR SUPPRESSOR SUPPORT STRAPS AT STATIONS 555,575, AND 594	OLR/DS-2, HAAF / 912-315-7963	14-Nov-2007	2	RD459339	
IVHUMS AWR DATED 27 NOV 07 REV 6 SUPERSEDES IVHMS AWR DATED 07 SEP 07 REV 5.	D CO 3-10 GSAB, FT DRUM NY 13602	07-Dec-2007	1	KC981398	
H-47-08-ASAM-01 INSP FWD & AFT ROTOR HEAD HOUSING, MECHANICAL, PITCH C/W AT 5604.9 ACFT HRS.	D CO 3-10 GSAB, FORT DRUM NY	12-Feb-2008	1	JH704968	
COMPLIED WITH INSTALLATION OF MWO 1-1520-240-50-114 CREW CHIEF HEADREST ON THIS DATE.	DS2, FT DRUM, NY	18-Mar-2008	1	CW586947	
C/W INSTALLAION OF MWO 1-1520-240-50-115 ARMOR SEAT COMP ON THIS DATE.	DS2, FT DRUM, NY	18-Mar-2008	2	CW586947	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
H-47-08-AMAM-03 INSP AN/ASN-128B/D DOPPLER GPS NAV SET, C/W @ 6850.7 ACFT HRS.	D CO 3-10 GSAB, FT DRUM, NY	21-Apr-2008	1	KC981398	
ACE COMPLETED AT 6902 A/C HRS. BY ACE TEAM MEMBER BB. AMCOM MWO/OLR BRANCH	DS2, FT DRUM, NY	06-Jun-2008	1	JG389608	
PMS-3 COMPLETED @6902.1 ACFT HRS, NEXT PMS-2 DUE AT 7102.1 ACFT HRS	D-CO 3/10 GSAB, FT DRUM, NY	03-Sep-2008	1	AC312272	
ACFT DEPLOYED TO SOUTHWEST ASIA THEATER OF OPERATIONS	D CO 3-10 GSAB, IRAQ APO AE 09393	02-Nov-2008	2	KC981398	
H-47-09-SOF-02 ENG CROSS SHAFT AND ADAPTERS INSP CW @ 7030.5 ACFT HRS.	D CO 3-10 GSAB, IRAQ APO AE 09393	17-Dec-2008	2	KC981398	
H-47-MIM-08-002 CW @ 7085.3 ACFT HOURS	B CO 277TH ASB, FT. DRUM, NY	25-Jan-2009	1	MG416109	
PMS-2 COMPLETED BY 277 18JAN09. ACFT HRS. 7080.7	D CO 3-10 GSAB, IRAQ APO AE 09393	21-Feb-2009	1	CH477819	
#1 & #2 ENG MT NDI/ DRAG LINK INSP COMPLETED DURING 400HR CSP @ 7252.9 ACFT HRS	L-3 VERTEX, IRAQ APO AE 09393	25-Apr-2009	1	JM745497	
STA 420 FLOOR BEAM AUTH REPAIR IAW MEC# F91676 A. THIS IS A TEMP REPAIR AND SHALL BE REEVALUATED AT NEXT RESET.	L-3 VERTEX, IRAQ APO AE 09393	04-May-2009	1	JM745497	
400 HOUR CYCLE PHASE COMPLETED AT 7252.9 ACFT HRS. NEXT CYCLE PHASE INSPECTION (200 HR) DUE AT 7452.9 ACFT HRS	L-3 VERTEX, IRAQ APO AE 09393	06-May-2009	1	JM745497	
AWR DATED 30JUN09 (TTS 48786, REV B) (PILOT/C0-PILOT SEAT CUSHION).	D CO 3-10 GSAB, IRAQ APO AE 09393	05-Jul-2009	1	KC981398	
H-47-09-AMAM-02 AFT SLIDER SHAFT ASSEMBLY RETIREMENT LIFE, C/W @ 7344.3 ACFT HRS	D CO 3-10 GSAB, IRAQ APO AE 09393	17-Jul-2009	1	KC981398	
A3T (ARMY AIRFRAME ASSESSMENT TEAM) INSP FOR SBE CANDIDATES COMPLIED WITH @7397 ACFT HRS.	1106 TASMG (TAMP IQ), IRAQ APO AE 09393	08-Aug-2009	1	RP397190	
200 HOUR CYCLE PHASE COMPLETED AT 7438.4 ACFT HRS. NEXT CYCLE PHASE INSPECTION (400 HR) DUE AT 7638.4 ACFT HRS.	D CO 3-10 GSAB, IRAQ APO AE 09393	08-Sep-2009	1	JH704968	
H-47-09-AMAM-03 CW @ 7441.1 AC HRS (HALON FIRE EXTINGUISHER INSP)	WHNRD0 D CO 3/10 GSAB, IRAQ APO AE 09393	16-Sep-2009	1	JB178832	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO		3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
A/C WAS TRANSFERRED FROM B CO. 3-10 GSAB TO B CO. 3-25 GSAB @ 7443.6 A/C HOURS	D CO. 3-25 AVN, COB SPEICHER, APO, AE 09393	01-Oct-2009	1	KH684815	
COMPLIED WITH H-47-10-ASAM-02 (#1 PTU HYD LINE CLAMPS)	D CO 3-25 AVN REGT, COB SPEICHER, APO, AE 09393	20-Dec-2009	1	LS800246	
MEC # F102590 AUTHORIZATION GRANTED TO REPAIR CRACK ON LHS STATION 502 FORMER IAW DMWR 1-1520-240, WP 0116. CRACK WAS PREVIOUSLY REPAIRED, CRACK DEVELOPED IN REPAIR. OLD REPAIR REMOVED AND NDI COMPLETED. REPAIRED IAW WITH MEC # F102590	B CO 209TH ASB, COB SPIECHER, APO AE 09393	31-Dec-2009	1	JC641475	
DURING REPAIR OF CRACK AT STA. 482 BELLCRANK SUPPORT WAS REMOVED. DURING INSPECTION BELLCRANK LOWER MOUNT HOLE WAS FOUND ELONGATED BY A DRILL BIT. PERMISSION WAS GRANTED PER MEC # F102975 TO KEEP BELLCRANK IN SERVICE. NDI WAS COMPLETED AS PER MEC # F102975. CHECK FOUND OK.	B CO 209TH ASB, COB SPIECHER, APO AE 09393	10-Jan-2010	1	JC641475	
During 400 hr Phase Maintenance inspection, crack was discovered at Sta 482, BL 20L, WL+50 Bellcrank Support Fitting Former. Crack traveled approx. 5 in. cracking through the Bellcrank Support mounting hardware hole. After removing the previous repair to estimate full damage, found crack traveled passed stop drill hole. PERMISSION WAS GRANTED PER MEC # F102700 TO REPAIR. Inspect the condition of the repair at the next 200 hour phase for any structural change (fretting, or movement of hardware), and annotate in the aircraft historical records.	BCO 209TH ASB, COB SPIECHER, APO AE 09393	12-Jan-2010	1	CO675797	
1200 HOUR FUEL TANK INSPECTION C/W AT 7621.3 ACFT HRS.	B CO 209TH ASB, COB SPIECHER, APO AE 09393	13-Jan-2010	1	JC641475	
AFT PYLON REMOVED AND REINSTALLED AT ACFT HRS 7621.3 TO FACILITATE CRACK REPAIR AT STA 482	B CO 209TH ASB, COB SPIECHER, APO AE 09393	14-Jan-2010	1	JC641475	
DURING 400 HOUR INSPECTION, A/C HOURS 7621.3, DISCOVERED VOID IN FUSELAGE EQUIPMENT SUPPORT STRUCTURE. VOID IS LOCATED AT STA 240, BL 0.00, WL-35. STRUCTURE WAS REPAIRED IAW 1-1500-204-23.	B209TH ASB, COB SPIECHER, APO AE 09393	15-Jan-2010	1	CO675797	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
DURING 400 HOUR INSPECTION, A/C HOURS 7621.3, DISCOVERED VOID IN FUSELAGE EQUIPMENT SUPPORT STRUCTURE. VOID IS LOCATED AT STA 260, BL 0.00, WL-35. STRUCTURE WAS REPAIRED IAW 1-1500-204-23.	B209TH ASB, COB SPEICHER, APO AE 09393	15-Jan-2010	2	CO675797
DURING 400 HOUR INSPECTION, A/C HOURS 7621.3, DISCOVERED VOID IN FUSELAGE EQUIPMENT SUPPORT STRUCTURE. VOID IS LOCATED AT STA 400, BL 0.00, WL-38. STRUCTURE WAS REPAIRED IAW 1-1500-204-23.	B209TH ASB, COB SPEICHER, APO AE 09393	15-Jan-2010	3	CO675797
COMPLIED WITH H-47-10-AMAM-02 (ULLS-A(E) LCF CHANGE 60B)	D CO. 3-25 AVN, COB SPEICHER, APO AE 09393	19-Jan-2010	1	KH684815
400 HOUR CYCLE PHASE COMPLETED AT 7621.3 ACFT HRS. NEXT CYCLE PHASE INSPECTION 200 HOUR DUE AT 7821.3 ACFT HRS.	B CO 209TH ASB, COB SPEICHER, APO AE 09393	20-Jan-2010	1	JC641475
MEC# F104415 GOUGE IN AFT TRUSS MEASURING 0.025 INCH WIDE AND 0.070 INCH DEEP. NDI CHECKED GOOD NO CRACKS NOTED. GOUGE WAS BLENDED AND REFINISHED AS REQUIRED.	L-3, COB SPEICHER, APO AE 09393	05-Feb-2010	1	WM791582
COMPLIED WITH GEN-10-AMAM-02(DISTRIBUTION OF NEW AIRCRAFT ELECTRONIC LOGBOOK)	3-25 GSAB, COB SPEICHER, APO AE 09393	08-Feb-2010	1	KS335693
COMPLIED WITH H-47-10-AMAM-03 (FORWARD ROTOR HUB RETIREMENT HOURS ADJUSTMENT)	D CO 3-25 AVN REGT, COB SPEICHER, APO AE 09393	16-Mar-2010	1	LS800246
MEC# F104444 PERMISSION GRANTED TO INSTALL SLEEVE BUSHINGS PART NUMBER 145C2517-3/ NSN 3120-01-117-7445 IN AFT PYLON WORK PLATFORM LATCH RECEPTACLES FOR REINFORCEMENT.	B CO 209TH ASB, COB SPEICHER, APO AE 09393	08-Apr-2010	1	JC641475
COMPLIED WITH H-47-10-AMAM (AFT SLIDER SHAFT ASSEMBLY RETIREMENT LIFE)	BCO 209TH ASB, COB SPEICHER, APO AE 09393	08-Apr-2010	2	CO675797
PURIFICATION OF # 1, #2, AND UTILITY HYDRAULIC SYSTEMS COMPLETED @ 7821.3 A/C HOURS	D CO. 3-25 GSAB, COB SPEICHER, APO AE 09393	09-Apr-2010	1	KH684815
200 HOUR CYCLE PHASE COMPLETED AT 7821.3 ACFT HRS. NEXT CYCLE PHASE INSPECTION 400 HOUR DUE AT 8021.3 ACFT HRS.	B CO 209TH ASB, COB SPEICHER, APO AE 09393	12-Apr-2010	1	JC641475

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
MEC# F107361 PERMISSION GRANTED TO FABRICATE SLEEVE BUSHINGS PART NUMBER NAS77-7-035/ NSN 3120-01-326-4361 FOR BELLCRANK AT STATION 482 FWD.	BCO 209TH ASB, COB SPIECHER, APO AE 09393	13-Apr-2010	1	CO675797
MEC# F107360 PERMISSION GRANTED TO FABRICATE SLEEVE BUSHINGS PART NUMBER 114H4030-1/ NSN 3120-00-781-4495 FOR BELLCRANK AT STATION 482 FWD.	BCO 209TH ASB, COB SPIECHER, APO AE 09393	13-Apr-2010	2	CO675797
#1 AND #2 ENGINE 600 HR ENGINE MOUNT NDI AND DRAG LINK INSPECTION COMPLETED @ 7950.1 ACFT HOURS	L-3 VERTEX, COB SPEICHER, APO AE 09393	18-Jun-2010	1	JM745497
400 HR CYCLE PHASE COMPLETED AT 7950.1 ACFT HRS. NEXT 200 HR PHASE DUE AT 8150.1 ACFT HRS	L-3 VERTEX, COB SPEICHER, APO AE 09393	25-Jun-2010	1	JM745497
MEC# F111288A AUTHORIZATION GRANTED TO TEMPORARILY REPAIR CONNECTOR 300J79 (# 1 ENG) BY RESEATING RECEPTACLE PINS, APPLYING RTV TO BACK SIDE OF GROMMET, AND PERFORMING CONTINUITY CHECKS AND MOCS PER APPLICABLE TECHNICAL MANUALS	D CO 3-25 AVN REGT, COB SPEICHER, APO AE 09393	03-Jul-2010	1	RJ478705
AIRCRAFT ENROUTE TO WHEELER ARMY AIRFIELD, HAWAII	D CO 3-25 GSAB, COB SPEICHER, APO AE 09393	08-Jul-2010	1	LS800246
COMPLIED WITH H-47-10-ASAM-04	D CO 3-25 GSAB, WAAF, HI 96786	17-Sep-2010	1	RJ478705
COMPLIED WITH H-47-10-ASAM-07	D CO 3-25 AVN, WAAF, HI 96857	30-Sep-2010	1	RJ478705
COMPLIED WITH H-47-11-ASAM-01 (ALUMINUM WASHER P/N AN960-1016)	D CO. 3-25 GSAB, WAAF, HI 96857	14-Oct-2010	1	KH684815
COMPLIED WITH H-47-11-AMAM-01	D CO. 3-25 GSAB, WHEELER AAF, HI 96857	03-Dec-2010	1	KH684815
ACE PERFORMED AT 8000 ACFT HRS AT WHEELER AAF, HI BY JJ & E	AFMA/URS JBLM, WHEELER AAF, HI 96857	04-Feb-2011	1	CA409396
H-47-11-ASAM-04, MAINTENANCE MANDATORY, ALL H-47 SERIES AIRCRAFT, BLADE LAG DAMPNER ROD END BEARING COMPLIED WITH AT 8014.7 AIRCRAFT HOURS	D CO 3/2 GSAB, 2ID, KOREA	19-Apr-2011	1	EN231672
ACE COMPLETED@8059.7 ACFT HRS @ USAG HUMPHREYS KOREA BY ACE TEAM MEMBER "C"AMCOM OLR/MWO BRANCH HUNTSVILLE ALABAMA	D CO 3-2 GSAB, KOREA	04-Aug-2011	1	DT742318

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
H-60-11-AMAM-04, AN/ASN-128D DOPPLER AND AMPS SOFTWARE UPGRADE, COMPLY WITH ON THIS DATE	D CO 3-2 GSAB APO AP 96271, KOREA	24-Oct-2011	1	FY642166
AIRCRAFT IS EQUIPPED WITH DGNS P3I AN/ASN-128D, AWR TN52014 DATED 22 FEB 08 IS IN EFFECT	AMCOM AFMA KOREA, USAG HUMPHREYS	15-Nov-2011	1	EM684008
AIRCRAFT IS EQUIPPED WITH P3 DRAIN LINE, AWR TTS 70944 DATED 25 JUN 09 IS IN EFFECT	AMCOM AFMA, USAG HUMPHREYS	01-Dec-2011	1	EM684008
ACE COMPLETED@8098.8 ACFT HRS @ USAG HUMPHREYS KOREA BY ACE TEAM MEMBER "C"AMCOM OLR/MWO BRANCH HUNTSVILLE ALABAMA	B CO 602ND GSB, USAG HUMPHREYS	11-Apr-2012	1	DT742318
H-47-12-AMAM-02, TRANSMISSION OIL SAMPLE INTERVAL CHANGE, COMPLY WITH ON THIS DATE	D CO 3-2 GSAB, APO AP 96271, KOREA	30-May-2012	1	KH941158
DURING CCI, AT 8111.8 ACFT HOURS, UNIT DISCOVERED 1 EA HI-LOC FASTENER AT APPROXIMATELY STA 482, WL 55, BLL 24 HAS 0.034 INCH (0.85MM) GAP UNDER HEAD. THE UNIT IS REQUESTING AUTHORIZATION TO CONTINUE OPERATION UNTIL NEXT 400 HR PHASE INSPECTION , WHICH IS DUE IN 38.3 HR OR 8150.1 ACFT HOURS; AT THAT TIME THE DISCREPANT FASTENER WILL BE INSPECTED (USING A FEELER GAGE METHOD) AT EVERY POST FLIGHT INSPECTION UNTIL NEXT 400 HR INSPECTION. ANY ADDITIONAL GAP DETECTED WILL BE REPORTED THRU AMCOM LAR FOR FURTHER ENGINEERING EVALUATION IAW MEC#F146857 DATED 30 MAY 2012.	D CO 3-2 GSAB, APO AP 96271, KOREA	30-May-2012	2	KH941158
H-47-12-ASAM-01, OBSERVANCE OF POSSIBLE CONTACT BETWEEN YAW ILCA LOWER INPUT REMOTE CONTROL LEVER HARDWARE AND HYDRAULIC PRESSURE TUBE ASSEMBLY COMPLIED WITH ON 14 AUG 2012	B CO 602ND ASB, USAG HUMPHREYS	14-Aug-2012	1	FB764762
400 HR PHASE INSP COMPLETED @ 8117.0 HRS. NEXT INSP DUE @ 8517.0 HRS.	B CO, 602D ASB, APO AP 96271, CAMP HUMPHREYS	20-Aug-2012	1	AW614318
H-47-13-ASAM-03; IRSS NOT INSTALLED. COMPLIED WITH ASAM ON THIS DATE.	B CO 602ND ASB, USAG HUMPHREYS	20-Dec-2012	1	FB764762
AIRCRAFT IS EQUIPPED WITH DUAL EDM SYSTEM, AWR TN 106093 DATED 2 MAY 12	URS AFMA, USAG HUMPHREYS	09-Jan-2013	1	SP905754

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8601654		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
AIRCRAFT IS EQUIPPED WITH AWIS/EAWIS SYSTEM, AWR TN 107597B DATED	URS AFMA, USAG HUMPHREYS	09-Jan-2013	2	SP905754
COMPLIED WITH H-47-13-AMAM-02 (LCF CHANGE 63 REQUIREMENTS) ON THIS DATE	D CO 3-2 GSAB APO AP, KOREA	25-Jan-2013	1	FY642166
CONTROLLED EXCHANGED YOLK ASSY, CYCL PN: 114C3043-6 FROM ACFT 8424158 TO ACFT 8601654 CONTROL EXCHANGE NUMBER: 13-0003	D CO 3/2 GSAB, KOREA	13-Mar-2013	2	CB818894
ACE COMPLETED@8176 ACFT HRS @ USAG HUMPHREYS KOREA BY ACE TEAM MEMBER "U"AMCOM OLR/MWO BRANCH HUNTSVILLE ALABAMA	B CO 602ND GSB, USAG HUMPHREYS	05-Jun-2013	1	JS861046
COMPLIED WITH H-47-13-SOF-02, SYNC SHAFT BOLTS PN 114D3053-2 AT ACFT HRS 8176.2	3-2 GSAB, KOREA	17-Jun-2013	1	RM916486
COMPLIED WITH H-47-13-ASAM-06 IMPROPERLY INSTALLED FASTNERS	3-2 GSAB, KOREA	29-Aug-2013	2	RM916486