

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
ONE TIME INSPECTION FOR INSTALLATION OF CORRECT INTERNAL PORTABLE FIRE EXTINGUISHER COMPLIED WITH (GEN-88-02) (TB55-1500-220-20-01). (NO PID)	BOEING HELICOPTERS  PHILA, PA	05-Jan-1989	2	QC000000
AIRCRAFT S/N 66-19129 CH-47B, INDUCTED AND CONVERTED TO CH47D, S/N 88-0070 ON 12 DEC 88. TOTAL TIME AT MODIFICATION: 4005.0 HRS. (NO PID)	BOEING HELICOPTERS  PHILA., PA.	05-Jan-1989	1	QC000000
AIRCRAFT S/N 88-0070 TEST FLOWN AND ACCEPTED AT 4011.6 HRS. (NO PID)	BOEING HELICOPTERS  PHILA, PA	08-Feb-1989	1	QC000000
SOF CH-47-89-04 ONE TIME INSPECTION OF THE FWD AND AFT ROTARY WING HEAD I/A/W TB55-1520-240-20-34C C/W THIS DATE. C.J. SHELTER, TI. (NO PID)	89 ARCOM ASF, 37 A IND. AP KS  KS 66031-0020	24-Feb-1989	2	QC000000
AIRCRAFT PREPARED FOR AIR SHIPMENT TO KOREA I/A/W TM 55-1520-241S A/C TIME 4020.7 C/W THIS DATE C.J. SHELTER, TI. (NO PID)	89TH ARCOM 37 A INDUSTRIAL AP KS  KANSAS 66031-0020	24-Feb-1989	1	QC000000
AIRCRAFT ASSEMBLED AND PREPARED FOR FLIGHT I/A/W TM55-1520-241-S C. ROBERTSON, SSG 45TH TRANS CO. APO SF 96271. (NO PID)	45TH TRANS CO  APO SF 96271	09-Mar-1989	1	QC000000
AIRCRAFT CONVERTED TO PHASE MAINTENANCE PROGRAM I/A/W TB55-1520-240-20-31 (CH-47-89-01)PHASE 1 CYCLE 1 DUE AT 6205.0 ACFT HRS D.HELFRICH SFC, A CO 2-501ST AVN REGT, APO 96271. (NO PID)	A CO 2/501ST AVN RGT  APO SF 96271	06-Apr-1989	1	QC000000
SOF EMERGENCY CH47-89-08, IMMEDIATE GROUNDING OF CH-47D AIRCRAFT WITH COMBINING XMSN COOLER FAN P/N145DS518-3 SSG A CO 2-501ST AVN REGT. APO SF 96271 (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	30-Jul-1989	1	QC000000
SOF TECHNICAL CH-47-89-06 REVISION OF CH47D ENGINE CROSS SHAFT INSPECTION INTERVAL IS PREVIOUSLY COMPLIED WITH THIS DATE 29 JUN 89 AT 4098.9 AIRCRAFT HOURS. F. ABENDANIO, SSG A CO 2-501ST AVN REGT APO SF 96271 (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271-0146	31-Jul-1989	1	QC000000
SOF CH-47-89-11 COMPLETED 20 OCT 89 AT 4108.4 ACFT HRS TI, A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	24-Oct-1989	2	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
SOF CH-47-89-10 COMPLETED 16 OCT 89 AT 4108.4 ACFT HRS. TI A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	24-Oct-1989	1	QC000000	
SOF EMERGENCY CH-47-89-12 IMMEDIATE GROUNDING OF CH47D'S DUE TO LOSS OF GREASE AROUND C-BOX COOLER FAN DRIVE CARTRIDGE TI A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	28-Oct-1989	1	QC000000	
SOF CH-47-89-13 COMPLETED 19 NOV 89 AT 4111.6 ACFT HRS ELAINE CARRERA, TI, A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	19-Nov-1989	1	QC000000	
SOF CH-47-89-14 COMPLETED 19 NOV 89 AT 4112 ACFT HRS. ELAINE CARRERA, TI A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	21-Dec-1989	2	QC000000	
SOF CH-47-89-15 COMPLETED AT 4136.4 ACFT HRS. ELAINE CARRERA, TI, A CO 2/501ST AVN REGT. APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	21-Dec-1989	1	QC000000	
SOF CH-47-90-01 COMPLETED 15 JAN 90 AT 4141.2 ACFT HRS. PAUL PARKS, TI A CO 2/501ST AVN REGT. APO SF 96271 (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	15-Jan-1990	1	QC000000	
SOF CH47-90-03 COMPLETED AT 4174.5 ACFT HRS ELAINE CARRERA. A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	05-Feb-1990	1	QC000000	
PHASE 1 CYCLE1 COMPLETED 21 MAR 90 AT 4202.8 ACFT HRS, NEXT PHASE DUE AT 4402.8 ACFT HRS. PAUL PARKS, TI, A CO 2/501ST AVN REGT. APO SF 96271. (NO PID)	A CO 2/501 AVN REGT REGT  APO SF 96271	21-Mar-1990	1	QC000000	
SOF CH-47-90-05 COMPLIED WITH AT 4208.8 ACFT HRS TI, A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	06-Apr-1990	1	QC000000	
SOF CH-47-90-06 COMPLIED WITH 20 APR 90 AT 4215.3 ACFT HRS IAW TB 55-1520-240-20-98 TI, A 2/501ST AVN REGT, APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT  APO SF 96271	20-Apr-1990	1	QC000000	
SOF CH-47-90-07 COMPLIED WITH AT 4215.3 ACFT HRS A CO 2/501ST AVN REGT. APO SF 96271. (NO PID)	A 2/501ST AVN REGT REGT  APO SF 96271	21-Apr-1990	1	QC000000	
SOF CH-47-90-09 COMPLIED WITH AT 4215.3 ACFT HRS E. CARRERA. A CO 2/501ST AVN	A CO 2/501ST AVN REGT	02-May-1990	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
REGT. APO SF 96271. (NO PID)				
APO SF 96271				
OCM/ACE PERFORMED AT 4266 A/C HRS AT CAMP HUMPHREY KOREA. (NO PID)	AVSCOM OCMSEC ST LOUIS	19-Jul-1990	1	QC000000
APO SF 96271				
SOF CH-47-90-11 COMPLIED WITH AT 4268.0 ACFT HRS P. PARKS TI, A CO 2/501ST AVN REGT, APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT	09-Aug-1990	1	QC000000
APO SF 96271				
SOF CH-47-90-12 COMPLETED ON 15 SEP 90 AT 4283.5 ACFT HOURS. A CO 2/501ST AVN REGT APO SF 96271. TI (NO PID)	A CO 2/501ST AVN REGT	15-Sep-1990	1	QC000000
APO SF 96271				
SOF CH-47-90-13 COMPLETED ON 27 SEP 90 AT 4295.5 ACFT HRS. A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT	27-Sep-1990	1	QC000000
APO SF 96271				
SOF CH-47-91-01 COMPLETED ON 3 APR 91 AT 3937.9 ACFT HRS. A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT	03-Apr-1991	1	QC000000
APO SF 96271				
PHASE 2 CYCLE 1 COMPLETED AT 4398.9 ACFT HRS. PHASE 3 CYCLE 1 DUE AT 4598.9 ACFT HRS ART PATTERSON A CO 2/501ST AVN REGT APO SF 96271. (NO PID)	A CO 2/501ST AVN REGT	23-May-1991	1	QC000000
APO SF 96271				
OCM, ACE PERFORMED AT 4409 A/C HRS AT CAMP HUMPHREYS. ROK BY ACE TEAM MEMBER P AVSCOM OCMSEC ST LOUIS MO. (NO PID)	ASVCOM OCMSEC	24-Jun-1991	1	QC000000
CAMP HUMPHREYS 96271				
CH-47-92-ASAM-01 ONE TIME INSP OF INTERFERENCE BETWEEN THE ENG. CROSS SHAFT AND THE R/H FAIRING ACCESS COVER. COMPLETED 29 OCT 91 AT 4456.7 ACFT HRS. A CO 2/501ST AVN REGT APO AP 96271. (NO PID)	A CO 2/501ST AVN REGT	29-Oct-1991	1	QC000000
APO AP 96271				
CH-47-92-ASAM-02 ONE TIME INSPECTION OF GENERATOR WIRE HARNESS FOR CHAFFING AGAINST FIRE EXT. DISCHARGE TUBES AT STA 502, WL 66, COMPLETED 21 NOV 91 AT 4486.1 ACFT HRS. A CO 2/501ST AVN APO AP 96271. (NO PID)	A CO 2/502ST AVN REGT	21-Nov-1991	1	QC000000
APO AP 96271				
CH-47-91-ASAM-08 (TB 1-1520-240-20-58) COMPLIED WITH 4 SEPT 91 AT 4430.0 ACFT HRS. SSG, CO A 2/501 AVN REGT APO AP 96271. (NO PID)	A CO 2/501ST AVN REGT	30-Nov-1991	1	QC000000
APO AP 96271				

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-92-ASAM-04 COMPLETED AT 4587.1 ACFT HRS. INSP OF ENG D/S ADAPTERS AND RETORQUE OF ALL BOLTS TI. A CO 2/501ST AVN REGT. (NO PID)	A CO 2/501ST AVN REGT  APO AP 96271	28-Apr-1992	1	QC000000
MWO 55-1520-240-50-34(REPLACEMENT OF COATED PITCH LINK BOLTS) COMPLETED THIS DATE AT 4598.8 ACFT HRS BY DYNCORP AT CAMP HUMPHREYS KOREA APO AP 96271. (NO PID)	DYNCORP  APO AP 96271	19-May-1992	1	QC000000
OCM/ACE PERFORMED AT 4599 A/C HRS AT CAMP HUMPHREY KOREA BY ACE TEAM MEMBER "R" AVSCOM OCMSEC, ST LOUIS, MO. (NO PID)	AVSCOM OCMSEC  APO AP 96271	05-Jun-1992	1	QC000000
PHASE 3 CYCLE 1 COMPLETED 26 JUN 92 AT 4598.8 ACFT HRS, NEXT PHASE DUE AT 4798.8 ACFT HRS.(PHASE #4) A CO 2/501ST AVN REGT APO AP 96271. (NO PID)	A CO 2/501ST AVN  APO AP 96271	26-Jun-1992	1	QC000000
SAFETY OF FLIGHT, EMERGENCY IMMEDIATE GROUNDING OF CH-47 AND MH-47 SERIES AIRCRAFT CH-47-93-01 C/W A CO 2/501ST AVN REGT, APO AP 96271. (NO PID)	A CO 2/501ST AVN  APO AP 96271	26-Oct-1992	1	QC000000
SAFETY-OF-FLIGHT U.S. ARMY CH-47D, MH-47D AND MH-47E AIRCRAFT UNGROUNDING OF U.S. ARMY CH-47D, MH-47D AND MH-47E AIRCRAFT CH-47-93-02 C/W. A CO 2/501ST AVN REGT, APO AP 96271. (NO PID)	A CO 2/501ST AVN REGT.  APO AP 96271	04-Nov-1992	1	QC000000
COMPLIED WITH C-BOX SHIMMING TO ALIGN ENGINE DRIVESHAFTS. .050 INCH SHIMS INSTALLED AT EACH LEG OF C-BOX UNDER BUSHINGS. (NO PID)	BOEING HELICOPTERS  APO AP 96271	27-Jan-1993	1	QC000000
#1 AND #2 FWD. ENGINE MOUNT LUGS DISASSEMBLY AND DYE PENETRANT INSPECTION PREVIOUSLY COMPLETED ON 8 JUNE 92 AT 4598.8 ACFT HRS SEE ATTACHED AMSAV-Q FORM 40 A CO 2/501ST AVN REGT, APO AP 96271. (NO PID)	(NO ORGANIZATION)  APO AP 96271	11-Feb-1993	1	QC000000
ASAM, MAINT, MANDATORY , ALL CH-47D, MH-47D, AND MH-47E AIRCRAFT INSP OF HI-LOCK FASTENERS AT FUSELAGE STA. 83 TO 120 CH-47-93-ASAM-02, C/W A CO 2/501ST AVN REGT APO AP 96271. (NO PID)	A CO 2/501ST AVN REGT  APO AP 96271	04-Mar-1993	1	QC000000
ASAM, MAINT. MANDATORY ONE TIME	A CO 2/501ST AVN	16-Mar-1993	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
INSPECTION OF PUMPING UNIT HYDRALIC NSN 1650-01-240-4341, CH-47-93-ASAM-03 COMPLETED. A CO 2/501ST AVN APO AP 96271. (NO PID)					
APO AP 96271					
OCM/ACE PERFORMED AT 4799 A/C HRS AT CAMP HUMPHREY ROK, BY ACE TEAM MEMBER "U" AVSCOM OCM SEC ST LOUIS, MO. (NO PID)	AVSCOM OCM SEC	28-May-1993	1	QC000000	
APO AP 96271					
PHASE 4 COMPLETED AT 4798.7 ACFT HRS PHASE #1 DUE AT 4998.7 ACFT HRS. A CO 2/501ST AVN REGT, APO AP 96271. (NO PID)	A CO 2/501ST AVN REGT	03-Jun-1993	1	QC000000	
APO AP 96271					
SOF CH-47-93-03 ONE TIME RECORDS CHECK OF ENG XMSN P/N 145D6300 SERIES. (NO PID)	A CO 2-501 AVN REGT	18-Jul-1993	1	QC000000	
APO AP 96271					
CH-47-ASAM-94-01 MAINTENANCE MANDATORY ALL CH-47D MH-47D AND MH-47E ONE TIME AND RECURRING INSPECTION OF BUSHINGS ON ROTORHEAD P/N 145R2003-9 AND 145R2004-18, COMPLIED WITH AT 4845.3 ACFT HRS. (NO PID)	A CO 2-501ST AVN APO AP 96271	04-Nov-1993	1	QC000000	
APO AP 96271					
CH-47-94-ASAM-02 MAINTENANCE MANDATORY, ALL CH-47D, MH-47D AND MH-47E AMENDMENT TO ASAM CH-47- 94-01 COMPLIED WITH 4845.3 AFT HRS. (NO PID)	A CO 2-501 AVN	10-Nov-1993	1	QC000000	
APO AP 96271					
CH-47-94-ASAM-03 MAINTENANCE MANDATORY ALL CH-47D, MH-47D AND MH-47E ONE TIME AND RECURRING INSPECTION OF RIGID CONNECTION LINKS PN145C3340-10 COMPLIED WITH 4895 ACFT HRS. (NO PID)	A CO 2-501 AVN REGT	25-Jan-1994	1	QC000000	
APO AP 96271					
CH-47-94-ASAM-04 MAINTENANCE MANDATORY ONE TIME INSPECTION OF PILOT / CO-PILOT LAP BELTS COMPLIED WITH AT 4898.2 ACFT HRS. (NO PID)	A CO 2-501 AVN	10-Feb-1994	1	QC000000	
APO AP 96271					
CH-47-94-ASAM-06 MAINTENANCE MANDATORY INSPECTION OF HYD PUMPS COMPLETED 4930.6 ACFT HRS NO STRATO POWER PUMPS INSTALLED. (NO PID)	A CO 2-501 AVN	28-Apr-1994	1	QC000000	
APO AP 96271					
OCM/ACE PERFORMED AT 4958 AC HRS AT CP HUMPHREYS, ROK BY "C" OCM/ACE . (NO PID)	OCM/ACE	08-Jul-1994	1	QC000000	
CP HUMPHREYS ROK					

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-94-ASAM-05 5000LB TIE DOWN ASSY INSPECTION COMPLETED 4938.1 HRS. (NO PID)	A CO 2-501 AVN  APO AP 96271	01-Aug-1994	1	QC000000	
AFT ROTOR HEAD 400 HR END CAP INSPECTION COMPLETED AT 4998.3 ACFT HRS. (NO PID)	A CO 2-501 AVN  APO AP 96271	11-Aug-1994	2	QC000000	
PHASE NO 1 COMPLETED AT 4998.3 ACFT HRS. NEXT PHASE DUE AT 5198.3 ACFT HRS. (NO PID)	A CO 2-501 AVN  APO AP 96271	11-Aug-1994	1	QC000000	
CH-47-95-01 ONE TIME INSP OF UPPER DUAL BOOST ACTUATORS COMPLETED AT 5024.7 HRS. (NO PID)	A CO 2-501 AVN  APO AP 96271	07-Dec-1994	1	QC000000	
CH-47-95-ASAM-02 ONE TIME TORQUE VERIFICATION OF THE NUTS SECURING THE #1 AND #2 PTU MOTOR PUMP TO 85LB INCHES COMPLETED 5030.2 ACFT HRS. (NO PID)	A 2-501 AVN  APO AP 96271	20-Jan-1995	1	QC000000	
CH-47-95-ASAM-04 ONETIME INSP FOR STRATOPOWER PUMPS NSN 1650-01-249-4341 COMP 5064.8. (NO PID)	A CO 2-501 AVN  APO AP 96271	24-Mar-1995	1	QC000000	
SOF CH-47-95-02 ONE TIME VISUAL INSP AND TORQUE CHECK OF LOWER DRIVE LINK TO SWASHPLATE RETAINING HARDWARE COMPLETED 5097.9 ACFT HRS. (NO PID)	A CO 2-501 AVN  APO AP 96271	07-May-1995	1	QC000000	
CH-47-95-ASAM-05 MAINTENANCE MANDATORY ALL CH-47D AND MH-47D AND MH-47E ACFT ONE TIME AND RECURRING INSP AND LUBRICATION OF THE FLIGHT CONTROL ROD END BEARINGS (ROLLING ELEMENT) TB 1-1520-240-20-77. (NO PID)	A CO 2-501 AVN  APO AP 96271	30-May-1995	1	QC000000	
OCM/ACE PERFORMED AT 5106 A/C HRS, AT CAMP HUMPHREYS. (NO PID)	OCM/ACE  CAMP HUMPHREYS ROK	11-Jul-1995	1	QC000000	
CH-47-95-ASAM-06 COMPLIED WITH AT 5134.0 ACFT HOUR (NO PID)	A CO 2/501 AVN  APO AP 96271	25-Aug-1995	1	QC000000	
CH-47-95-ASAM-07 COMPLIED WITH AT 5140.7 ACFT HOURS. (NO PID)	A CO 2-501 AVN  APO AP 96271	14-Sep-1995	1	QC000000	
CH-47-95-ASAM-08 COMPLIED WITH AT 19 SEP 95 AT 5143.2 ACFT HRS. (NO PID)	A CO 2/52 AVN	19-Sep-1995	2	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
APO AP					
CH-47-95-ASAM-08 COMPLIED WITH AT 19 SEP 95 AT 5143.2 ACFT HRS. (NO PID)	A CO 2/52 AVN	19-Sep-1995	1	QC000000	
APO AP					
CH-47-96-ASAM-01 COMPLIED WITH AT 5182.8 ACFT HRS (NO PID)	A CO 2/501 AVN	08-Nov-1995	1	QC000000	
APO AP 96271					
CH-47-96-ASAM-03 COMPLIED WITH AT 5198.1 ACFT HRS. (NO PID)	A CO 2/52 AVN	21-Feb-1996	1	QC000000	
APO AP 96271					
#1 AND #2 ENG FWD MOUNT FLOURECENT PENETRANT INSP COMP AT 5198.1 ACFT HRS NEXT INSP DUE AT 5798.1 ACFT HRS. (NO PID)	DYNCORP	08-Mar-1996	2	QC000000	
APO AP 96271					
PHASE #2 COMP AT 5198.1 ACFT HRS PHASE #3 DUE AT 5398.1 ACFT HRS. (NO PID)	DYNCORP	08-Mar-1996	1	QC000000	
APO AP 96271					
OCM/ACE PERFORMED AT 5304 A/C HRS AT APO AP 96271 BY ACE TEAM MEMBER 'L' AVSCOM OCMSEC, ST LOUIS,MO. (NO PID)	A CO 2-52 AVN	11-Jun-1996	1	QC000000	
APO AP 96271					
CH-47-ASAM-04 COMPLIED WITH AT 5274.7 ACFT HRS. (NO PID)	A CO 2/52 AVN	12-Jun-1996	1	QC000000	
APO AP 96271					
CH-47-96-ASAM-05 COMPLIED WITH AT----- ----- (THE DA FORM 2408-15 SAYS THE ACFT HRS ARE 5990.9 ACFT HRS. BUT, IT IS HIGHLY UNLIKELY THAT THIS ACFT FLEW OVER 700 HRS BETWEEN 12 JUN 96 AND 25 JUN 96. CORRECTED HRS SHOULD BE)----- - 5290.9 ACFT HRS. (NO PID)	A CO 2/52 AVN	25-Jun-1996	1	QC000000	
APO AP 96271					
CH-47-96-ASAM-06 ONE TIME INSP ON UPPER BOOST ACT AND SWASHPLATE AT 5297.8 ACFT HRS. (NO PID)	DYNCORP	02-Jul-1996	1	QC000000	
APO AP 96271					
CH-47-96-ASAM-07 COMPLIED WITH AT 5304.2 ACFT HRS. (NO PID)	A CO 2/52 AVN	11-Jul-1996	1	QC000000	
APO AP 96271					
CH-47-ASAM-08 COMPLIED WITH AT 5336.4 ACFT HRS. (NO PID)	A CO 2/52 AVN	22-Aug-1996	1	QC000000	
APO AP 96271					
CH-47-ASAM-09 ALL CH-47D, MH-47D, AND MH-47E INSP AND REPAIR OF AFT PYLON CLAMSHELL DOOR LOWER LATCH TO PRECLUDE WEAR AND/OR IN-FLIGHT LOSS OF DOORS. (NO PID)	A CO 2/52 AVN	13-Sep-1996	1	QC000000	
APO AP 96271					



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-95-ASAM-08 COMPLIED WITH AT 19 SEP 95 AT 5143.2 ACFT HRS. (NO PID)	A CO 2/52 AVN	19-Sep-1996	1	QC000000	
APO AP					
CH-47-97-ASAM-01 COMPLIED WITH AT 5374.1 ACFT HRS. (NO PID)	A CO 2/52 AVN	11-Oct-1996	1	QC000000	
APO AP 96271					
SOF CH-47-97-01-ASAM-01 ALL CH-4D, MH-47D, MH-47E ONE TIME VISUAL INSP OF FWD XMSN MOUNTING (BARREL) NUTS COMPLIED WHT AT 5388.8 ACFT HRS. (NO PID)	A CO 2/52 AVN	15-Nov-1996	1	QC000000	
APO AP 96271					
GEN-97-ASAM-03 COMPLIED WITH AT 5398.0 ACFT HRS. (NO PID)	A CO 2/52 AVN	07-Jan-1997	2	QC000000	
APO AP 96271					
CH-47-97-ASAM-02 COMPLIED WITH AT 5398.0 ACFT HRS. (NO PID)	A CO 2-52 AVN	07-Jan-1997	1	QC000000	
APO AP 96271					
ATCOM APPROVED TO REAM MOUNT 1.000" #1 ENGINE MOUNT FWD INSIDE/ OUT SIDE LUG REAMED. (NO PID)	A CO 2/52 AVN	06-Feb-1997	2	QC000000	
APO AP 96271					
CH-47-97-ASAM-03 200 HR RECURRING INSP OF 5000LB TIE DOWN COMPLIED WITH AT 5398.0 ACFT HRS. (NO PID)	A CO 2/52 AVN	06-Feb-1997	1	QC000000	
APO AP 96271					
PHASE #3 COMPLETED AT 5398.0 ACFT HRS. PHASE #4 DUE AT 5598.0 ACFT HRS. (NO PID)	DYNCORP	21-Feb-1997	1	QC000000	
APO AP 96271					
CH-47-ASAM-05 ONE TIME INSPECTION FOR AND REPLACEMENT OF AN320-12 CASTELLATED NUTS MADE BY GREER STOP NUT INC. COMPLIED W/5421.6 ACFT HRS. (NO PID)	A CO 2/52 AVN	14-Mar-1997	2	QC000000	
APO AP 96271					
CH-47-ASAM-04 ONE TIME INSPECTION AND REPLACEMENT OF CERTAIN P/N 4C3074 CRISSAIR INC CHECK VALVES COMPLIED WITH 5421.6 ACFT HRS. (NO PID)	A CO 2/52 AVN	14-Mar-1997	1	QC000000	
APO AP 96271					
CH-47-ASAM-06 ONE TIME VISUAL INSP OF NAVSTAR AN/ASN-149(V1) SERIES GPS COMPLIED WITH AT 5465.3 ACFT HRS. (NO PID)	A CO 2/52 AVN	08-Apr-1997	1	QC000000	
APO AP 96271					
CH-47-97-ASAM-07 ONE TIME AND RECURRING INSP OF POWER DISTRUBUTION PANELS COMPLIED WITH AT 5476.8 ACFT HRS. (NO PID)	A CO 2/52 AVN	21-Apr-1997	1	QC000000	
APO AP 96271					



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-97-ASAM-08 INSPECTION AND LUBBRICATION REQUIREMENTS OF FLT CONTROL ROD END BEARINGS COMPLIED WITH AT 5476.8 ACFT HRS. (NO PID)	A CO 2/52 AVN	24-Apr-1997	1	QC000000	
APO AP 96271					
CH-47-97-ASAM-09 ONE TIME RECORDS CHECK OF APU TIMES AND SERIAL NUMBERS COMPLIED WITH AT 5499.2 ACFT HRS. (NO PID)	A CO 2/52 AVN	02-Jun-1997	1	QC000000	
APO AP 96271					
ATCOM ENGINEER APPROVED #7126-RK-056 AUTHORIZE DISCONNECTION OF WIRE W559-11-20 PRONE TERMINAL 4 OF SWITCH 11151 FOR NVG'S MUST BE REVERTED UPON ACFT TRANSFER. (NO PID)	A CO 2/52 AVN	16-Jun-1997	1	QC000000	
APO AP 96271					
CH-47-97-ASAM-10 ONE TIME INSP OF ANVIS/HUD POWER SUPPLIES COMPLIED WITH AT 5574.0 ACFT HOURS. (NO PID)	A CO 2/52 AVN	30-Sep-1997	1	QC000000	
APO AP 96271					
CH-47-98-ASAM-01 ONE TIME RECORDS CHECK. OF ACFT 6 MONTH FILE FOR FLIGHT CONTROL ANOMALIES COMPLIED WITH AT 5574.0 A/C HRS. (NO PID)	A CO 2/52 AVN	16-Oct-1997	1	QC000000	
APO AP 96271					
CH-47-98-ASAM-02 AFT LANDING GEAR DRAG LINK (ASSY-3) EXTENDED UNTIL 30 APR 99 COMPLIED WITH AT _____ ACFT HRS. (NO PID)	A CO 2/52 AVN	24-Oct-1997	1	QC000000	
APO AP 96271					
ATCOM APPROVED TO REAM MOUNT FOR #1 ENG INBOARD FWD MOUNT. INSIDE REAM DIAMETER, MAX LIMIT TO 1.0690 RECOMMEND ENG MOUNT REPLACEMENT AT THE NEXT PHASE INSP. REPAIR COMPLIED AT 5595.5 ACFT HRS. (NO PID)	C CO 52ND AVN	06-Feb-1998	1	QC000000	
APO AP 96271					
PHASE #4 COMPLETED AT 5595.5 ACFT HRS. PHASE #1 DUE AT 5795.5 ACFT HRS. (NO PID)	DYNCORP	20-Feb-1998	1	QC000000	
APO AP 96271					
SOF MESSAGE CH-47-98-01 ONE TIME INSPECTION OF UPPER AFT BOOST ATUATORS TO STATIONARY SWASHPLATE RETAINING HARDWARE (PN:14SR3650-1) COMPLETED AT 5626.1 ACFT HRS. (NO PID)	A CO 2/52 AVN	19-Mar-1998	1	QC000000	
APO AP 96271					
ACE COMPAT 5671 ACFT HRS CP HUMPHREYS ROK ACECODE 'L' BY AMCOM OLR MWO BRANCH HUNTSVILLE, AL. (NO PID)	A CO 2/52 AVN	06-May-1998	1	QC000000	
APO AP 96271					

1. AIRCRAFT MODEL	2. NOMENCLATURE	3. AIRCRAFT SERIAL NUMBER		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47D	HELICOPTER, CARGO	8800070		
CH-47-98-ASAM-03 MANDATORY TORQUE CHECK AND REPLACEMENT OF AUXILIARY POWER UNIT BOLTS COMPLETED AT 5670.5 ACFT HRS. (NO PID)	A CO 2/52 AVN	11-May-1998	1	QC000000
APO AP 96271				
CH-47-98-ASAM-04 ONE TIME INSPECTION FOR AFT TRANSMISSIONS WITH SUSPECTED IMPROPERLY SHIMMED INPUT PINION GEAR ASSY COMPLETED AT 5670.5 HRS. (NO PID)	A CO 2/52 AVN	19-May-1998	1	QC000000
APO AP 96271				
CH-47-99-ASAM-01 ONE TIME INSPECTION OF LAG DAMPERS C/W 9 FEB 99 AT 5776.9 ACFT HRS (DE7739)	C.CO.52ND AVN REG	09-Feb-1999	1	QC000000
APO AP96271				
CH-47-99-ASAM-02 ACTIONS TO REDUCE FLT CONT LOCK- UP C/W 18 FEB 99 AT 5776.9 ACFT HRS (DE7739)	C.CO.52ND AVN REG	18-Feb-1999	1	QC000000
APO AP 96271				
CH-47-99-ASAM-03 ONE TIME AND RECURRING INSP OF HOIST/CARGO HOOK CONTROL PANEL AND WATER INTRUSION IN THE COCKPIT. C/W 10 MAR 99 AT 5777.2 ACFT HRS (DE7739)	C.CO.52ND AVN REG	10-Mar-1999	2	QC000000
APO AP 96271				
ACE PERFORMED AT 5777 A/C HOURS AT CAMP HUMPHRIES, ROK BY ACE TEAM MEMBER U, AMCOM,OLR/MWO BRANCH, HUNTSVILLE,AL. (DB4808)	C.CO.52ND AVN REG	10-Mar-1999	1	QC000000
APO AP96271				
CH-47-99-ASAM-04, FWD & AFT LONGITUDINAL CYCLIC TRIM YOKE BUSHING INSPECTIONS AND ACFT MAINTENANCE MANUAL CHANGES C/W 17 MAR 99 AT 5776.9 ACFT HRS (DE7739)	C.CO.52ND AVN REG	19-Mar-1999	1	QC000000
APO AP 96271				
CH-47-99-ASAM-05 EXTENSION FOR REPLACEMENT OF THE AFT LANDING GEAR DRAG LINK ASSY THAT ARE SUSCEPTIBLE TO STRESS COROSION CRACKING C/W 30 APR 99 AT 5789.2 ACFT HRS (DE7739)	C.CO.52ND AVN REG	30-Apr-1999	1	QC000000
APO AP 96271				
#2 ENG FWD MOUNT FLORECENT PENETRANT INSP COMP AT 5789.2 ACFT HRS NEXT INSP DUE AT 6389.2 ACFT HRS (JL2299)	C CO. 52ND AVN REGT	19-May-1999	1	QC000000
APO AP 96271				
AFT ROTOR HEAD S/N#A5-344 400HR END CAP INSP COMPLETED AT 5789.2 ACFT HRS NEXT INSP DUE AT 6189.2 ACFT HRS (DE7739)	C.CO.52ND AVN REG	15-Jun-1999	2	QC000000
APO AP 96271				

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
FWD ROTOR HEAD S/N# A4-1582 400HR END CAP INSP COMPLETED AT 5789.2 ACFT HRS NEXT INSP DUE AT 6189.2 ACFT HRS. (DE7739)	C.CO.52ND AVN REG	15-Jun-1999	1	QC000000	
APO AP 96271					
(SOF)CH-47-99-01 ONE TIME INSPECTION OF SYNC SHAFT MOUNTING BRACKETS FOR PROPER CLEARANCE TO SYNC SHAFT (JL2299)	C.CO.52ND AVN REG	06-Jul-1999	1	QC000000	
APO AP 96271					
(SOF)CH-47-99-02 IMMEDIATE GROUNDING OF ALL H-47 SERIES ACFT UNTILL A FULL RECORDS SEARCH AND INSPECTIONS CAN BE CONDUCTED TO DETERMINE EXTENT OF THE DISCREPENT PARTS (JL2299)	C.CO.52ND AVN REG	10-Aug-1999	1	QC000000	
APO AP 96271					
SOF CH-47-99-03, INSPECTION OF FWD & AFT XMSN GEAR/BEARING ASSEMBLIES C/W 26 AUG 99, AT 5789.2 ACFT HRS (DE7739)	C CO. 52ND AVN REGT	26-Aug-1999	1	QC000000	
APO AP 96271					
SOF CH-47-99-04, INSPECTION OF FWD & AFT XMSN GEAR/BEARING ASSEMBLIES IDENTIFIED BY SERIAL # PREFIX "VB", C/W 27 AUG 99, AT 5789.2 ACFT HRS. (DE7739)	C CO. 52ND AVN REGT	27-Aug-1999	1	QC000000	
APO AP 96271					
SOF CH-47-99-05 REPLACEMENT OF SUSPECT FORWARD AND AFT TRANSMISSION ASSEMBLIES WITH ONES THAT HAVE BEEN INSPECTED AND CLEARED FOR OPERATION (JL2299)	C CO. 52ND AVN REGT	15-Sep-1999	1	QC000000	
APO AP 96271					
PHASE 1 COMPLETED AT 5789.2 ACFT HRS. PHASE 2 DUE AT 5989.2 ACFT HRS (JL2299)	C.CO. 52ND AVN REGT	24-Sep-1999	1	QC000000	
APO AP 96271					
SOF CH-47-00-01 INSP AND CALCULATION OF APU STARTS (JL2299)	C CO. 52ND AVN REGT	09-Oct-1999	1	QC000000	
APO AP 96271					
SOF CH-47-00-02, CW 10 NOV 99 AT 5800.8 ACFT HRS (DE7739)	C CO 52ND AVN REGT	10-Nov-1999	1	QC000000	
APO AP 96271					
SOF CH-47-00-03 INSP AND CORRECTION PROCEDURE REQUIRED IAW SOF CH-47- 00-03, PARA. 8 AND 9 COMPLIED W/ 5818.9 ACFT HRS. (JH7517)	A CO 2/52 AVN	07-Dec-1999	1	QC000000	
APO AP 96271-0146					
SOF CH-47-00-04 ALL H-47 SERIES AIRCRAFT, ONE TIME INSPECTION OF ENGINE TRANSMISSIONS RECORDS FOR SUSPECT GEARS AND REPLACEMENT OF SUSPECT TRANSMISSIONS, IAW SOF CH-47 -00-04 (TB 1-1520-240-20-117) COMPLIED	A CO 2/52 AVN REGT	29-Jan-2000	1	QC000000	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8800070</b>		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID

WITH AT 5849.8 ACFT HRS. (JH7517)

APO AP 96271-0146

ALL PREVIOUS ENTRIES LISTED ON DA FORM 2408-15 HAVE BEEN ENTERED INTO ULLS-A AS OF 25 MAR 00 @ 1750 HRS. (RC4932)	A CO 2-52 AVN REGT	25-Mar-2000	1	QC000000
---	--------------------	-------------	---	----------

APO AP 96271-0146

SOF CH-47-00-05 ALL H-47 SERIES ACFT ONE TIME INSP OF PITCH HOUSINGS P/N 145R2075-13/-14/-15/-16 (TB 1-1520-240-20-120) C/W AT 5938.2 ACFT HRS. (PF8930)	A CO 2/52 AVN REGT	03-May-2000	2	QC000000
--	--------------------	-------------	---	----------

APO AP 96271-0146

CH-47-00-ASAM-01 MAINTENANCE MANDATORY, ALL CH-47D & MH-47D ACFT, INITIAL & RECURRING INSP OF FUEL PODS FOR CORROSION & ELECTRICAL BONDING (TB 1-1520-240-20-119) C/W @ 5938.2 ACFT HRS. (KG8535)	A CO 2-52 AVN REGT	03-May-2000	1	QC000000
---	--------------------	-------------	---	----------

APO AP 96271-0146

ACE PERFORMED AT 5940 A/C HOURS AT CP HUMPHREYS KOREA BY ACE TEAM MEMBER A, AMCOM, OLR/MWO BRANCH, HUNTSVILLE, AL (DC9265)	A CO 2/52 AVN REGT	15-May-2000	2	QC000000
--	--------------------	-------------	---	----------

APO AP 96271-0146

CH-47-00ASAM-02 MAINTENANCE MANDATORY, CH-47D, MH-47D & MH-47E, INITIAL & RECURRING INSP & REPLACEMENT OF HORIZONTAL HINGE PIN SHOULDERED BOLTS, P/N 114R2201-1 TB 1-1520-240-20-118) C/W @ 5938.2 ACFT HRS. (RC4932)	A CO 2-52 AVN REGT	15-May-2000	1	QC000000
---	--------------------	-------------	---	----------

APO AP 96271-0146

CH-47-00-ASAM-03 MAINT MANDATORY, ALL H-47 SERIES ACFT, HYD FLUID SAMPLING FROM FLT CONTROL & UTILITY SYSTEMS C/W @ 5949.2 ACFT HRS. (KG8535)	A CO 2-52 AVN REGT	02-Jun-2000	1	QC000000
---	--------------------	-------------	---	----------

APO AP 96271-0146

CH-47-00-ASAM-05 INSPECTION OF FWD & AFT SLIDER SHAFT SEALS IAW CH-47-00-ASAM-05 COMPLIED WITH AT 5987.8 ACFT HRST HRS, BUT NLT 9 AUG 00. (RC4932)	A CO 2-52 AVN REGT	28-Jul-2000	2	QC000000
--	--------------------	-------------	---	----------

CP HUMPHRYS KOREA  
APO AP 96271

CH-47-00-ASAM-04 INSPECTION OF HORIZONTAL HINGE PIN DA FORM 2408-16 IAW CH-47-00-ASAM-04 COMPLIED WITH AT 5987.8 HRS(22) WITHIN THE NEXT 10 FLIGHT HRS, BUT NLT 9 AUG 00. (RC4932)	A CO 2-52 AVN REGT	28-Jul-2000	1	QC000000
--	--------------------	-------------	---	----------

CP HUMPHRYS KOREA  
APO AP 96271

CH-47-00-ASAM-06 INSP FOR DEFECTIVE FULL AUTHORITY DIGITAL ELECTRONIC	C CO 52 AVN	27-Sep-2000	3	QC000000
---	-------------	-------------	---	----------

1. AIRCRAFT MODEL <b>CH-47D</b>		2. NOMENCLATURE <b>HELICOPTER, CARGO</b>		3. AIRCRAFT SERIAL NUMBER <b>8800070</b>	
4. REMARKS		5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID

CONTROL (FADEC) P3 DRAIN CARTRIDGE  
COMPLIED WITH AT 5987.9 ACFT HRS  
(CS3813)

APO AP 96271-0139

SOF CH-47-00-07 ALL H-47 ACFT  
COMBINING TRANSMISSION COOLING FAN  
DRIVE SHAFT INSPECTIONS C/W AT 5987.9  
ACFT HRS (CS3813)

C CO 52 AVN

27-Sep-2000

2

QC000000

APO AP 96271-0139

CH-47-00-ASAM-07 INSP OF UNTESTED  
FLIGHT SAFETY PART (FSP) BOLTS, P/N  
114R3650-7 C/W AT 5987.9 ACFT HRS  
(CS3813)

C CO 52 AVN

27-Sep-2000

1

QC000000

APO AP 96271-0139

CH-47-00-ASAM-08 ALL H-47 ACFT,  
INSPECTION OF FWD YOKE SHAFT FOR  
CORROSION, C/W AT 5987.9 ACFT HRS  
(FB7776)

C CO 52 AVN

28-Sep-2000

1

QC000000

APO AP 96271-0139

CH-47-01-ASAM-01 ALL H-47 ACFT,  
INSPECT FOR INSTALLATION OF MA-16  
INERTIA REELS, P/N 015-870145-3-16 CH-47-  
01-ASAM-01 (TB 1-1520-240-20-127) C/W AT  
5987.9 ACFT HRS (CS3813)

C CO 52 AVN

13-Oct-2000

1

QC000000

APO AP 96271-0139

CH-47-01-ASAM-02 INSP OF UNTESTED  
FLIGHT SAFETY PART (FSP) BOLTS P/N  
114R3650-6 AND 114R3650-11 COMPLIED  
WITH AT 5987.8 ACFT HOURS (CS3813)

C CO 52ND AVN

31-Oct-2000

1

QC000000

CAMP HUMPHREYS  
KOREA

CH-47-01-ASAM-03 ALL H-47 SERIES ACFT  
FORWARD AND AFT ROTOR HUB  
LIGHTENING HOLE INSPECTIONS C/W AT  
5987.8 ACFT HRS (CS3813)

C CO 52ND AVN

21-Nov-2000

1

QC000000

CAMP HUMPHREYS  
KOREA

CH-47-01-ASAM-05 ALL H-47 SERIES ACFT,  
ONE TIME INSP OF ROTOR HEAD ASSY  
DROOP STOP BOLTS FOR PROPER  
LENGTH (TB 1-1520-240-20-132) (CS3813)

C CO 52 AVN

15-Dec-2000

2

QC000000

APO AP 96271-0139

CH-47-01-ASAM-04 ALL H-47 SERIES  
AIRCRAFT INSPECT FOR UNTESTED  
FLIGHT SAFETY PART (FSP) TIE BAR  
PINSASSEMBLIES P/N 114R2168-3 AND  
114R2168-4 (TB 1-1520-240-20-133) (CS3813)

C CO AVN

15-Dec-2000

1

QC000000

APO AP 96271-0139

CH-47-01-ASAM-06 ALL H-47 SERIES ACFT,  
REVISION TOCH-47-01-ASAM-04 INSP FOR  
UNTESTED FLIGHT SAFETY PART (FSP) TIE  
BAR PINS ASSY P/N 114R2168-3 AND -4 (TB  
1-1520-240-20-133) (CS3813)

C CO 52 AVN

27-Dec-2000

2

QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8800070</b>		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID

APO AP 96271-0139

CH-47-01-01 SOF CH/MH-47D ACFT ONE  
TIME INSP OF AFT ROTOR HEAD  
ASSEMBLIES AND ENGINE CROSS SHAFT  
ADAPTER ASSEMBLIES CH-47-01-01 TB 1-  
1520-240-20-134 (CS3813)

CAMP HUMPHREYS  
KOREA

CH-47-01-02 SOF ALL H-47 SERIES ACFT  
INSP OF DROOP STOPS (CS3813)

APO AP 96271-0139

CH-47-01-ASAM-07 ALL H-47 SERIES ACFT,  
INSPECTION FOR UNTESTED (FSP) BOLTS  
P/N:114R3650-13 AND 114R3650-15. (TB 1-  
1520-240-20-135) (CS3813)

KOREA

SOF CH-47-01-03 (TB 1-1520-240-20-137) ALL  
H-47 SERIES ACFT UNGROUNDING  
REQUIREMENTS FOR ACFT WITH  
INCORRECTLY INSTALLED DROOP STOPS.  
(CS3813)

KOREA

HYDRAULIC PURIFICATION OF UTILITY AND  
FLIGHT CONTROL SYSTEMS COMPLETED  
@ 5987.9 ACFT HRS. AGPU S/N: 83-360A-  
0119 PURIFIER S/N:PE01078. (FB7776)

KOREA

PHASE #2 COMPLETED @ 5987.9 ACFT  
HRS. PHASE #3 DUE@ 6187.9 ACFT HRS.  
(FB7776)

KOREA

CH-47-01-ASAM-08 (TB 1-1520-240-20-138)  
INSPECT POWER, PRESSURE AND RETURN  
CONTROL MODULE ASSEMBLIES TO  
ENSURE SHUT-OFF DIAPHRAGM  
HARDWARE IS INSTALLED COMPLIED WITH  
AT ACFT HRS 6009.2 (PI6204)

KOREA

ACE PERFORMED AT 6018 ACFT HRS AT  
ACAMP HUMPHREYS, ROK BY ACE TEAM  
MEMBER "U" AMCOM OLR/MWO BRANCH  
HUNTSVILLE, ALABAMA. . (DB4808)

KOREA .

CH-47-01-ASAM-09 (TB 1-1520-240-20-139)  
INSPECTION FOR UNTESTED FSP BOLTS  
P/N 114R3650-9 AND BACB30ST10-40.  
COMPLIED WITH AT 6010.2 ACFT HRS.  
(ST0737)

KOREA

CH-47-02-ASAM-01 (TB 1-1520-240-20-142)  
INSPECTION OF STRUT ASSEMBLIES  
COMPLIED WITH 10 OCT 01 AT ACFT HRS  
6047.8 (PI6204)

DA FORM 2408-15, OCT 91  
EDITION OF JAN 64 IS OBSOLETE

HISTORICAL RECORD FOR AIRCRAFT

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

FOUO - For Official Use Only

1. AIRCRAFT MODEL <b>CH-47D</b>		2. NOMENCLATURE <b>HELICOPTER, CARGO</b>		3. AIRCRAFT SERIAL NUMBER <b>8800070</b>	
4. REMARKS		5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID

**KOREA**

CH-47-02-ASAM-02 (TB 1-1520-240-20-143)  
RECORDS CHECK TO DETERMINE IF  
FORWARD YOKE SHAFT REQUIRES  
REPLACEMENT COMPLIED WITH 28 DEC 01  
ACFT HRS 6083.8 (PI6204)

**KOREA**

SOF CH-47-02-03 (TB1-1520-240-20-141)  
INSPECT TIE BAR ASSY. PRIOR TO NEXT  
FLT. ACFT REST TO 111 PERCENT  
TRANSIENT ROTOR TACHOMETERS  
COMPLIED WITH 25 JAN 02 6084 ACFT HRS.  
(NC9707)

**KOREA**

SOF CH-47-02-02 (TB1-1520-240-20-141)  
INSPECT TIE BAR ASSY. PRIOR TO NEXT  
FLT. ACFT REST TO 111 PERCENT  
TRANSIENT ROTOR TACHOMETERS  
COMPLIED WITH 25 JAN 02 6084 ACFT HRS.  
(NC9707)

**KOREA**

SOF CH-47-02-01 (TB1-1520-240-20-144)  
INSPECT SWASHPLATE LOWER SEAL  
RETAINER SELF-LOCKING NUTS COMPLIED  
WITH 25 JAN 02 6084 ACFT HRS. (NC9707)

**KOREA .**

SOF CH-47-02-04 (TB 1-1520-240-20-145)  
INSPECTION OF THE FORWARD PIVOTING  
ACTUATOR UPPER ATTACHMENT BEARING  
C/W AT 6102.4 ACFT HRS 08 FEB 02  
(ST0737)

**KOREA**

TACAN ARN-154 INSTALLED IAW  
RAYTHEON AIS AT 6127.8 AIRCRAFT  
HOURS DRWG NUMBER NO961 (TA9817)

RAYTHEON AIS  
BLUEGRASS ARMY  
DEPOT  
RICHMOND, KY 40475

SOF CH-47-02-05(TB1-1520-240-20-146) INSP  
TIE BAR ASSY PRIOR TO NEXT FLT;ACFT  
REST TO 111% TRANSIET ROTOR  
SPEED;REWORK ALL ROTOR TACHS, C/W  
25 MAR 02, 6131.5 ACFT HRS. (MH4975)

**KOREA**

#1 & #2 ENGINE FWD MOUNTS DYE  
PENTRENT INSPECTION COMPLETED AT  
6131.5 ACFT HOURS:NEXT INSPECTION  
DUE AT 6731.5 ACFT HOURS (GG8204)

**KOREA**

ACE PREFORMED AT 6131.5 ACFT HRS. AT  
CAMP HUMPHREY KOREA BY ACE TEAM  
MEMBERS "U" AMCOM OLR/MWO  
BRANCHHUNTSVILLE,AL (DB4808)

**KOREA APO AP 96271**



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
PURIFICATION COMPLETED AT 6131.5 ACFT HRS. AGPU 0127: PUR A020 UTILITY START STOP PUR 504 506 AGPU 548 550 #1 FLT START STOP #2 FLT START STOP PUR 512 514 PUR 508 510 AGPU 552 534 AGPU 550 552 (GG8204)	B-CO 2/52 AVN REGT.	17-May-2002	2	QC000000	
KOREA					
PHASE #3 COMPLETED AT 6131.5 AIRCRAFT HOURS: PHASE #4 DUE AT 6331.5 AIRCRAFT HOURS (GG8204)	B-CO 2/52 AVN REGT. (DYNCORP)	17-May-2002	1	QC000000	
KOREA					
CH-47-02-ASAM-03 INSPECT FUEL CONTROL RELAY BOX IAW TB 1-1520-240- 20-147 COMPLIED WITH @A/C 6158.4 (ST0737)	B. CO. 2/52 AVN REGT	14-Jun-2002	1	QC000000	
KOREA					
CH-47-02-SOF-06 INSPECT COMBINING TRANSMISSION IAW (TB-1-1520-240-148) COMPLIED WITH @ 6168.7 ACFT HRS (ST0737)	B CO 2-52 AVN REGT	19-Jun-2002	1	QC000000	
APO 96271-5212					
SOF CH-47-03-01 INITIAL AND RECURRING FWD AND AFT SWASHPLATE INSPECTION AND GREASE SAMPLE COMPLIED WITH ON 22 OCT 02 (TA9817)	B CO 2-52 AVN DYNA CORP	22-Oct-2002	1	QC000000	
KOREA					
PHASE #4 COMPLETED AT 6331.4 AIRCRAFT HOURS PHASE #1 DUE AT 6531.4 AIRCRAFT HOURS (GG8204)	B-CO 2/52 AVN REGT. (DYNCORP)	11-Mar-2003	1	QC000000	
APO AP 96271 KOREA					
CH-47-03-ASAM-01, TBO TIME EXTENSION FOR SPECIFIC ENG. DRIVE SHAFT (PN 145D3504-2) COMPLIED WITH ON 20030326 @ 6332.4 ACFT HRS. (TA9817)	B CO 2/52ND AVN REGT	26-Mar-2003	1	QC000000	
KOREA					
CH-47D 8800070 INPUT FOR CORROSION TREAT, AND CAR PAINTING AT 6415.9 ACFT HRS, CONTRACT NO: DAJB03-02-D-0026 (RF4388)	ASD KAL KIMHAE	22-Aug-2003	1	QC000000	
KOREA					
ACFT EXTERIOR & BILGE AREA STRIPPED, INSPECTED FOR CORROSION, TREATED AND REPAINTED USING CARC-P, MIL-C- 46168D (ACFT EXTERIOR) AT MIL-C-22750, COLOR NO 17875 (BILGE AREA) AT 6415.9 HRS ON 20031002 AT KAL N.S. PARK IAW CONTRACT NO: DAJB03-02-D-0026. (RF4388)	ASD KAL KIMHAE	02-Oct-2003	1	QC000000	
KOREA					
AWR FOR RELOCATION OF CABIN BUBBLE WINDOW IS IN EFFECT DATED 28 NOV 03 R1 (NO AWR NUMBER).	D CO 3-2 GSAB	28-Nov-2003	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
KOREA				
ACFT MODIFIED WITH T55-GA-714A ENGINES. COMPLY WITH AWR 02 APR 03	B CO. 2-52 AVN	13-Jan-2004	1	QC000000
APO AP 96271				
ECL ENGINE CONTROL QUADRANT P/N MCH-15-6, S/N-107, FOUND TO BE ACCEPTABLE AND MARKED IAW AMCOM ON LOCATION REPAIR PROCEDURE FOR CONTROL QUADRANT P/N 3759086-1, DATED 17 NOV 02 (GS1688)	B CO 2/52 AVN REGT	14-Jan-2004	1	QC000000
CP HUMPHREYS KOREA				
CH-47-04-ASAM-01 ALL FOUR BOLT HEAD FACE INBOARD COMPLIED WITH 20040204, 6463.5 ACFT HRS (NC9707)	B CO. 2/52ND AVN.	04-Feb-2004	1	QC000000
KOREA				
SOF CH-47-04-01 FWD AND AFT SWASHPLATE BEARING INSPECTION AND GREASE SAMPLE REVISION COMPLIED WITH 20040206 (PI6204)	B CO 2/52 AVN	06-Feb-2004	1	QC000000
KOREA				
ACE PERFORMED AT 6529 ACFT HRS AT CAMP HUMPHREYS KOREA BY ACE TEAM MEMBER 'LL' AMCOM OLR/MWO BRANCH HUNTSVILLE, AL (GS1688)	B CO 2/52 AVN REGT	23-Mar-2004	1	QC000000
CP HUMPHREYS KOREA				
PHASE #1 COMPLETED AT 6529.9 ACFT HRS PHASE #2 DUE AT 6729.8 ACFT HRS (GS1688)	B CO 2/52 AVN REGT	19-Apr-2004	1	QC000000
CP HUMPHREYS KOREA				
COMPLY WITH REQUIREMENTS OF CH-47-04-ASAM-02; INSP OF AFT FIXED LINK AND CGI GAGE REMARK (GS0784)	BCO 2/52ND AVN	30-Apr-2004	1	QC000000
CP HUMPHRIES KOREA 96271				
CH-47-05-ASAM-01 INSP AFT CRITICAL DYNAMIC COMPONENTS, COMPLIED WITH 20041015, 6707.4 AC HRS (TC0481)	B CO 2/52 AVN	15-Oct-2004	1	QC000000
CP HUMPHREYS, KOREA 96271				
CH-47D 8800070 IMPUT TO KAL FOR REFURBISHMENT AT 6723.1, CONTRACT NO: W91QVN-05-D-0005 (TC0481)	KAL	18-Nov-2004	1	QC000000
GIMHAE, KOREA				
CH-47-05-SOF-01, EDDY CURRENT INSP FOR FWD AND AFT SWASHPLATE COMPLIED WITH ON 24 JAN 05 @ 6723.1 AC HRS (TC0481)	KAL	24-Jan-2005	1	QC000000
GIMHAE, KOREA				
CH-47-05-SOF-02, TECHNICAL, ALL H-47 SERIES ACFT, ROTOR BLADE, ROOT END FIBER DISTORTION. COMPLIED WITH AT	B CO 2/52 AVN REGT	22-Jul-2005	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
6723.1 ACFT HRS. (TC0481)	CP HUMPHREYS KOREA			
CAP CRACKED AND INPROPERLY REPAIRED UP CAP OF THE CROWN FORMER FS 594 RBL 23 WL 50. STOPDRILLED UE @ 6923.1 AC HRS. (TC0481)	KAL	28-Jul-2005	1	QC000000
	GIMHAE, KOREA			
CH-47-05-ASAM-04 INSP OF AFT XMSN RETAINER COMPLIED WITH ON 2 SEP 2005 @ 6723.1 AC HRS (TC0481)	KAL	02-Sep-2005	1	QC000000
	GIMHAE, KOREA			
AWR DATED 16 SEP 05 R1 (TACAN AN/ARN-154 INSTALLED) IS IN EFFECT (NO AWR NUMBER).	D CO 3-2 GSAB	06-Sep-2005	1	QC000000
	KOREA			
AWR DATED 30 SEP 2005 FOR IMPLEMENTATION OF MODIFIED SEAL, P/N 114R3428-1 IS IN EFFECT (NO AWR NUMBER).	D CO 3-2 GSAB	30-Sep-2005	2	QC000000
	KOREA			
AIRCRAFT EXTERIOR AND INTERIOR REPAINTING USING CARC-P, MIL-C-46168, ON 20051005, BY KAL (TC0481)	KAL	05-Oct-2005	1	QC000000
	GIMHAE, KOREA			
PHASE MAINTENANCE INSPECTION 1 THROUGH 4 COMPLETED@ 6723.1 AC HRS. 200HR MAINTENANCE CHECKLIST DUE @ 6923.1 AC HRS. (TC0481)	KAL	13-Oct-2005	1	QC000000
	GIMHAE, KOREA			
AIRCRAFT WIRING HARNESS REMOVED FROM AIRCRAFT WITH THE EXCEPTION OF THE LINE REPLACEABLE UNITS AND COAXIAL CABLES, MANUFACTURED NEW WIRING HARNESS AND INSTALLED THE NEW WIRING HARNESS (TC0481)	KAL	17-Oct-2005	1	QC000000
	GIMHAE, KOREA			
CH-47-05-ASAM-06 HYDRALIC FLUID SYSTEM MAINTENANCE COMPLIED WITH ON 31 OCT 2005 @ 6723.1 AIRCRAFT HRS (TC0481)	KAL	31-Oct-2005	1	QC000000
	GIMHAE, KOREA			
CH-47-06-SOF-01 INSP M24 DOOR MOUNTED ARMAMENT SUBSYSTEM C/W @ 6738.1 ACFT HRS (RM3496)	PROJECT OLR KOREA	20-Jan-2006	1	QC000000
	APO AP 96271			
COMPLIED WITH REQUIREMENTS OF CH-47 -06-SOF-02 AT 6739.4 ACFT HRS (GS1688)	D CO 2/52 GSAB	15-Feb-2006	1	QC000000
	CP HUMPHREYS, KOREA			
COMPLIED WITH CH-47-06-ASAM-02	D CO 2/52 GSAB	04-Mar-2006	2	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
(GS1688)	CP HUMPHREYS, KOREA				
COMPLIED WITH CH-47-06-ASAM-01 (TC0481)	D CO 2/52 GSAB	04-Mar-2006	1	QC000000	
	CP HUMPHREYS, KOREA				
COMPLIED WITH CH-47-06-ASAM-03 (GS1688)	D CO 2/52 GSAB	08-Mar-2006	1	QC000000	
	CAMP HUMPHREYS, KOREA				
CH-47-06-SOF-03 TEMPORARY FLIGHT RESTRICTIONS DUE TO AFT ROTOR BLADE FIBER DISTORTION COMPLIED WITH REQUIREMENTS @ 6750 HRS (GS1688)	D CO 2/52 GSAB	09-Mar-2006	1	QC000000	
	CAMP HUMPHREYS, KOREA				
ACE PERFORMED @ 6750.0 ACFT HRS CAMP HUMPREYS KOREA BY ACE TEAM MEMBER "Z", AMCOM OLR/MWO BRANCH HUNSTVILLE AL (DT2318)	B CO 2/52 GSAB	23-Mar-2006	1	QC000000	
	CAMP HUMPHREYS, KOREA				
CH-47-06-ASAM-03 AFT LCT ACTUATOR COMPLIED WITH REQUIREMENTS @ 6779.9 ACFT HRS (VV0168)	D CO 2/52 GSAB	12-May-2006	1	QC000000	
	CAMP HUMPHREYS, KOREA				
CH-47-06-SOF-04 SUSPECT AFT ROTOR BLADES COMPLIED WITH REQUIREMENTS @ 6802.3 ACFT HRS (SV2006)	D CO 2/52 GSAB	31-May-2006	1	QC000000	
	CAMP HUMPHREYS, KOREA				
AWR DATED 17 AUG 2006 (AWR 32395) FOR ADVANCED HUD SDC (P/N 125110-007) INSTALLED IS IN EFFECT	D CO 3-2 GSAB	17-Aug-2006	1	QC000000	
	KOREA				
CH-47-06-SOF-05 SUSPECT FORWARD ROTOR BLADES COMPLIED WITH REQUIREMENTS AT 6843.5 ACFT HRS (RD3074)	DCO,2-52 GSAB	23-Aug-2006	1	QC000000	
	CP. HUMPHREYS KOREA				
CH-47-06-SOF-06, TECHNICAL, H-47 SERIES AIRCRAFT, AFT CRITICAL DYNAMIC COMPONENTS. COMPLIED WITH AT6855.6 ACFT HRS. (RD3074)	DCO,2-52 GSAB	18-Sep-2006	1	QC000000	
	CP. HUMPHREYS KOREA				
CH-47-07-SOF-01 SWASHPLATE ROTATING RING, COMPLIED WITH REQUIREMENTS AT 8325.9 ACFT HRS (RD3074)	D CO 2-52 GSAB	24-Oct-2006	1	QC000000	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8800070</b>		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
<b>CP. HUMPHREYS KOREA</b>				
<b>CH-47-05-ASAM-05 MAINTENANCE MANDATORY, ALL H-47 AIRCRAFT, HYDRAULIC CHECK VALVES AND FLUID PARTS, COMPLIED WITH ON THIS DATE @ 6401.4 ACFT HRS (PH8741)</b>	<b>D CO 3-2 GSAB</b>	<b>11-Jan-2007</b>	<b>4</b>	<b>QC000000</b>
<b>APO AP 96271</b>				
<b>CH-47-02-ASAM-04 MAINTENANCE MANDATORY, ALL H-47 SERIES AIRCRAFT, INSPECTION FOR UNTESTED CRITICAL SAFETY ITEM P/N 114C3044-2 AFT YOKE SUPPORT SHAFT COMPLIED WITH ON THIS DATE 6901.4 ACFT HRS (PH8741)</b>	<b>D CO 3-2 GSAB</b>	<b>11-Jan-2007</b>	<b>3</b>	<b>QC000000</b>
<b>APO AP 96271</b>				
<b>CH-47-05-ASAM-03 MAINTENANCE MANDATORY, CH-47 AIRCRAFT, VERTICAL HINGE PIN BEARINGS COMPLIED WITH ON THIS DATE @ 6901.4 ACFT HRS (RD3074)</b>	<b>D CO 3-2 GSAB</b>	<b>11-Jan-2007</b>	<b>2</b>	<b>QC000000</b>
<b>APO AP 96271</b>				
<b>CH-47-05-ASAM-02 MAINTENANCE MANDATORY, ALL H-47 SERIES AIRCRAFT, AFT ROTARY WING, COMPLIED WITH ON THIS DATE @ 6901.4 ACFT HRS (PH8741)</b>	<b>D CO 3-2 GSAB</b>	<b>11-Jan-2007</b>	<b>1</b>	<b>QC000000</b>
<b>APO AP 96271</b>				
<b>CH-47-07-ASAM-01, MAINTENANCE MANDATORY, H-47 SERIES, ARC 220/KY-100 START UP PROCEDURES. COMPLIED WITH AT 6901.8 ACFT HRS. (RD3074)</b>	<b>D CO 2/52 GSAB</b>	<b>18-Jan-2007</b>	<b>1</b>	<b>QC000000</b>
<b>APO AP 96271</b>				
<b>CH-47-07-SOF-02, TECHNICAL, ALL H-47 SERIES ACFT, SUSPECT ROTOR BLADES. COMPLIED WITH AT 6909.1 ACFT HRS. (KH7429)</b>	<b>B CO 2/52 AVN REGT</b>	<b>24-Jan-2007</b>	<b>1</b>	<b>QC000000</b>
<b>CP HUMPHREYS KOREA</b>				
<b>CH-47-05-ASAM-05, REPLACEMENT OF HYD MODULE CHECK VALVES, MAINTENANCE REQUIREMENTS COMPLIED WITH AT 6918.0 ACFT HRS. (DF1800)</b>	<b>B CO. 3-2 GSAB, DYNCORP</b>	<b>28-Feb-2007</b>	<b>1</b>	<b>QC000000</b>
<b>APO AP 96271-5212</b>				
<b>COMPLIED WITH REQUIREMENTS OF CH-47 -07-ASAM-02, INSPECTION OF 145C3340-2 CONNECTING LINKS, AT 6918.0 ACFT HRS. (DF1800)</b>	<b>B CO. 3-2 GSAB, DYNCORP</b>	<b>06-Mar-2007</b>	<b>1</b>	<b>QC000000</b>
<b>APO AP 96271-5212</b>				
<b>200 HR CYCLE SERVICE MAINTENANCE CHECKLIST COMPLETED AT 6918.0 ACFT HRS. NEXT SCHEDULED INSP 400 HR DUE AT 7123.1 ACFT HRS (DF1800)</b>	<b>B CO. 3-2 GSAB, DYNCORP</b>	<b>07-Mar-2007</b>	<b>1</b>	<b>QC000000</b>
<b>APO AP 96271-5212</b>				
<b>ACE PERFORMED @ 7020.2 ACFT HRS @ CAMP HUMPHREYS, KOREA BT ACE TEAM</b>	<b>B CO 3-2 GSAB</b>	<b>15-Aug-2007</b>	<b>1</b>	<b>QC000000</b>

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
MEMBER "GG" AMCOM OLR/MWO BRANCH HUNTSVILLE, AL. (AL9816)				
APO AP 96271				
CH-47-07-SOF-03, TECHNICAL, ALL H-47 SERIES AIRCRAFT, SUSPECT ROTOR BLADES, COMPLIED WITH AT 7116.9 ACFT HRS (RD3074)	D CO 3-2 GSAB	10-Oct-2007	1	QC000000
APO AP 96271				
400 HR PHASE MAINTENANCE CYCLE CHECKLIST COMPLETED AT 7116.9 ACFT HRS. NEXT SCHEDULED PHASE INSPECTION 200 HR DUE AT 7316.9 ACFT HRS	B CO. 3-2 GSAB, DYNCORP	09-Nov-2007	1	DF701800
KOREA				
FE/CE (SIMULA) SEAT AND FRAME KIT INSTALLED. COMPLY WITH AWR 3 JUN 02.	D CO. 3-2 GSAB	17-Dec-2007	1	RW984580
APO AP 96271				
CH-47-08-AMAM-03, MAINTENANCE MANDATORY, ALL CH-47D AIRCRAFT, AN/ASN-128B/D DOPPLER GPS NAVIGATION SYSTEM SET (DGNS). COMPLIED WITH AT 7226.3 ACFT HRS.	DYNCORP 3-2 GSAB	28-Apr-2008	1	RW984580
KOREA				
ACE COMPLETED AT 7261.8 ACFT HOURS AT CP HUMPHREYS KOREA BY ACE TEAM MEMBER M, AMCOM OLR/MWO BRANCH HUNTSVILLE AL	PROJECT OLR KOREA	17-Jul-2008	1	JR295472
KOREA				
AWR DATED 07 AUG 2008 (TTS 54838) FOR OPERATION OF M240H MACHINE GUN AND REDESIGNED ROLLER BEARING CAM FOLLOWER P/N 13019572 (NSN 1005-01-534- 6800) INSTALLED FOR THE M41 GUN MOUNTS IS IN EFFECT	D CO 3-2 GSAB	07-Aug-2008	1	QC000000
KOREA				
200 HR PHASE MAINTENANCE INSPECTION COMPLETED AT 7316.2 ACFT HRS. NEXT INSPECTION IS 400 HOUR PHASE MAINTENANCE INSPECTION REQUIRED AT 7516.9 ACFT HRS	B CO 3-2 GSAB, DYNCORP	02-Oct-2008	2	DF701800
APO AP 96271 KOREA				
#1 & #2 ENGINE MOUNTS EDDY CURRENT INSPECTION COMPLETED AT 7316.2 ACFT HRS. NEXT INSPECTION REQUIRED AT 7916.2 ACFT HRS	B CO 3-2 GSAB, DYNCORP	02-Oct-2008	1	DF701800
APO AP 96271 KOREA				
H-47-09-ASAM-01, MAINTENANCE MANDATORY, ALL CH-47F AND MH-47G SERIES AIRCRAFT, CONTAMINATED ENGINE FUEL SUPPLY LINES, N/A THIS SERIES AIRCRAFT ON THIS DATE	D CO 3-2 GSAB	22-Oct-2008	1	PH568741
KOREA				

1. AIRCRAFT MODEL	2. NOMENCLATURE	3. AIRCRAFT SERIAL NUMBER			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47D	HELICOPTER, CARGO	8800070			
H-47-09-SOF-02 ENGINE D/S AND ADAPTERS RECORDS CHECK FOR RETIREMENT COMPONENT TIME COMPLIED WITH.	DYNCORP 3-2 GSAB	17-Dec-2008	1	RW984580	
	KOREA				
AWR (TTS 56878A) DATED 13 FEB 2009 R1 FOR INSTALLATION OF EBC-406HM EMERGENCY LOCATOR TRANSMITTER (ELT) IS IN EFFECT.	D CO 3-2 GSAB	13-Feb-2009	1	QC000000	
	KOREA				
AWR DATED 01 JUN2009 R1 (TTS 68650A) FOR USE OF SEI INDUSTRIES BAMBI BUCKET (MODELS BBT HL5000, BBT HL7590, BBT HL 7600) WITH OPTIONAL REMOTE POWER SUPPLY, POWERFILL I FOR THE TORRENTULA VALVE, COVERAGE CONTROLLER, AND SACKSAFOAM INJECTION SYSTEM INSTALLED IS IN EFFECT	D CO 3-2 GSAB	01-Jun-2009	1	QC000000	
	KOREA				
ACE COMPLETED AT 7476.8 ACFT HRS AT CAMP HUMPHREYS KOREA BY ACE TEAM MEMBER NN AMCOM OLR/MWO BRANCH HUNTSVILLE ALABAMA	AMCOM/OLR	22-Jun-2009	1	JP593236	
	KOREA				
H-47-09-AMAM-02 MAINTENANCE MANDATORY, ALL H-47 SERIES ACFT. AFT SLIDER SHAFT ASSY RETIREMENT LIFE	LSI 3-2 GSAB	17-Jul-2009	1	RW984580	
	KOREA				
MEC APPROVED TO ALLOW REPLACEMENT OF #1 FORWARD ENGINE MOUNT BE INSTALLED WITH #2 ENGINE MOUNT FIXTURE MEC # F97098	DCO 3/2 GSAB APO AP 96271	24-Aug-2009	3	QC000000	
	KOREA				
MEC APPROVED FOR TO REAM "B" LUG TO FIRST OVERSIZED 0.939. MEC # F97099	DCO 3/2 GSAB APO AP 96271	24-Aug-2009	2	QC000000	
	KOREA				
MEC APPROVED FOR TO REAM "A" LUG TO FIRST OVERSIZED 0.8281. MEC # F97101	DCO 3/2 GSAB APO AP 96271	24-Aug-2009	1	QC000000	
	KOREA				
MEC APPROVED TO FABRICATE AND INSTALLED 0.100 SHIM AT GAP INBOARD HALF OF FORWARD AND AFT LOWER ANGLES. MEC # F97247	DCO 3/S GSAB APO AP 96271	26-Aug-2009	1	QC000000	
	KOREA				
COMPLIED WITH GEN-09-AMAM3.	LSI, 3-2 GSAB	04-Sep-2009	1	RW984580	
	KOREA				
400 HOUR CYCLE MAINTENANCE CHECKLIST COMPLETED AT 7516.9 ACFT HRS. NEXT 200 HOUR CYCLE MAINTENANCE CHECKLIST INSPECTION DUE AT 7716.9 ACFT HRS.	LSI 3-2 GSAB	01-Oct-2009	1	RW984580	



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
	KOREA				
AIRCRAFT IS EQUIPPED WITH BFT/EDM, AWR TTS 69499 R5 DATED 05 NOV 09	D CO 3-2 GSAB	05-Nov-2009	1	QC000000	
	KOREA				
AWR DATED 09 NOV 2009 R2 (TTS 27259B) FOR OPERATION OF CH-47D HELICOPTERS WITH THE MILTOPE MAINTENANCE SUPPORT DEVICE (MSD) INSTALLED IS IN EFFECT	D CO 3-2 GSAB	09-Nov-2009	1	QC000000	
	KOREA				
H-47-09-AMAM-03, MAINTENANCE MANDATORY, HALON HAND HELD FIRE EXTINGUISERS, COMPLIED WITH.	LSI 3-2 GSAB	19-Nov-2009	1	RW984580	
	KOREA				
H-47-10-ASAM-02, MAINTENANCE MANDATORY, FWD PYLON HYD LINE CLAMPING COMPLIED WITH.	LSI 3-2 GSAB	22-Dec-2009	1	RW984580	
	KOREA				
GEN-10-AMAM-02, MAINTENANCE MANDATORY, DISTRIBUTION OF NEW ACFT ELECTRONIC LOGBOOK. COMPLIED WITH.	LSI 3-2 GSAB	28-Jan-2010	2	RW984580	
	KOREA				
H-47-10-AMAM-02, MAINTENANCE MANDATORY, ULLS-A ENHANCED LCF CHANGE 60B DATABASE UPDATE COMPLIED WITH.	LSI 3-2 GSAB	10-Feb-2010	1	RW984580	
	KOREA				
H-47-10-AMAM-03, MAINTENANCE MANDATORY, CH-47D/F FWD ROTOR HUB RETIREMENT LIFE REDUCTION COMPLIED WITH.	LSI 3-2GSAB	16-Mar-2010	1	RW984580	
	KOREA				
H-47-10-AMAM-04, MAINTENANCE MANDATORY, ALL CH-47D/F SERIES ACFT. AFT SLIDER SHAFT ASSY RETIREMENT LIFE COMPLIED WITH.	URS 3-2 GSAB	07-Apr-2010	1	RW984580	
	KOREA				
AIRCRAFT IS EQUIPPED WITH P3 DRAIN LINE, AWR TTS 70944 DATED 25 JUN 09 IS IN EFFECT	AMCOM, AFMA	20-May-2010	2	EM684008	
	KOREA				
AIRCRAFT IS EQUIPPED WITH AVA SINGLE CAMERA TRACKER BRACKET, AWR TTS 54785 DATED 26 MAR 08 IS IN EFFECT	AMCOM, AFMA	20-May-2010	1	EM684008	
	KOREA				
200 HR PHASE MAINTENANCE INSPECTION COMPLETED AT ACFT HRS 7716.5 BY D CO 3-2 47 MAINTENANCE PHASE TEAM LEADER SSG HACKETT. NEXT INSPECTION IS 400 HR PHASE (IF AUTHORIZED BY AWR) DUE AT ACFT HRS 8116.5.	B CO 3-2 GSAB	26-Aug-2010	1	JC495122	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
	KOREA			
FWD TRANSMISSION BUSHING FOUND TO BE DEFECTIVE BUSHING REPLACED IAW MEC#F116208 DATED 7 OCT 2010	URS B.CO 3/2 PHASE TEAM	07-Oct-2010	1	MH585088
	KOREA			
H-47-10-ASAM-07, 5000 LBS TIE DOWN ASSY INSPECTION COMPLETED 7729 HRS.	D CO. 3/2 GSAB	08-Oct-2010	1	JA956419
	KOREA			
IAW MEC F116208, FWD XMSN SN A7282MG SWIVELING ACTUATOR MOUNT LUG DID NOT ALLOW INSTALLATION OF BOLT. BUSHING WAS REPLACED IAW DMWR 55-1615-321.	D CO 3/2 GSAB	13-Oct-2010	1	EN231672
	KOREA			
H-47-11-ASAM-01, MAINTENANCE MANDATORY, ALL H-47 SERIES AIRCRAFT, AN960-1016 ALUMINUM WASHERS COMPLIED WITH.	DCO 3/2 GSAB APO AP 96271	14-Oct-2010	1	FY642166
	KOREA			
ACE COMPLETED @ 77704 ACFT HRS @USAG HUMPHREYS KOREA BY ACE TEAM MEMBER "C" AMCOM OLR/MWO BRANCH HUNTSVILLE ALABAMA	D CO 3-2 GSAB	22-Nov-2010	1	DT742318
	KOREA			
H-47-11-AMAM-01, INTEGRATED MATERIEL MANAGEMENT CENTER LEGITIMATE CODE FILE CHANGE COMPLY WITH ON THIS DATE	DCO 3/2 GSAB APO AP 96217	19-Jan-2011	1	FY642166
	KOREA			
AWR DATED 02 APR 2003 FOR FLIGHT OPERATIONS ON U.S. ARMY AIRCRAFT CH-47D HELICOPTERS WITH T55-GA-714A ENGINES IS NO LONGER IN EFFECT PER USRDEC MEMO DATED 11 FRB 2011.	D CO 3-2 GSAB	11-Feb-2011	1	QC000000
	KOREA			
AWR DATED 10 MAR 2011 (TN 93334) FOR OPERATION OF AVIATOR'S NIGHT VISION IMAGING SYSTEM (ANVIS) AN/AVS-6 SERIES NIGHT VISION GOGGLES (NVGS) IS IN EFFECT	D CO 3-2 GSAB	10-Mar-2011	1	QC000000
	KOREA			
AIRCRAFT IS EQUIPPED WITH AFT PYLON ACCESS PANEL, NO AWR	AMCOM AFMA	04-Apr-2011	8	EM684008
	KOREA			
AIRCRAFT IS EQUIPPED WITH ELECTRIC HYDRAULIC HAND PUMP, AWR TTS 49400 R1 DATED 16 OCT 07 IS IN EFFECT	AMCOM AFMA	04-Apr-2011	7	EM684008
	KOREA			
AIRCRAFT IS EQUIPPED WITH RELOCATED FLUX VALVE, NO AWR	AMCOM AFMA	04-Apr-2011	6	EM684008
	KOREA			
AIRCRAFT IS EQUIPPED WITH MASTER DA FORM 2408-15, OCT 91 EDITION OF JAN 64 IS OBSOLETE	AMCOM AFMA	04-Apr-2011	5	EM684008

HISTORICAL RECORD FOR AIRCRAFT

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

FOUO - For Official Use Only

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>8800070</b>		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID

CAUTION SHIELD, NO AWR

KOREA

AIRCRAFT IS EQUIPPED WITH EAPS, NO AWR	AMCOM AFMA	04-Apr-2011	4	EM684008
--	------------	-------------	---	----------

KOREA

AIRCRAFT IS EQUIPPED WITH CMWS, AWR TN 67638 DATED 10 APR 09 IS IN EFFECT	AMCOM AFMA	04-Apr-2011	3	EM684008
---	------------	-------------	---	----------

KOREA

AIRCRAFT IS EQUIPPED WITH BFT/EDM, AWR TTS 69499 R5 DATED 05 NOV 09 IS IN EFFECT	AMCOM AFMA	04-Apr-2011	2	EM684008
--	------------	-------------	---	----------

KOREA

AIRCRAFT IS EQUIPPED WITH AN/ASN-128D, AWR TN 52014 DATED 22 FEB 08 IS IN EFFECT	AMCOM AFMA	04-Apr-2011	1	EM684008
--	------------	-------------	---	----------

KOREA

H-47-11-ASAM-04, MAINTENANCE MANDATORY, ALL H-47 SERIES AIRCRAFT, BLADE LAG DAMPNER ROD END BEARING COMPLIED WITH AT 7829.4 AIRCRAFT HOURS	D CO 3/2 GSAB, 2ID	19-Apr-2011	1	EN231672
--	--------------------	-------------	---	----------

KOREA

ACE COMPLETED @ 7833ACFT HRS @ USAG HUMPHREYS KOREA BY ACE TEAM MEMBER "C" AMCOM OLR/MWO BRANCH HUNTSVILLE ALABAMA	D CO 3-2 GSAB	24-May-2011	1	DT742318
--	---------------	-------------	---	----------

KOREA

ASAM H-47-11-ASAM-03, MAINTENANCE MANDATORY, REPLACE CONNECTING LINK PN145C3340-1/-2/-8/-9/-10/-11/-12 COMPLY WITH 04 MAY 2011 CAMP HUMPHREYS KOREA(JA956419)	D CO 3-2 GSAB	27-May-2011	1	JA956419
---	---------------	-------------	---	----------

KOREA

AWR DATED 04 AUG 2011 (TN 98912) FOR CH-47D HELICOPTERS EQUIPPED WITH AN/ASN-128D DOPPLER GLOBAL POSITIONING SYSTEM NAVIGATION SYSTEM (DGNS) IS IN EFFECT	D CO 3-2 GSAB	04-Aug-2011	1	QC000000
---	---------------	-------------	---	----------

KOREA

AWR DATED 09 AUG 2011 (TTS 79958) FOR USE OF INTEGRATED PERFORMANCE AND AIRCRAFT CONFIGURATION (IPAC) SOFTWARE VERSION 1.0.7.2509 FOR PERFORMANCE PREDICTION IS IN EFFECT	D CO 3-2 GSAB	09-Aug-2011	1	QC000000
---	---------------	-------------	---	----------

KOREA

400 HOUR CYCLE MAINTENANCE CHECKLIST COMPLETED AT 7915.2 ACFT HRS. NEXT 200 HOUR CYCLE MAINTENANCE CHECKLIST INSPECTION DUE AT 8115.2 ACFT HRS.	D CO. 3-2 GSAB	06-Sep-2011	1	JA956419
---	----------------	-------------	---	----------

KOREA

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
H-60-11-AMAM-04, AN/ASN-128D DOPPLER AND AMPS SOFTWARE UPGRADE, COMPLY WITH ON THIS DATE	D CO 3-2 GSAB APO AP 96271	24-Oct-2011	1	FY642166	
KOREA					
H-47-11-AMAM-03, ULLS-A (E) INTEGRATED MATERIEL MANAGEMENT CENTER LCF CHANGE 62 REQUIREMENTS, COMPLIED WITH THIS DATE	D CO 3-2 GSAB APO AP 96271	16-Nov-2011	1	FY642166	
KOREA					
COMPLY WITH REQUIREMENTS OF H-47-12-SOF-01 PRIOR TO NEXT FLIGHT, BUT NLT 2 DEC, 11. COMPLIED WITH THIS DATE.	D CO. 3-2 GSAB	23-Nov-2011	1	JA956419	
KOREA					
400 HOUR CYCLE MAINTENANCE CHECKLIST COMPLETED AT 7915.2 ACFT HRS. NEXT 200 HOUR CYCLE MAINTENANCE CHECKLIST INSPECTION DUE AT 8115.2 ACFT HRS.	D CO. 3-2 GSAB	29-Dec-2011	1	JA956419	
KOREA					
AWR DATED 16 MAY 2012 R1 (TTS 83544A) FOR CH-47D AND CH-47F WITH A NCS MAGNUS MODEL RNM101 LAPTOP ONBOARD AND OPERATING IS IN EFFECT	D CO 3-2 GSAB	16-May-2012	1	QC000000	
KOREA					
H-47-12-AMAM-02, TRANSMISSION OIL SAMPLE INTERVAL CHANGE, COMPLY WITH ON THIS DATE	D CO 3-2 GSAB AP	30-May-2012	1	FY642166	
KOREA					
ACE COMPLETED @ 8099 ACFT HRS @ USAG HUMPHREYS KOREA BY ACE TEAM MEMBER "U" AMCOM OLR/MWO BRANCH HUNTSVILLE ALABAMA	D CO 3-2 GSAB	04-Jun-2012	1	JS861046	
KOREA					
H-47-12-ASAM-01, YAW INTEGRATED LOWER CONTROL ACTUATOR INPUT CONTROL HARDWARE/HYDRAULIC PRESSURE TUBE CLEARANCE, COMPLIED WITH ON THIS DATE.	D CO, 3-2 GSAB	16-Aug-2012	1	CA185769	
KOREA					
H-47-12-AMAM-04 ALL H-47 SERIES ACFT, FULL AUTHORITY DICITAL ENGINE CONTROLS (FADEC) EMERGENCY PROCEDURES COMPLIED WITH ON THIS DATE	DCO 3/2 GSAB	20-Sep-2012	1	RM089644	
KOREA					
200 HOUR MAINTENANCE INSPECTION COMPLETED AT 8115.2 ACFT HRS URS AT D CO 3-2 GSAB, USAG HUMPHREYS. NEXT 400 HOUR CYCLE MAINTENANCE CHECKLIST INSPECTION DUE AT 8315.2 ACFT HRS.	D CO 3-2 GSAB, APO AP 96271	05-Dec-2012	1	FY642166	
KOREA					

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 8800070		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
H-47-13-ASAM-01, CORRODED CONNECTING LINKS, PN 145C3340-7 COMPLY WITH ON THIS DATE	D CO 3-2 GSAB, APO AP 96271	07-Dec-2012	1	FY642166
	KOREA			
MEC APPROVED TO FRABRICATE CAP ANGLE TO REINFORCE CRACKED AREA, # F157926	D CO 3-2 GSAB APO AP 96271	09-Dec-2012	1	FY642166
	KOREA			
H-47-13-ASAM-03 INFRARED SUPPRESSOR SYSTEM (IFSS) COMPLIED WITH ON THIS DATE	D CO 3-2 GSAB, APO AP 96271	18-Dec-2012	1	QC000000
	KOREA			
H-47-13-ASAM-02, MID-CABIN HATCH CARGO HOOK COMPLIED WITH ON THIS DATE.	D CO 3-2 GSAB, APO AP 96271	21-Dec-2012	1	FY642166
	KOREA			
COMPLIED WITH H-47-13-AMAM-02 (LCF CHANGE 63 REQUIREMENTS) ON THIS DATE	D CO 3-2 GSAB APO AP	25-Jan-2013	1	FY642166
	KOREA			
MEC APPROVED TO FABRICATE SLEEVE BUSHING P/N 114C1216-9. MEC #F162836	DCO 3-2 GSAB	19-Mar-2013	1	MM634646
	KOREA			
COMPLIED WITH H-47-13-SOF-02, SYNC SHAFT BOLTS PN 114D3053-2 AT ACFT HRS 8181.7	3-2GSAB	17-Jun-2013	1	RM916486
	KOREA			
COMPLIED WITH H-47-13-ASAM-06 IMPROPERLY INSTALLED FASTNERS	3-2 GSAB	29-Aug-2013	1	RM916486
	KOREA			
COMPLIED WITH H-47-13-AMAM-04 LCF CHANGE 64 ON 15 SEP 2013	D CO 3/2 GSAB	15-Sep-2013	1	CB818894
	KOREA			
ACE COMPLETED @ 8221 ACFT HRS @ USAG HUMPHREYS KOREA BY ACE TEAM MEMBER "U" AMCOM OLR/MWO BRANCH HUNTSVILLE ALABAMA	D CO 3/2 GSAB	20-Sep-2013	1	FY642166
	KOREA			