

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
AIRCRAFT S/N 62-02123 CH-47A, INDUCTED AND CONVERTED TO CH:47D S/N 92-00302 24 SEP 93 TOTAL TIME AT MODIFICATION 3479 HRS. (WC8215)	BOEING HELICOPTERS, PHILA, PA.	24-Sep-1993	1	QC000000	
AIRCRAFT S/N 92-00302 TEST FLOWN AND ACCEPTED AT 3487.6 ACFT HRS. (WC8215)	BOEING HELICOPTERS, PHILA, PA.	25-Oct-1993	1	QC000000	
SMALL CRACK ON FINGER PLATE LOCATED AT FS 482 W.L. +57.5, B.L. 23R -ALLOWABLE DAMAGE IAW TM 55-1520-240-23-2, TASK 2-6, PG 2-16.1, NOTE B. (WC8215)	AASF #1 HIARNG, WHEELER AAF	09-Dec-1993	1	QC000000	
CH-47-94-ASAM-04 MSG DTD FEB 94 ONE-TIME INSP OF PILOT & CO-PILOT SEAT BELT PIN. (AV9566)	AASF #1 HIARNG, WHEELER AAF	10-Feb-1994	1	QC000000	
AWR ISSUED FOR INSTALLATION OF DMDT 1-1-1 ELT ASSY (AV9566)	AASF #1 HIARNG, WHEELER AAF	04-May-1994	1	QC000000	
CH-47-94-ASAM-05 ONE-TIME INSP OF 5000LB TIE-DOWN RINGS. (WC8215)	AASF #1 HIARNG, WHEELER AAF	10-May-1994	1	QC000000	
CH-47-94-ASAM-06 ONE-TIME & RECURRING INSP. OF HYD PUMPS. (WC8215)	AASF #1 HIARNG, WHEELER AAF	10-May-1994	2	QC000000	
ACE PERFORMED AT 3554 ACFT. HRS. (WC8215)	AASF #1 HIARNG, WHEELER AAF	17-Jun-1994	1	QC000000	
SOF CH-47-95-01 ONE-TIME INSP OF UPPER BOOST ACTUATOR SN. (WC8215)	AASF #1 HIARNG, WHEELER AAF	06-Dec-1994	1	QC000000	
CH-47-ASAM-95-01 ONE-TIME AND RECURRING INSP. OF THRUST IDLER ASSY. (WC8215)	AASF #1 HIARNG, WHEELER AAF	15-Dec-1994	1	QC000000	
ADJUSTABLE ENG. AFT MOUNT LINK MEASUREMENT FOR #1 ENG. IS 6.320 IN. #2 ENG IS 6.426 IN. MWO 1-1520-240-50-60 COMP. AT 3563.7 ACFT. HRS. (AV9566)	PROJ OLR LSI, WHEELER AAF	13-Jan-1995	1	QC000000	
CH-47-95-ASAM-02 ONE-TIME TORQUE VERIFICATION OF NUTS SECURING THE NO. 1 & NO.2 PTU MOTOR PUMP. (WC8215)	AASF#1 HIARNG, WHEELER AAF	24-Jan-1995	1	QC000000	
CH-47-95-ASAM-04 ONE-TIME FOR STRATO POWER PUMPS NSN 1650-01-249-4341 AND REPORTING FOR TURNAROUND PROGRAM C/W. (WC8215)	AASF#1 HIARNG, WHEELER AAF	29-Mar-1995	1	QC000000	
SOF MSG CH-47-95-02 ONE-TIME INSP AND TORQUE CHECK OF LOWER DRIVE LINK FOR FWD. & AFT SWASHPLATE. (AV9566)	AASF#1 HIARNG, WHEELER AAF	07-May-1995	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-95-ASAM-05 INSP AND LUBE OF FLT CNTRL ROD END BRGS. (WC8215)	AASF#1 HIARNG, WHEELER AAF	30-May-1995	1	QC000000
CH-47-95-ASAM-06 INSP AND LUBE OF FLT CNTRL ROD END BRGS. (WC8215)	AASF#1 HIARNG, WHEELER AAF	25-Aug-1995	1	QC000000
CH-47-95-ASAM-07 ONE-TIME RECORDS CHECK AND RE-ACCURING DAILY INSP. FOR SLIPPED AND/OR CRACKED PITCH HOUSING LUGS FOR ROTOR HEADS THAT HAVE MWO 1-1520-240-50-69. (JS7289)	AASF#1 HIARNG, WHEELER AAF	09-Sep-1995	1	QC000000
CH-47-95-ASAM-08 VISUAL INSP OF OF AFT VERTICAL SHAFT FOR ADJACENT TO THE DUST SEAL AND FOR AND FOR PROPER CLEARANCE OF THE DUST SEAL. (TA4801)	AASF#1 HIARNG, WHEELER AAF	18-Sep-1995	1	QC000000
31 OCT. 95 PHASE #1 COMPLETED AT 3677.5 ACFT. HRS. PHASE #2 DUE AT 3877.5 ACFT. HRS. (WC8215)	AASF#1 HIARNG, WHEELER AAF	31-Oct-1995	1	QC000000
CH-47-96-ASAM-01 ONE-TIME INSP OF LDG GEAR LINKS L5,R5 (WC8215)	AASF#1 HIARNG, WHEELER AAF	07-Nov-1995	1	QC000000
CH-47-96-ASAM-03 ONE-TIME VISUAL INSP OF ACCUMALATOR PRESSURE GAGES. (WC8215)	AASF#1 HIARNG, WHEELER AAF	09-Feb-1996	1	QC000000
CH-47-96-ASAM-04 ONE-TIME INSP OF FWD AND AFT ROTOR HUB ASSY OIL PORTS. (JS7289)	AASF#1 HIARNG, WHEELER AAF	12-Jun-1996	1	QC000000
CH-47-96-ASAM-05 ONE-TIME INSP OF FWD ROTOR HEAD BOLTS MANUFACTUR NAME. (WC8215)	AASF#1 HIARNG, WHEELER AAF	28-Jun-1996	1	QC000000
CH-47-96-ASAM-06 ONE-TIME VISUAL INSP AND RECORDS CHECK OF UPPER BOOST ACTUATORS, AND PULL TEST OF SWASHPLATES. (AV9566)	AASF#1 HIARNG, WHEELER AAF	16-Jul-1996	1	QC000000
CH-47-96-ASAM-07 INSP OF ENGINE INLET STRAP ASSEMBLIES FOR LOOSENESS. (AV9566)	AASF#1 HIARNG, WHEELER AAF	21-Jul-1996	1	QC000000
CH-47-96-ASAM-08 VISUAL INSP OF FWD XMSN OIL PUMP (WF6620)	AASF#1 HIARNG, WHEELER AAF	27-Aug-1996	1	QC000000
CH-47-96-ASAM-09 INSPECTION AND REPAIR OF AFT PYLON CLAMSHELL DOOR LOWER LATCH TO PRECLUDE WEAR AND/OR INFLT LOSS. (WC8215)	AASF#1 HIARNG, WHEELER AAF	18-Sep-1996	1	QC000000
CH-47-97-ASAM-01 ONE-TIME RECORDS/ VISUAL INSP OF SYNCH. SHAFT SN. (WF6620)	AASF#1 HIARNG, WHEELER AAF	16-Oct-1996	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-97-SOF-01 ONE-TIME VISUAL INSP. OF XMSN MOUNT BARREL NUTS (WC8215)	AASF#1 HIARNG, WHEELER AAF	22-Nov-1996	1	QC000000	
CH-47-97-ASAM-02 ONE-TIME INSP OF WINCH/HOIST OPERATOR GRIP FOR GUARD. (WC8215)	AASF#1 HIARNG, WHEELER AAF	03-Jan-1997	1	QC000000	
GEN-97-ASAM-03 CHANGE OF LOADING PROCEDURE FOR AN/ASN-149 GPS RECEIVERS. (WF6620)	AASF#1 HIARNG, WHEELER AAF	07-Jan-1997	1	QC000000	
CH-47-97-ASAM-03 ONE-TIME & RECURRING IMSP OF 5000 LB. TIE-DOWN RINGS. (TA4801)	AASF#1 HIARNG, WHEELER AAF	08-Feb-1997	1	QC000000	
CH-47-97-ASAM-05 ONE-TIME & REPLACEMENT OF 4N320-12 CASTELLATED CW. (WC8215)	AASF#1 HIARNG, WHEELER AAF	17-Mar-1997	1	QC000000	
CH-47-97-ASAM-06 INFORMATIONAL UPDATE AND CHANGES FOR NAVSTAR G.P.S. (JS7289)	AASF#1 HIARNG, WHEELER AAF	04-Apr-1997	1	QC000000	
CH-47-97-ASAM-07 INSP. OF PWR. DIST FEEDER WIRING PDP CIRCUIT BREAKER CW. (KN3594)	AASF#1 HIARNG, WHEELER AAF	30-Apr-1997	1	QC000000	
CH-47-97-ASAM-08 INSP./LUBE FLT. CONTROL ROD END BRGS. AT NEXT PHASE AND EVERY 1ST AND 3RD PHASE THEREAFTER. (AV9566)	AASF#1 HIARNG, WHEELER AAF	03-May-1997	1	QC000000	
CH-47-97-ASAM-09 OPERATION OF T-62 APU AND REPORT OF APU FLT HRS. (AV9566)	AASF#1 HIARNG, WHEELER AAF	02-Jun-1997	1	QC000000	
CH-47-97-ASAM-04 REPLACEMENT OF CRISSAIR CHECK VALVES SW. (WF6620)	AASF#1 HIARNG, WHEELER AAF	10-Jun-1997	1	QC000000	
CH-47-97-ASAM-10 ONE-TIME INSP OF ANVISHUD PWR SUPPLY (WC8215)	AASF#1 HIARNG, WHEELER AAF	06-Oct-1997	1	QC000000	
CH-47-98-ASAM-01 UNCOMMANDED CONTROL INPUTS RECORD INSP. CW. (AV9566)	AASF#1 HIARNG, WHEELER AAF	15-Oct-1997	1	QC000000	
CH-47-98-ASAM-02 EXTENSION OF AFT LANDING GEAR DRAG STRUT CW. (KN3594)	AASF#1 HIARNG, WHEELER AAF	24-Oct-1997	1	QC000000	
CH-47-SOF-98-01 ONE-TIME INSP. OF UPPER BOOST ACT HARDWARE (AFT ACTUATORS) CW. (KN3594)	AASF#1 HIARNG, WHEELER AAF	18-Mar-1998	1	QC000000	
CH-47-98-ASAM-03 MANDATORY TORQUE CHECK AND REPLACEMENT OF APU BOLTS. (WF6620)	AASF#1 HIARNG, WHEELER AAF	14-May-1998	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-98-ASAM-04 ONE-TIME INSP. OF AFT TRANSMISSION SERIAL NUMBERS, CW. (JS7289)	C-CO 193RD AVN., WAAF, HI.	15-May-1998	1	QC000000
SOF MSG CH-47-98-02 FLIGHT RESTRICTIONS FOR ACFT W/MWO 1-1520-240-50-67 APPLIED (TA4801)	AASF#1 HIARNG, WHEELER AAF	16-Jul-1998	1	QC000000
SOF MSG CH-47-98-02 FLIGHT RESTRICTIONS FOR ACFT W/MWO 1-1520-240-50-67 APPLIED (TA4801)	AASF#1 HIARNG, WHEELER AAF, HI	16-Jul-1998	2	QC000000
CH-47-98-ASAM-05 ACFT RESTRICTED TO FLT OPNS & INSP W/-3 DRAG LINKS C.W. (TA4801)	AASF#1 HIARNG, WHEELER AAF, HI	18-Sep-1998	1	QC000000
ACE PERFORMED AT 3868 ACFT HRS AT WHEELER AAF, HI BY PROJECT OLR (KN3954)	PROJECT OLR, FT. LEWIS, WA.	30-Oct-1998	1	QC000000
CH47-99-ASAM-01 ONE TIME INSP OF LAG DAMPENERS (HO4933)	C COMPANY 193D AVIATION, WAAF HI 96857	09-Feb-1999	1	QC000000
CH-47-99-ASAM-02, INSP AND RECORDS CHK OF ALL SERVOCYLINDERS, CW. (AV9566)	AASF#1 HIARNG, WAAF, HI 96857	23-Feb-1999	1	QC000000
CH47-99-ASAM-04 FWD/AFT LCT YOKE BUSHING INSP AND TM CHANGES (AV9566)	AASF#1 HIARNG, WAAF, HI 96857	26-Mar-1999	1	QC000000
CH-47-99-ASAM-05 EXTENSION OF -3 LANDING GEAR DRAG LINK REPL, C.W. (XY6573)	AASF#1 HIARNG, WAAF, HI	23-Apr-1999	1	QC000000
CH-47-99-ASAM-03 ONE-TIME AND RECURRING INSP OF HOIST CONTROL PANEL, C.W. (XY6573)	AASF#1 HIARNG, WAAF, HI	27-Apr-1999	1	QC000000
SOF CH-47-99-01, ONE-TIME CLEARANCE CHK SYNC SHAFT ASSY AND MOUNTING BRACKET, CW. (JY6573)	AASF#1 HIARNG, WAAF, HI 96857	09-Jul-1999	1	QC000000
SOF MSG CH-47-99-02, IMMEDIATE GROUNDING OF ACFT UNTIL FULL SEARCH/INSP CAN BE CONDUCTED. (AV9566)	AASF#1 HIARNG, WAAF, HI 96857	06-Aug-1999	1	QC000000
HISTORICAL RECORD (2408-15) CONVERTED TO ULLS-A ON 10 AUG 99 AT 2870 ACFT HRS (JY6573)	AASF#1 HIARNG, WHEELER AAF, HI	10-Aug-1999	1	QC000000
SOF CH-47-99-03 INSPECTION OF H-47 AIRCRAFT FORWARD AND AFT TRANSMISSION GEAR/BEARING ASSEMBLIES (JY6573)	AASF#1 HIARNG, WHEELER AAF, HI	25-Aug-1999	1	QC000000



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF CH-47-99-04 INSP OF FWD/AFT XMSN RECORDS FOR SPECIFIC PART NUMBER/SERIAL NUMBER COMBINATIONS DUE NLT 1 SEP 99 C/W (JY6573)	AASF#1 HIARNG, WHEELER AAF, HI	31-Aug-1999	1	QC000000
ACE PERFORMED AT 3870 AC HRS AT WHEELER AAF BY DD&EE (MF9867)	PROJECT OLR, FT. LEWIS, WA	09-Sep-1999	1	QC000000
SOF CH-47-99-05, IMPLIMENTATION OF SHIPPING INSTRUCTIONS FOR FWD AND AFT XMSN'S (JS7289)	C CO. 193 AVN, WHEELER ARMY AIRFIELD HI 96857	14-Sep-1999	1	QC000000
SOF CH-47-00-01 OPERATIONAL RESTRICTIONS AND REVISION OF HISTORICAL RECORD FOR T-62T-2B APUS (JY6573)	AASF#1 HIARNG, WHEELER AAF, HI	12-Oct-1999	1	QC000000
SOF CH-47-00-02 REVISION TO PORTIONS OF CH-47-00-01 (XY6573)	AASF#1 HIARNG, WHEELER AAF, HI	09-Nov-1999	1	QC000000
SOF CH-47-00-03 DTD 8 DEC 99 INCREASE OF OPERATING LIMITATIONS FOR "VB" TRANSMISSIONS (N/A) (JY6573)	AASF#1 HIARNG, WHEELER AAF, HI	10-Dec-1999	1	QC000000
SOF CH-47-00-04 ONE TIME INSP OF XMSN FOR FAULTY GEARS. (AV9566)	AASF#1 HIARNG, WAAF, HI 96857	28-Jan-2000	1	QC000000
INSPECT FUEL PODS IAW CH-47-00-ASAM-01 CW (XY6573)	AASF #1, HIARNG, WHEELER AAF, HI	28-Apr-2000	1	QC000000
SOF CH-47-00-ASAM-05 INSPECT ALL PITCH HOUSINGS FOR "TM" PREFIX SERIAL NUMBERS (XY6573)	AASF #1, HIARNG, WHEELER AAF, HI	01-May-2000	1	QC000000
PHASE NO. 2 COMPLETED @ 3869.5 ACFT HRS NEXT PHASE DUE @ 4069.5 ACFT HRS (JY6573)	AASF #1, HIARNG, WHEELER AAF, HI	04-May-2000	1	QC000000
SOF CH-47-00-06 LIFTING OF OPERATIONAL LIMITATIONS FOR APU'S W/CONTAINMENT SHIELDS INSTALLED (XY6573)	AASF #1, HIARNG, WHEELER AAF, HI	10-May-2000	1	QC000000
CH-47-00-ASAM-02, INSP OF HORZ HINGE PIN BOLT (AV9566)	C CO 193RX AVN, HIARNG, WAAF, HI 96857	11-May-2000	1	QC000000
CH-47-00-ASAM-03 HYD OIL SAMPLE OF #1, #2 FLT AND UTILITY HYD SYSTEMS CW (XY6573)	AASF #1, HIARNG, WHEELER AAF, HI	02-Jun-2000	1	QC000000
ACE PERFORMED AT 3899 AC HRS AT WHEELER AAF BY E&DD (MM6264)	PROJECT OLR, FT. LEWIS, WA	12-Jun-2000	1	QC000000
CH-47-00-ASAM-04 INSPECT ROTOR HEAD DA FORM 2408-16'S FOR HORIZONTAL HINGE PINS C/W (XY6573)	AASF #1, HIARNG, WHEELER AAF, HI	26-Jul-2000	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
CH-47-00-ASAM-05 INSPECT THE FWD & AFT SLIDER SHAFT SEALS C/W (XY6573)	AASF #1, HIARNG, WHEELER AAF, HI	31-Jul-2000	1	QC000000	
CH-47-00-ASAM-06 ONE TIME INSPECTION FOR DEFECTIVE FULL AUTHORITY DIGITAL ELECTRONIC CONTROL (FADEC) P3 DRAIN CARTRIDGE0-ASAM-06 (JY6573)	AASF #1, HIARNG, WHEELER AAF, HI 96854	25-Sep-2000	1	QC000000	
INSPECT CBOX FAN SHAFT IAW SOF CH-47-00-07 (JY6753)	AASF #1, HIARNG, WHEELER AAF, HI 96857	27-Sep-2000	1	QC000000	
INSPECT FOR UNTESTED 114R3650-7 BOLTS ON H-47 ACFT IAW CH-47-00-ASAM-07 CW (WF6620)	AASF #1, HIARNG, WHEELER AAF, HI 96857	29-Sep-2000	1	QC000000	
INSPECT FWD YOKE SHAFT IAW CH-47-00-ASAM-08 ACFT CW (JY6753)	AASF #1, HIARNG, WHEELER AAF, HI 96857	29-Sep-2000	2	QC000000	
CH47D INSP FOR MA-16 INERTIA REELS ASAP WITHIN 10 FLT HRS BUT NLT 26 OCT 00 AT WHICH TIME ACFT STATUS CHGS TO A REX X. WILL CHG TO A RED X. (AV9566)	AASF #1, HIARNG, WAAF, HI 96857	12-Oct-2000	1	QC000000	
CH-47-01-ASAM-02 INSPECT FOR UNTESTED FSP PN 114R3650-6 AND 114R3650-11 BOLTS (XY6573)	AASF #1, HIARNG, WHEELER AAF, HI	23-Oct-2000	1	QC000000	
CH-47-01-ASAM-03 FORWARD AND AFT ROTOR HUB LIGHTENING HOLE INSPECTIONS (XY6573)	AASF #1, HIARNG, WHEELER AAF, HI	09-Nov-2000	1	QC000000	
CH-47-01-ASAM-04 INSPECTION FOR UNTESTED FLIGHT SAFETY PART (FSP) TIE BAR PINS ASSEMBLIES P/N 114R2168-3 AND 114R2168-4 (JY6573)	AASF #1, HIARNG, WHEELER AAF, HI	14-Dec-2000	1	QC000000	
CH-47-01-ASAM-05 ONE TIME INSPECTION OF ROTOR HEAD ASSEMBLY DROOP STOP BOLTS FOR PROPER LENGTH (JY6573)	AASF #1, HIARNG, WHEELER AAF, HI	14-Dec-2000	2	QC000000	
REVISION TO CH-47-01-ASAM-04, INSPECTION FOR UNTESTED FLIGHT SAFETY PART (FSP) TIE BAR PINS ASSEMBLIES P/N 114R2168-3 ADN 114R2168-4 PER CH-47-01-ASAM-06 (JY6573)	AASF #1, HIARNG, WHEELER AAF, HI	26-Dec-2000	1	QC000000	
SOF CH-47-01-01 ONE TIME INSPECTION OF AFT ROTOR HEAD ASSEMBLIES AND ENGINE CROSS SHAFT ADAPTER ASEMBLIES (JY6573)	AASF #1, HIARNG, WHEELER AAF, HI	26-Dec-2000	2	QC000000	
SOF CH47-01-02 INSP OF DROOP STOPS CW (AV9566)	AASF #1, HIARNG, WAAF, HI 96857-5016	05-Feb-2001	1	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
CH-47-01-ASAM-07 INSP FOR UNTESTED FSP P/N 114R3650-13 AND 114R3650-15 BOLTS (JY6573)	AASF #1, HIARNG, WHEELER AAF, HI 96857-5016	15-Feb-2001	1	QC000000
SOF CH-47-01-03 INSP ACFT IAW CH-47-01-03 PRIOR TO NEXT ENGINE START (ROTOR TURNING).	AASF #1 HIARNG (JY6573), WHEELER AAF HI 96857-5016	16-Feb-2001	1	QC000000
CH-47-01-ASAM-08 INSP PWR, PRESS., AND RETURN CTRL MODULE ASSEMBLIES TO ENSURE SHUT-OFF DIAPHRAGM HARDWARE IS INSTALLED	AASF #1 HIARNG (XY6573), WHEELER, AAF, HI. 96857	09-Aug-2001	1	QC000000
ACE PERFORMED AT 4043 ACFT HRS AT WAAF, HI BY E&DD	PROJECT OLR FT LEWIS WASH (MM6284), WAAF, HI AASF #1 HIARNG 96857	20-Sep-2001	1	QC000000
CH-47-02-ASAM-01 ONE TIME INSPECTION OF TUNNEL COVER STRUT ASSEMBLIES.	C CO 193D AVN (AA1276), WAAF, HI	04-Oct-2001	1	QC000000
SOF CH-47-02-01 SWASHPLATE LOWER SEAL RETAINER SELF-LOCKING NUT INSPECTION.	C CO 193D AVN (AA1276), WAAF, HI.	24-Jan-2002	1	QC000000
CH47-SOF-02-02 INSP OF ROTOR TACHOMETER.	AASF #1 HIARNG (AV9566), WAAF, HI 96857	24-Jan-2002	2	QC000000
200 HR PURIFICATION COMPLETED @ 4066.5ACFT HRS W/AGPU SN:0263 PURIFIER SN: A049. AGPU START: 41 3.7 END: 428.7 PURIFIER START: 413 END: 428	AASF #1 HIARNG (WF6620), WAAF, SCHOFIELD BARRACKS HI	11-Apr-2002	1	QC000000
CH47-ASAM-02-03, INSP FOR IMPROPERLY ASSEMBLED FUEL CONTROL RELAY BOXES	AASF #1 HIARNG (AV9566), SCHOFIELF BARRACKS, HI	13-Jun-2002	1	QC000000
PHASE #3 COMPLETED @ 4064.2 ACFT HRS, NEXT PHASE DUE @ 4264.2 ACFT HRS.	AASF #1 HIARNG (WF6620), WHEELER AAF, HI	02-Jul-2002	1	QC000000
EMC TEST COMPLETED FOR MODIFIED 10A APU.	AASF #1, HIARNG (JY6573), WHEELER AAF, HI	02-Jul-2002	2	QC000000
CH-47-02-ASAM-04 INSPECT FOR UNTESTED CSI P/N 114C3044-2 AFT YOKE SUPPORT SHAFT, CW.	C CO 193D AVN (JY6573), WHEELER AAF, HI.	25-Jul-2002	1	QC000000
SOF CH-47-02-03 REVISION TO CH-47-02-02, INSPECTION OF THE ROTARY WING HEAD TIE BAR ASSEMBLY AND ROTOR TACHOMETER.	C CO 193D AVN (AA1276), WAAF, HI.	03-Aug-2002	1	QC000000

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
SOF CH-47-02-04 INSPECTION OF FWD PIVOTING ACTUATOR TO SWASHPLATE ATTACHMENT HARDWARE FOR PROPER INSTILLATION.	C CO 193D AVN (AA1276), WAAF, HI.	03-Aug-2002	2	QC000000
SOF CH-47-02-05 ROTOR HEAD TIE BAR.	C CO 193D AVN (AA1276), WAAF, HI.	03-Aug-2002	3	QC000000
SOF CH-47-02-06 INSPECTION OF C-BOX.	C CO 193D AVN (AA1276), WAAF, HI.	03-Aug-2002	4	QC000000
SOF CH-47-03-01 INSP FWD AND AFT SWASHPLATE BEARING.	AASF #1 HIARNG (JY6573), WHEELER AAF, HI.	01-Nov-2002	1	QC000000
ACE PERFORMED AT 4141 ACFT HRS AT WHEELER AAF, HI BY E & DD.	PROJECT OLR (MM6284), FT. LEWIS, WA.	25-Nov-2002	1	QC000000
GEN-ASAM-03-01 ARC-201 BATTERY BOX INSPECTION C/W.	AASF #1 HIARNG (JY6573), WHEELER AAF, HI.	07-Jan-2003	1	QC000000
ACE/CPCE PERFORMED AT 4581 ACFT HRS AT WHEELER AAF BY ACE TEAM MEMBER. (C)	PROJECT OLR, FT. HOOD TX. 76542, AASF #1 HIARNG WHEELER AAF	13-Jun-2003	1	QC000000
EMC TEST COMPLETED ON 17 JAN 04 @ 4249.7 ACFT HRS FOR AN/AVS-6 (V) 3 GOGGLES.	C-CO 193RD AVN (TA4801), WAAF, HI	17-Jan-2004	1	QC000000
CH-47-04-ASAM-01 ONE TIME INSP OF AFT FUELSAGE BELCRANK FASTENER INSTALLATION.	CO. C 193D AVN (AA1276), WAAF, HI.	06-Feb-2004	1	QC000000
SOF CH-47-04-01, SUPERCEDE SOF CH-47-03-01, DELETE AOAP GREASE SAMPLING REQUIREMENT FOR FWD AND AFT SWASHPLATE BEARINGS.	CO C 193D AV (AA1276), WAAF, HI.	08-Feb-2004	1	QC000000
AIRCRAFT ENTERED COMBAT OPERATION IN SOUTHEAST ASIA, IRAQ @ 4255.4 ACFT HRS.	C-CO 193RD AVN (HH) (TA4801), BALAD, IRAQ	24-Mar-2004	1	QC000000
200 HR HYD PURIFICATION COMPLETED @ 4262.4 ACFT HRS W/AGPU SN: 079. PURIFIER SN: AQ45. AGPU START: 291.9 END: 299.0. PURIFIER START: 405 END: 412	C-CO 193RD AVN (HH) (TA4801), BALAD, IRAQ.	08-May-2004	1	QC000000
PHASE #4 COMPLETED @ 4264.2 ACFT HRS, NEXT PHASE #1 DUE @ 4464.4 ACFT HRS.	M. CO 158TH AVN. (KL7244), LSA ANACONDA, IRAQ	13-May-2004	1	QC000000
CH-47-04-ASAM-02 TRANSIENT AND AVOID BANDS ON THE CRUISE GUIDE INDICATOR.	M.CO 158TH AVN (KL7244), LSA ANACONDA IRAQ	13-May-2004	2	QC000000

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>9200302</b>		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
COMPLY WITH CH-47-MIM-04-001, APU START MODULE HOUSING @NEXT PHASE INSP. C/W @ 4458.4 ACFT HRS.	C-CO 193RD AVN (HH) (TA4801), BALAD, IRAQ	12-Jun-2004	1	QC000000
#1 ENG FORWARD MOUNT HAS DAMAGE TO THE OUTBD FACE OF LUG "A" THAT EXTENDS INTO THE EXISTING SPOT FACE. LUG "B" HAS DAMAGE INTO SPOT FACE AND INTO LUG "T". AUTHORIZATION WAS GRANTED BY BOEING STRESS ENGINEER AND AMCON MEC NO: LE-KU006-0498 FOR ONETIME REPAIR. FINAL CLEAN-UP LUG "A" BORE=0.109 T= 0.503, LUG "B" BORE=0.9688 "T"= 0.385 IAW BOEING SERV. NOTE 145-022 REV1 1 JUNE 2001 & PER MEC ENG MOUNT STAMPED WITH MIL #57406 LOT GBP 1/15/93. REPAIR COMPLETED @ 4458.4 ACFT HRS.	TF 1107TH AVCRAD, LSA ANACONDA IRAQ	12-Jun-2004	2	QC000000
FWD ENG MOUNT/Drag LINK INSP LAST COMPLETED AT 4066.5 ACFT HRS.	CO C 193D AV (HH) (AA1276), LSA ANACONDA	09-Sep-2004	1	QC000000
HYD PURIFICATION (200) COMPLETED @ 4458.4 ACFT HRS AGPU S/N:83-360A-482, PURIFIER S/N: A049, AGPU START: 503 END: 504.2, PURIFIER START: 656.3 END: 659.9 (BARREL METHOD) BY D. LOPEZ C-CO 193RD AVN (HH).	CO. C 193D AV (HH) (TA4801), LSA ANACONDA	09-Oct-2004	1	QC000000
COMPLY W/TB 1-1520-240-155 DESERT ENVIRONMENT INSP AT PHASE #1 C/W @ 4458.4 ACFT HRS.	C-CO 193RD AVN (HH) (TA4801), BALAD IRAQ	11-Oct-2004	1	QC000000
#1 ENG FORWARD MOUNT HAS DAMAGE TO THE OUTBD FACE OF LUG "A" THAT EXTENDS INTO THE EXISTING SPOT FACE. LUG "B" HAS DAMAGE INTO SPOT FACE AND INTO LUG "T". AUTHORIZATION WAS GRANTED BY BOEING STRESS ENGINEER AND AMCON MEC NO: LE-KU006-0498 FOR ONETIME REPAIR. FINAL CLEAN-UP LUG "A" BORE=0.109 T= 0.503, LUG "B" BORE=0.9688 "T"= 0.385 IAW BOEING SERV. NOTE 145-022 REV1 1 JUNE 2001 & PER MEC ENG MOUNT STAMPED WITH MIL #57406 LOT GBP 1/15/93. REPAIR COMPLETED @ 4458.4 ACFT HRS.	TF 1107TH AVCRAD, LSA ANACONDA IRAQ	12-Oct-2004	1	QC000000
CH-47-05-ASAM-01 AFT CRITICAL DYNAMIC COMPONENTS.	CO C 193D AV (HH) (AA1276), LSA ANACONDA	24-Oct-2004	1	QC000000
PHASE #1 COMPLETED AT 4458.4 ACFT HRS. NEXT PHASE (#2) DUE AT 4658.4 ACFT HRS.	C/193D AVN (FD5131), BALAD IRAQ	04-Nov-2004	1	QC000000



1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
NDI OF #1 ENG FWD MOUNTS PERFORMED AT 4458.4 ACFT HRS.	C/193D AVN (FD1531), BALAD IRAQ	04-Nov-2004	2	QC000000	
EMC TEST COMPLETED FOR RECORDS RECONCILIATION PURPOSES FOR THE FOLLOWING MWO'S APPLIED TO AND /OR IN USE BY THIS ACFT: AN/AVS-7(V)7 HUD, T-62T-2B APU, EBC302/305HM ELT, EFRS II "A" KIT, AN/AVS-6(V)3 ANVIS, AN/ALE-47 COUNTERMEASURE, BLUE FORCE TRACKER. ALL LISTED MODIFICATIONS MUST BE INSTALLED AND IN USE POWERED UP WHEN TEST PERFORMED.	CO C 193RD AVN (SM7041), LSA ANACONDA	11-Nov-2004	1	QC000000	
NDI OF #1 ENG FWD INBD MOUNT PERFORMED AT 4557.4	C-CO 193RD AVN (HH) (TA4801), BALAD, IRAQ	14-Dec-2004	1	QC000000	
12" CRACK ON FORMER AND T-CAP @ STA. 594. BL-22L, WL-50 REPAIRED @ 4577.9 ACFT HRS.	C-CO 193RD AVN (HH) (TA4301), BALAD, IRAQ	05-Jan-2005	1	QC000000	
ACFT TRANSFERED TO CO G 185TH AV (HH) CMDR W2FAA ON 09 FEB 2005 AS PER MEMO DTD 20050119 NGB CROSS LEVELING. DIRECTED AT 4614.4 ACFT HRS. CO G 185TH TO FERRY ACFT TO CONUS FOR RESET AND REASSIGNMENT.	CO C 193RD AV (HH), LSA ANACONDA, BALAD IRAQ	09-Feb-2005	1	QC000000	
OCM/ACE PERFORMED AT 4627 ACFT HRS. BY TEAM MEMBER J	DYN CORP PROJECT OLR (LH9501), FT CAMPBELL KY. 42223	02-Sep-2005	1	QC000000	
#1 & #2 ENG FWD AND AFT MOUNTS NDI COMPLETED @ 4627.0 ACFT HRS, NEXT INSP DUE @ 5227 HRS.	DYN CORP INTERNATIONAL DOL/ALMD (EM7232), FTCKY 42223	23-Sep-2005	1	QC000000	
CH-47-05-ASAM-05. ALL CH-47 AIRCRAFT, HYD CHECK VALVES AND FLUID PARTS.	DYNCORPINTERNATION AL (EM7232), DOL/ALMD, FTCKY	23-Sep-2005	2	QC000000	
CH-47-05-ASAM-06, ALL CH-47 AIRCRAFT HYD FLUID SYSTEM SAMPLING RESCINDED, PURIFICATION INTERV, 400HRS	DYNCORP INTERNATIONAL (EM7232), DOL/ALMD, FTCKY	23-Sep-2005	3	QC000000	
PHASE 1-4 COMPLETED @4626.5 ACFT HRS. NEXT PHASE #1 DUE @ 4826.5 ACFT HRS.	DYNCORP INTERNATIONAL (EM7232), DOL/ALMD FTCKY	02-Nov-2005	1	QC 000000	
TB1-1520-240-30-02, CH-47D AIRCRAFT DESERT OPERATIONS SPECIAL INSP AND CLEANING COMPLETED @ 4646.5 ACFT HRS.	DYNCORP INTERNATIONAL (EM7232), DOL/ALMD, FTCKY	02-Nov-2005	2	QC000000	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
MWO 1-1520-240-50-83 COMPLIED WITH REFERENCE AWR SUBJECT FLIGHT OPERATIONS ON US ARMY CH47-D HELICOPTERS WITH T55-GA-714A ENGINES DATED 02 APR 2003.	DYNCORP PROJ OLR (CC0096), FTCKY 42223	20-Dec-2005	1	QC000000
ECL CONTROL QUADRANT PN SN FOUND TO BE ACCEPTABLE AND MARKED IAW AMCOM ON LOCATION REPAIR PROCEDURE DATED 17 NOV 2002.	DYNCORP PROJ OLR (CC096), FTCKY 42223	20-Dec-2005	2	QC000000
CH-47-06-ASAM-01 REQUIRE INSPECTION OF ALL 4 UBA'S FOR SWAPPED END CAPS.	DYNCORP PROJ OLR (JD7437), FTCKY 42223	01-Jan-2006	1	QC000000
CH-47-06-ASAM-02 REQUIRES INSPECTION OF M240P MACHINEGUNS PRIOR TO NEXT ARMED FLIGHT.	DYNCORP PROJ OLR (JD7437), FTCKY 42223	01-Feb-2006	1	QC000000
AWR FOR RELOCATION OF CABIN BUBBLE WINDOWS ON CH-47D HELICOPTERS DATED 28 NOV 03, REV 1, APPLIED TO AIRCRAFT.	D CO 2/135 GSAB, FT. HOOD TX	02-Apr-2006	1	QC000001
CH-47-06-ASAM-03 ONE TIME INSPECTION OF AFT LONGITUDINAL CYCLIC TRIM (LCT) ACTUATOR COMPLETED AT 4640.2 ACFT HRS.	DYNCORP (CS3813), FTCKY 42223	11-May-2006	1	QC000000
AWR ISSUED FOR IMPLEMENTATION OF ALTERNATE MAINTENANCE CHECKLISTS FOR SELECTED CH-47D AIRCRAFT. 27 AUG 2004 AIRCRAFT ENTERED INTO THE MODULAR PMD AND 400 CSP.	D-CO 2/135TH GSAB 36 CAB, FT. HOOD TX.	23-May-2006	1	QC000000
AIRCRAFT ENTERED INTO 400 HR CSP MAINT PROGRAM @ 4646.5 ACFT HRS. NEXT PHASE DUE @ 5026.5 ACFT HRS	D CO 2/135 GSAB, 36TH CAB, FT. HOOD, TX	24-May-2006	1	BF846868
AWR FOR HELICOPTERS EQUIPPED WITH PORTABLE VIBRATION MANAGEMENT PROGRAM/ AVIATION VIBRATION ANALYZER II (P-VMEP/AVA II). DATED 02 JUL 03. EMC TEST AND INSPECTIONS COMPLETED. INSP OK.	D CO 2/135 GSAB, FT. HOOD TX	24-May-2006	2	QC000001
AWR FOR OPERATION OF CH-47D HELICOPTERS WITH BLUE FORCE TRACKING (BFT) SYSTEM INSTALLED, DATED 07 FEB 07, APPLIED TO AIRCRAFT. EMC TEST OK.	D CO 2/135 GSAB, FT HOOD. TX	24-May-2006	3	QC000001
AIRCRAFT HISTORICALS ENTERED INTO ULLS-A (E) SCP 6 ON THIS DATE @ 4646.5 ACFT HRS.	D CO 2/135 GSAB, FT. HOOD, TX	24-May-2006	4	BF846868

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
ACFT TRANSFERRED TO OIF THEATER OF OPERATIONS THIS DATE AT 4678.3 ACFT HRS.	D CO 2/135TH AVN, UDAARI ARMY AIRFIELD	03-Sep-2006	1	BM862318	
CH-47-06-SOF-05 SUSPECT FWD ROTOR BLADES C/W @ 4678.3 ACFT HOURS	D-CO 2/135TH GSAB, BALAD, IRAQ	07-Sep-2006	1	CM806715	
CH-47-06-SOF-06 AFT CRITICAL DYNAMIC COMPONENTS C/W @ 4710.4 ACFT HRS.	D CO 2/135 TH GSAB, BALAD, IRAQ	21-Sep-2006	1	CM806715	
CH-47-07-SOF-01, SWASHPLATE ROTATING RING EDDY CURRENT INSPECTION (INSPECTION A190 CHANGED TO 200 HOUR INTERVALS) C/W AT 4824.0 AIRCRAFT HOURS	D CO., 2-135TH GSAB, 36TH CAB, BALAD, IRAQ	25-Oct-2006	1	LR728742	
200 HR CYCLE INSPECTION C/W @ 4825.0 ACFT HRS. 400 HR CYCLE INSPECTION NEXT DUE @ 5026.5 ACFT HRS (JF7775)	L3 VERTEX AEROSPACE, BALAD, IRAQ, APO AE 09391	10-Nov-2006	1	BF846868	
CH-47-05-ASAM-04 AFT TRANSMISSION RETAINER C/W @ 4825.0 ACFT HRS	VERTEX/L-3, BALAD, IRAQ, APO AE 09391	10-Nov-2006	2	BF846868	
CH-47-07-ASAM-01, ARC-220/KY-100 START-UP PROCEDURES, COMPLIED WITH AT 4940.5 AIRCRAFT HOURS	D CO., 2-135TH GSAB, LSA ANACONDA, BALAD, IRAQ	17-Jan-2007	1	LR728742	
CH-47-07-SOF-02 ALL H-47 SUSPECT ROTOR BLADES COMPLIED WITH AT 4969.3 ACFT HRS.	D CO 2/135TH GSAB 36TH CAB, BALAD, IRAQ	25-Jan-2007	1	CM806715	
COMPLIED WITH SOF MSG CH-47-07-SOF-02, CHECK SUSPECTED DISTORTED ROTOR BLADES @ 4969.3 ACFT HOURS	D COMPANY, 2/135TH GSAB, BALAD, IRAQ	26-Jan-2007	1	SM277372	
400 HR CSP PHASE COMPLETED AT 5027.8 ACFT HRS. NEXT 200 HR CSP DUE AT 5227.8	VERTEX/L3, BALAD, IRAQ	18-Feb-2007	1	BF846868	
CH-47-07-ASAM-02 RIGID CONNECTING LINKS COMPLIED WITH AT 5033.1 ACFT HRS	D CO 2/135 GSAB, BALAD, IRAQ	06-Mar-2007	1	BF846868	
200 HR CSP INSP COMPLETED @ 5226.4 ACFT HRS. 400 HR CSP PHASE INSP DUE @ 5427.8 ACFT HRS	B CO 449 ASB, LSA ANACONDA, BALAD IRAQ	19-Jun-2007	1	PK742774	
ACFT RETURNED TO HOME STATION-AASF, ST PAUL MN AT 5299.6 ACFT HRS	AASF ST PAUL, MN	11-Oct-2007	1	BF846868	
CH-47-07-SOF-03 SUSPECT ROTOR BLADES C/W @ 5299.6 ACFT HRS	AASF, ST. PAUL MN	12-Oct-2007	1	BF846868	
H-47-06-AMAM-02. DOES NOT APPLY TO CH-47D AIRCRAFT.	AASF, ST. PAUL, MN. 55107	18-Mar-2008	1	BF846868	

1. AIRCRAFT MODEL CH-47D	2. NOMENCLATURE HELICOPTER, CARGO	3. AIRCRAFT SERIAL NUMBER 9200302			
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID	
H-47-08-AMAM-03 COMPLIED WITH, (DOPPLER GPS NAVIGATION SET). SOFTWARE WAS PREVIOUSLY INSTALLED.	AASF, ST. PAUL, MN. 55107	25-Mar-2008	1	BF846868	
H-47 SERIES ACFT., ENGINE XMSN PINION GEAR. H-47-08-SOF-01, COMPLIED @ 5416.5 ACFT HRS/ "PASS" XMSN'S S/N NOT EFFECTED	OLR/LSI, FORT LEWIS, WA 98433	23-May-2008	1	CD482075	
H-47-08-AMAM-01, BEFORE 5427.8 AC HRS BUT NLT 27 NOV 08 (AFT XMSN RETAINER SEAL) COMPLETED "OK" @ 5416.5 AC HRS	LSI/OLR, FORT LEWIS, WA 98433	27-May-2008	1	CD482075	
ACE PERFORMED AT 5416 A/C HRS AT FT LEWIS, WA BY X & V	PROJECT OLR/LSI, FT LEWIS, WA	27-May-2008	2	DM410620	
H-47-08-AMAM-04 (FWD AND AFT SWASHPLATE RETAINING SPACERS) FWD SN A84-1415; AFT SN A84-1070 "PASS" ACFT HRS 5416.5	LSI/OLR, FORT LEWIS, WA 98433	13-Jun-2008	1	CD482075	
600 HOUR (NDI) #1 & #2 ENGINE MOUNT INSP COMPLETED AS 5416.5 ACFT HOURS. NEXT INSP DUE @ 6016.5 ACFT HOURS OR DURING NEXT ENG REMOVAL	PROJECT OLR WEST/LSI, FT. LEWIS, WA 98433, ST. PAUL, MN. 55107	30-Jul-2008	1	DM411876	
TB 1-1520-210-30-02, CH-47D ACFT DESERT OPERATIONS SPECIAL INSPECTION AND CLEANING COMPLIED WITH AT 5416.5 ACFT HOURS	PROJECT OLR WEST/LSI, FT. LEWIS, WA 98433, ST. PAUL, MN. 55107	30-Jul-2008	2	DM411876	
PHASE/RESET COMPLETED AT 5416.5 ACFT HOURS. NEXT PHASE (200 HRS) DUE AND 5616.5 ACFT HOURS, (400 HRS) 5816.5 ACFT HOURS.	PROJECT OLR WEST/LSI, FT. LEWIS, WA 98433, ST. PAUL, MN. 55107	30-Jul-2008	3	DM411876	
FUEL TANKS INSPECTION COMPLETED AT 5416.5 ACFT HOURS. NEXT INSPECTION DUE AT 6616.5 ACFT HOURS.	PROJECT OLR WEST/LSI, FT. LEWIS, WA 98433, ST. PAUL, MN. 55107	30-Jul-2008	4	DM411876	
HYD SYSTEM PURIFICATION COMPLETED AT 5416.5 ACFT HOURS.	PROJECT OLR WEST/LSI, FT. LEWIS, WA 98433, ST. PAUL, MN. 55107	30-Jul-2008	5	DM411876	
H-47-MIM-08-002, APU FORWARD MOUNT FITTING CHAFFING COMPLIED WITH AT 5416.5 ACFT HOURS.	PROJECT OLR WEST/LSI, FT. LEWIS, WA 98433, ST. PAUL, MN. 55107	30-Jul-2008	6	DM411876	
H-47-08-AMAM-05. AFT ROTOR HEAD PITCH VARYING HOUSING RETIREMENT LIFE COMPLIED WITH AT 5423.7 ACFT HOURS	PROJECT OLR WEST/LSI, FT. LEWIS, WA 98433	26-Aug-2008	1	DM411876	

1. AIRCRAFT MODEL <b>CH-47D</b>	2. NOMENCLATURE <b>HELICOPTER, CARGO</b>	3. AIRCRAFT SERIAL NUMBER <b>9200302</b>		
4. REMARKS	5. ORGANIZATION LOCATION	6. DATE	7. ENTRY NUMBER	8. PID
REPLACEMENT OF STA 594 REPAIR COMPLETED IAW ENCLOSED AWR #F81042. ACFT HOURS 5423.7.	ARMY FIELD MAINTENCE, LSI, FT. LEWIS, WA 98433	20-Oct-2008	1	DM411876