

MISHAP

CH47C IIAA5 - 4070 (D022)
TABRIZ AIRPORT IRAN
2 July 1977 1445 Hours (Local Time)

Major Accident - Strike

Aircraft was taxiing when the aft rotor blades struck a light/telephone pole. The forward and aft transmissions exited the airframe.

Only one of the crew sustained slight injuries. No fatalities.

The aircraft is considered a strike.



R. G. Orr

RGO:sam
P41-37